

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III17013928/AGA3Q2
Date: 18/05/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0016
Claimant Vehicle No :	SGW7011T	Insured Vehicle No :	SHD6711B
Date of Loss:	14/07/2017	Nature of Claim:	TP
		Claim No:	MCT17070528

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGW7011T	Engine No:	1NZC584740
Make & Model:	TOYOTA COROLLA, AXIO 1.5 X (A)	Chassis No:	NZE1416031443
Reg. Date:	26/07/2007 (Man. Year: 2007)	Odometer:	266519 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50R15	Rear Tyre Size:	195/50R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,463.70	1,590.45	873.25	35.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,000.00	1,250.00	55.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,713.70	2,590.45	2,123.25	45.04
Approved Total (Overridden) (S\$)		250.00		

(S\$)	4,713.70	250.00	4,463.70	94.70
+ GST 7.00/7.00% (S\$)	329.96	17.50	312.46	94.70
Nett Amount (S\$)	5,043.66	267.50	4,776.16	94.70
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 18/07/2017

Date Inspected: 19/07/2017

Estimated Period of Repair: 4.0 days

Inspected At: Vfix Auto Service Pte Ltd (HQ)
60 Kaki Bukit Ave 6, ARK@KB
Singapore 417892

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Sep 2020)
Parts:	143	TOYOTA COROLLA AXIO 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGW7011T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Dented	1,165.20 FL	*1,165.20 FL
2	1		*REAR DOOR LH	Dented	955.40 FL	*955.40 FL
3	1		*REAR FENDER LH	Repair	911.00 FL	*- FL
4	2		*DOOR HINGE REAR DOOR	Not Necessary	190.00 FS	*- FS
					Sub Total (\$)	3,221.60
					- List Item Discount on L Items 25.00/25.00% (\$)	757.90
					Total Parts (\$)	2,463.70
						1,590.45

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE/REPLACE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS/ATTACHMENTS REPAIR DENTED PANEL	New	1,000.00	400.00
2	TO SPRAY PAINT REPLACED/REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,000.00	600.00
3	TO REMOVE,INSTALL REAR BOOT COMPARTMENT GARNISHES	New	100.00	0.00
4	TO REMOVE,INSTALL REAR WINDSCREEN GLASS AND WATER TEST	New	150.00	0.00
Gross Labour Cost (\$\$)			2,250.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >