



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Your Ref: TP/IP/62279/2017
Our Ref : CI/TPD17023254/Z

14th December 2017

Fatal Accident Investigation Team

Traffic Police Department
Singapore Police Force
10 Ubi Avenue 3
Singapore 408865

MECHANICAL INSPECTION REPORT OF MOTOR LORRY GBB 4882K

1. We refer to your request on 23rd November 2017 to conduct a physical inspection of a motor lorry bearing registration number GBB 4882K (herein referred to as "**Motor Lorry**"), which was involved in a fatal road traffic accident on 18th November 2017.
2. The objective of this inspection is to determine if there was any possible mechanical failure to the Motor Lorry that may have contributed to the accident.
3. Following the request, we had carried out a physical inspection of the Motor Lorry on 13th December 2017 at the premises of Traffic Police vehicle pound, 517 Airport Road Singapore 539942. We now set out below our observations and comments with respect to this inspection.

General Condition

4. The mileage of the Motor Lorry at the time of our inspection was 307,629km.
5. The Motor Lorry was observed to have sustained relatively minor damages at its front right panel, front right wiper panel, front left lower bumper, front left side mirror (tilt inwards) and front left & right fender were amongst the body parts that were damaged as a result of the accident

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108



Photo 1 shows the mileage of the Motor Lorry at the time of our inspection was 307,629km. (circled).



Photo 2 shows The Motor Lorry was observed to have sustained relatively minor damages at its front right panel, front right wiper panel, front left lower bumper, front left side mirror (tilt inwards) and front right fender were amongst the body parts that were damaged as a result of the accident (circled).



Photo 3 shows The Motor Lorry was observed to have sustained relatively minor damages at its front right panel, front right wiper panel, front left lower bumper, front left side mirror (tilt inwards) and front right fender were amongst the body parts that were damaged as a result of the accident (circled).



Photo 4 shows the damage sustained on the front left lower bumper as a result of the accident.



Photo 5 shows the damage sustained on the front left wing mirror (tilt inwards) as a result of the accident.



Photo 6 shows the damage sustained on the front right panel & wiper panel as a result of the accident.



Photo 7 shows the damage sustained on the front right fender as a result of the accident.




Photo 8 shows a general view of the Motor Lorry's rear body at the time of our inspection. There was no damage found to the rear portion of the Motor Lorry.

Tyres and Wheel Rims

6. The 2 front tyres and 4 rear tyres of the Motor Lorry were observed to be in serviceable condition and sufficiently inflated for vehicular operation. We did not find any tear, cut or burst mark(s) on the outer and the inner sidewalls as well as across the tread of the 6 tyres. The tyre brand, tyre size and remaining tread depth of the 6 tyres of the Motor Lorry were recorded as follows:-

Yokohama Delivery Star 818
165R13 8PR(1mm)

Michelin Agilis 195R15C (4mm)



Yokohama Delivery Star 818
165R13 8PR(1.6mm)

Michelin Agilis 195R15C (5mm)

7. The 6 tyres were observed to be wrapped around standard alloy wheel rims that were found to be without any damage. See photo 9 – 12 below.



Photo 9 shows the condition of the front left tyre of the Motor Lorry, which was observed to be in serviceable condition with remaining tread depth of approximately 4mm. The tyre, which was wrapped around standard alloy wheel rim, was also observed to be sufficiently inflated for vehicular operation. There was no tear, cut or burst mark(s) on the outer and the inner sidewalls.



Photo 10 shows the condition of the front right tyre of the Motor Lorry, which was observed to be in serviceable condition with remaining tread depth of approximately 5mm. The tyre, which was wrapped around standard alloy wheel rim, was also observed to be sufficiently inflated for vehicular operation.



Photo 11 shows the condition of the rear left tyres of the Motor Lorry, which was observed to be in serviceable condition with remaining tread depth of approximately 1mm. The tyres, which were wrapped around standard alloy wheel rim, were also observed to be sufficiently inflated for vehicular operation.



Photo 12 shows the condition of the rear right tyres of the Motor Lorry, which were observed to be in serviceable condition with remaining tread depth of approximately 1.6mm. There was also no tear, cut or burst mark(s) on the outer and the inner sidewalls.

Engine Compartment & Operating Fluids

8. Upon examination of the Motor Lorry's engine compartment, we had observed all the parts and components inside the engine compartment to be intact and unaffected by the accident. The brake fluid, engine oil, power steering fluid and engine coolant were all found to be of sufficient level for operating purposes. Visually, there was also no contamination found to these fluids.
9. Further examination of the engine compartment found that there was no sign(s) or indication(s) of fresh fluid leakage and/or fluid stain within the engine compartment of the Motor Lorry.
10. Our subsequent checks on the underside of the Motor Lorry also revealed no fluid stain. Visually, the various undercarriage components of the Motor Lorry were all observed to be intact and without any visible damage. See photo 13 – 16 below.




Photo 13 shows a general view of the Motor Lorry's engine compartment, which was accessed by lifting the front passenger seat of the Motor Lorry. The various parts and components inside the engine compartment were unaffected by the accident. There was also no sign(s) or indication(s) of fresh fluid leakage and/or fluid stain within the engine compartment (photograph shows the engine compartment as viewed from the left front side of the Motor Lorry).



Photo 14 shows the brake fluid reservoir of the Motor Lorry at the time of our inspection. The brake fluid was observed to be of sufficient level and without any visible contamination.




Photo 15 shows the engine coolant reservoir of the Motor Lorry at the time of our inspection. The engine coolant was observed to be of sufficient level and without any visible contamination.



Photo 16 shows the engine dip stick of the Motor Lorry at the time of our inspection. The engine oil was observed to be of sufficient level and without any visible contamination (arrowed).

Steering System & Braking System

11. Static brake tests conducted on the Motor Lorry revealed no abnormality. The brake booster had responded well to the various tests conducted. There was also no abnormal movement of the brake pedal when it was depressed. In general, the static brake tests had suggested that there was no internal leakage of pressure/vacuum in the braking system of the Motor Lorry. The braking system of the Motor Lorry was likely to be in serviceable condition at the material time. This was also taking into consideration that the brake fluid was of sufficient level, and also that there was no sign(s) of brake fluid leakage along the brake hoses and brake pipes.
12. Static test on the steering system of the Motor Lorry also revealed no abnormality to the steering system. We did not experience any abnormal free play and/or other resistance when turning the steering wheel left and right to full lock positions. Our visual examination of the various steering components which had included the rack and pinion, tie rods, tie rod ends and ball joints had revealed that these components were all generally in good condition. See photo 17 - 21 below.



Photo 17 shows the brake pipe (arrowed) at the left rear wheel of the Motor Lorry. We did not observe any leakage of brake fluid at the time of our inspection of the Motor Lorry. Our static tests had indicated that there was no internal leakage of pressure/vacuum. Hence the braking system of the Motor Lorry was likely to be in serviceable condition at the material time of accident.



Photo 18 shows the brake pipe (arrowed) at the right rear wheel of the Motor Lorry. We did not observe any leakage of brake fluid at the time of our inspection of the Motor Lorry. Our static tests had indicated that there was no internal leakage of pressure/vacuum. Hence the braking system of the Motor Lorry was likely to be in serviceable condition at the material time of accident.

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108



Photo 19 shows the front left wheel of the Motor Lorry turned to its full left. During our steering system test, we did not experience any abnormal free play and/or resistance when we had turned the steering wheel towards full left and full right.



Photo 20 shows the various undercarriage components at the front right wheel of the Motor Lorry, in particular the steering tie rod end (arrowed). The various steering components were all found to be intact. There was also no sign of fluid stain(s) observed on the various undercarriage components.




Photo 21 shows the various undercarriage components at the front left wheel of the Motor Lorry, in particular the steering tie rod end (arrowed). The various undercarriage components of the Motor Lorry were all found to be intact without any visible damage. There was also no sign of fluid stain(s) observed on the various undercarriage components.

Electronic Safety / Warning Indicators

13. The Motor Lorry was not fitted with any electronic safety feature(s) like Anti-Brake Lock System (ABS), Supplemental Restraint System (SRS) etc. There was hence no test carried out on the functionality of these systems.

Operational Behaviour of the Motor Lorry

14. A short operational test of the Motor Lorry, to primarily determine whether there was any abnormality to its various operating systems like its engine system, its transmission system, steering system and braking system was subsequently carried out. The test was conducted by driving the Motor Lorry forward, stopping, before reversing and coming to a stop again.
15. During the operational test, the various transmission gears of the Motor Lorry were able to be engaged without any difficulty by stepping on the clutch pedal and manually shifting the gear lever. There were no abnormal sounds heard and/or abnormal behaviour of the Motor Lorry's engine system. It was able to move forward and backward normally. The braking system was also found to be in working condition as the Motor Lorry was able to slow down and come to a complete stop upon depressing of the brake pedal.

Conclusion

16. From our physical inspection of the Motor Lorry, it appears that its engine system, steering system, braking system and transmission system were all in serviceable condition. We did not find any evidence(s) to suggest that there was possible mechanical failure to the Motor Lorry that may have caused and/or contributed to the accident. This is also taking into consideration that the operational test of the Motor Lorry, which we had conducted, did not produce any sign(s) or symptom(s) to suggest that there was any abnormality to its various operating systems.

17. The 2 front tyres and 4 rear tyres fitted on the Motor Lorry were also found to be in serviceable condition. We did not find any tear, cut or burst mark(s) on the outer and the inner sidewalls as well as across the tread of the 6 tyres. The 6 tyres were also observed to be sufficiently inflated for vehicular operation with remaining tread depth of approximately 1 & 5mm each.



Rohaizal A. Rahim
Technical Investigator



Ang Bryan Tani
AMSOE, AMIRTE, AFF SAE, M.MATAI, AFF.Inst.AEA
Senior Technical Investigator
Technical Investigation & Reconstructionist (SAE-A)

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.