

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AXA18002631/AGA3Q2

**Date:** 28/04/2020

### REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

**Claimant**

**Vehicle No :** SKF3052T

**Insured Vehicle No :**

SHB9966Z

Date of Loss: 01/02/2018

Nature of Claim:

TP

Claim No: C0469951

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**SKF3052T**

Make & Model:

NISSAN LATIO, 1.5 (A)

Engine No:

HIDDEN

Reg. Date:

20/03/2008 (Man. Year: 2008)

Chassis No:

JN1FAAC11Z0003295

Colour:

Red

Odometer:

161438 km

Engine Capacity:

1498 cc

Market Value/New Car

N/A

Price:

Sum Insured (\$\$):

**Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:

185/65 R15

Rear Tyre Size:

185/65 R15

Front Left Side:

Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

*The above values represent the remaining tyre treads depth*

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,178.40	746.10	1,432.30	65.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,070.00	1,130.00	51.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,378.40</b>	<b>1,816.10</b>	<b>2,562.30</b>	<b>58.52</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,400.00</b>		
<b>(\$\$)</b>	4,378.40	1,400.00	2,978.40	68.02
<b>+ GST 7.00/7.00% (\$\$)</b>	306.49	98.00	208.49	68.03
<b>Nett Amount (\$\$)</b>	<b>4,684.89</b>	<b>1,498.00</b>	<b>3,186.89</b>	<b>68.02</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 07/02/2018

Date Inspected:

09/02/2018

Inspected At:

Torque 5 Pte Ltd (Kaki Bukit)

No. 8 Kaki Bukit Ave 4, #01-50

Singapore 415875

Estimated Period of Repair:

3.0 days

**Adjuster:** ADRIAN LING

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2020)
<b>Parts:</b>	144	NISSAN LATIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKF3052T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (CONSISTENT)	Deformed	564.00 F	*564.00 FL
2	1		*REAR BUMPER CLIPS (CONSISTENT)	Necessary	30.00 F	*30.00 FL
3	1		*REAR BUMPER SIDE HOLDER LH (CONSISTENT)	Necessary	35.00 F	*35.00 FL
4	1		*TAILLAMP LH (CONSISTENT)	Not Necessary	219.40 F	*- FL
5	1		*REAR LH FENDER (CONSISTENT)	Repair	1,080.00 F	*- FL
6	1		*REAR LH TYRE (CONSISTENT)	Cut	250.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,178.40</b>	<b>809.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	62.90
<b>Total Parts (\$\$)</b>	<b>2,178.40</b>	<b>746.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	800.00	400.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO UNDERSEAL	New	150.00	50.00
7	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,200.00</b>	<b>1,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >