



Your Ref: S8M00A51
Our Ref : CS/ASM18004432/N

14 March 2018

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(Motor Claims Department)

**TECHNICAL INVESTIGATION REPORT OF FIRE INCIDENT INVOLVING THE
MOTOR VEHICLE YM 9113J ON 6 FEBRUARY 2018**

1. We refer to your letter dated 7 March 2018 and the instructions therein.
2. Our analysis, comments and opinions with respect to the cause of fire to the Motor Vehicle YM 9113J (herein referred to as "**Insured Vehicle**") are set out below.

Inspection of the Motor Vehicle

3. The Insured Vehicle was physically inspected on 13 March 2018 at the premises of Veolia ES Singapore Ind. Pte. Ltd. (herein referred to as "**Veolia**") located at 23 Pandan Avenue, Singapore 609389.
4. A static inspection was carried out to the Insured Vehicle where the following general information was recorded:-

Vehicle Registration No.	: YM 9113J
Make / Model	: ISUZU FTR34P
Chassis No	: JALFTR34P87000023
Year of Registration	: September 2008
Mileage	: N.A (wiring affected)

5. The Insured Vehicle was noted to have sustained fire damage that was confined to its centre portion. The fire damage was observed to be most severe at its left centre portion. The exterior body of the Insured Vehicle was relatively unaffected by the fire except for the centre portion. The rear of the interior compartment was affected as a result of the fire. See photos 1 – 7 below.



Photo 1 shows the front view of the Insured Vehicle at the time of our inspection. The fire damage to the Insured Vehicle was confined to its centre portion. The exterior body of the Insured Vehicle was relatively unaffected by the fire except for the centre portion.



Photo 2 shows the right side of the Insured Vehicle at the time of our inspection. The exterior body of the Insured Vehicle was relatively unaffected by the fire except for the centre portion. The fire damage to the Insured Vehicle was confined to its centre portion (circled).



Photo 3 shows the left side of the Insured Vehicle at the time of our inspection. The exterior body of the Insured Vehicle was relatively unaffected by the fire except for the centre portion. The fire damage to the Insured Vehicle was confined to its centre portion. The fire damage was observed to be most severe at its left centre portion (circled).



Photo 4 shows the rear portion of the Insured Vehicle at the time of our inspection. The fire damage to the Insured Vehicle was confined to its centre portion. The rear portion was observed to have been unaffected by the fire.



Photo 5 shows the main engine compartment of the Insured Vehicle which is situated beneath the front cabin at the time of our inspection. The main engine compartment of the Insured Vehicle was relatively unaffected by the fire.



Photo 6 shows the interior compartment of the Insured Vehicle at the time of inspection. The rear portion of the interior compartment was significantly affected by the fire (circled).



Photo 7 shows a closer view of the rear portion of the interior compartment which was significantly affected by the fire.

6. At the time of inspection of the Insured Vehicle, we did not find any additionally fitted electronic and/or electrical component(s) on the Insured Vehicle. There also appears to be no modification(s) fitted on the Insured Vehicle.

Investigation and Technical Analysis

7. The Insured Vehicle has 2 engines. The main engine is situated beneath the front cabin. The sub engine is situated at the centre portion of the Insured Vehicle. The function of the sub engine is to power the movement of the Insured Vehicle's mechanical components. The mechanical components basically consist of a rotary brush on each side as well as a linear centre brush to sweep waste to a position and a high pressure fan in the suction system which creates a vacuum in the suction cup to draw the waste into a bin located at the rear portion of the Insured Vehicle.
8. For this particular case, the fire appears to have originated from the left centre portion of the Insured Vehicle, which houses the sub engine (herein referred to as "**sub engine compartment**"). This can be determined from the burn pattern and the high heat intensity burn marks (whitish burn marks) found on the left portion of the Insured Vehicle's sub engine compartment and also the rust that had developed at the areas around the sub engine compartment.

9. The whitish burn marks are a result of exposure to prolonged heat intensity. Rust would normally start to develop around these areas soon after a fire as prolonged exposure to high heat intensity usually causes steel/metal material body parts to be exposed to natural environmental condition. Hence the rust that had developed around the sub engine compartment of the Insured Vehicle is an indication that the fire to the Insured Vehicle had originated from the sub engine.
10. Under normal operational conditions, the sub engine compartment of the Insured Vehicle can be raised to reveal the sub engine via an external control panel which is located at the right centre portion of the Insured Vehicle. However due to the fire which had affected the electrical system of the Insured Vehicle, we were unable to gain access to the sub engine to access the degree of fire damage. See photos 8 & 10 below.



Photo 8 shows the sub engine compartment of the Insured Vehicle where the burn pattern and whitish burn marks were found (circled). Such whitish burn marks are a result of exposure to prolonged heat intensity, which had caused the steel/metal material of the sub engine compartment to be exposed to natural environmental condition. Hence the rust that had developed around the sub engine compartment of the Insured Vehicle is an indication that the fire to the Insured Vehicle had originated from the sub engine.



Photo 9 shows the right portion of the sub engine compartment which was badly burnt as a result of the fire (circled). Under normal operational conditions, the sub engine compartment of the Insured Vehicle can be raised to reveal the sub engine via an external control panel which is located at the right centre portion of the Insured Vehicle (arrowed).



Photo 10 shows a closer view of the external control panel which is used to raise the sub engine compartment of the Insured Vehicle to reveal the sub engine under normal operational conditions. However due to the fire affecting the electrical system of the Insured Vehicle, we were unable to gain access to the sub engine to access the degree of fire damage.

11. Upon closer examination around the areas in closest proximity to the sub engine which was where the fire to the Insured Vehicle had likely started, we had found several stretches of burnt wiring with greenish residue. These wirings were original factory fitted wirings below the sub engine compartment. We also found traces of greenish residue on several stretches of burnt wiring leading from the battery of the Insured Vehicle. The presence of greenish residue indicates internal heating of copper wires, a sign of an electrical short circuit occurring. The greenish residue is normally left behind from oxidation as a result of chemical reaction involving the copper wires. These physical evidences would appear to suggest that the cause of fire to the Insured Vehicle could have possibly been due to electrical in nature. See photos 11 - 17 below.



Photo 11 shows upon closer examination around the areas in closest proximity to the sub engine which was where the fire to the Insured Vehicle had likely started, we had found several stretches of burnt wiring with greenish residue. These wirings were original factory fitted wirings below the sub engine compartment (arrowed). We also found traces of greenish residue on several stretches of burnt wiring leading from the battery of the Insured Vehicle (circled). The presence of such greenish residue suggests occurrence of an electrical short circuit.



Photo 12 shows several original factory fitted wirings below the sub engine compartment with greenish residue (arrowed). The presence of such greenish residue suggests occurrence of an electrical short circuit.



Photo 13 shows a close up view of the greenish residue found on some of the burnt wirings below the sub engine compartment of the Insured Vehicle (circled). The presence of such greenish residue suggests occurrence of an electrical short circuit.



Photo 14 shows the several stretches of burnt wirings leading from the battery (circled) of the Insured Vehicle which had traces of greenish residue (arrowed). The presence of such greenish residue suggests occurrence of an electrical short circuit.



Photo 15 shows a closer view of the greenish residue found on some of the burnt wirings leading from the battery of the Insured Vehicle (arrowed). The presence of such greenish residue suggests occurrence of an electrical short circuit.



Photo 16 shows a closer view of the greenish residue found on some of the burnt wirings leading from the battery of the Insured Vehicle (arrowed). The presence of such greenish residue suggests occurrence of an electrical short circuit.



Photo 17 shows a close up view of the greenish residue found on some of the burnt wirings leading from the battery of the Insured Vehicle (arrowed). The presence of such greenish residue suggests occurrence of an electrical short circuit.

12. From the Police Report No. D/20180207/2019, Singapore Accident Statement and Veolia Preliminary Accident/Incident Report which were made by Mr Khairil Rezwan bin Roslan (herein referred to as "**Mr Khairil**"), we note that the fire to the Insured Vehicle had started at a time when he was driving the Insured Vehicle and waiting at a traffic junction. Mr Khairil was first alerted of the fire by another motorist.
13. We managed to speak to Mr Khairil on 13 March 2018 where we were able to gather further information pertaining to the incident as well as to the history of the Insured Vehicle.
14. According to Mr Khairil, on 6 February 2018, he drove the Insured Vehicle from Veolia along with his trainee, Mr Masran at approximately 0700 hours. He travelled along the West Coast flyover towards Cantonment Close which was the 1st scheduled cleaning location. At 1020 hours he proceeded along Cantonment Road from Cantonment Close to the next location at Eu Tong Sen Street. Mr Khairil was waiting at the traffic junction of Cantonment Road and Neil Road on the 1st lane. Suddenly he heard the sound of a car horn. He looked to his left and saw a lorry driver alerting him by pointing to the left portion of the Insured Vehicle. Mr Khairil alighted and went to check. He saw flames emitting from the left centre portion. He tried to raise the sub engine compartment via the external control panel but he could not raise it fully. He then quickly grabbed the fire extinguisher from the rear of the driver cabin, attempting to put out the fire. He was unable to extinguish the fire and immediately called the SCDF. Meanwhile Mr Masran was calling their team leader, Mr Jahis and reporting the incident to him.
15. Police were first to respond to the incident. They instructed both Mr Khairil and Mr Masran to move to the left side of the road. Police officers re-directed traffic while waiting for the SCDF. 2 fire bikes arrived in 10 minutes, cut the wires connected to the battery of the Insured Vehicle and attempted to put out the fire with foam extinguishers till the pumper arrived 5 minutes later. Firefighters took approximately 1 hour to extinguish the fire. Police and SCDF took down their statements and Mr Khairil assisted SCDF in their preliminary investigations.
16. The tow truck arrived at the incident location 20 minutes after the incident was reported to Mr Jahis. Mr Khairil was allowed to tow the Insured Vehicle after SCDF completed their preliminary investigations which took about an hour. The Insured Vehicle was towed to ComfortDelgro Engineering (herein referred to as "**Comfort**") located at 45 Pandan Road.

17. Mr Khairil made the Preliminary Accident/Incident Report at Veolia later that day. He lodged a police Clementi Neighbourhood Police Centre on 7 February 2018 at 1138 hours and proceeded to make an insurance report at Comfort at 1455 hours.
18. Mr Khairil mentioned that he is not the only driver of the Insured Vehicle. Drivers at Veolia are rotated to cover different jobs which require them to drive various vehicles. To the best of his recollection, there has not been any major mechanical problem and/or electrical problem with the Insured Vehicle whenever he was driving it.
19. With regards to the history of the Insured Vehicle, we were able to gather from Mr Myint Hlaing (herein referred to as "**Mr Myint**") who is the executive engineer of Veolia that the Insured Vehicle was purchased new 9 years ago.
20. Pertaining to the maintenance aspect, Mr Myint informed us that the Insured Vehicle was sent for periodical servicing every 3 months. The vehicle servicing is done at Veolia's in-house workshop.
21. Mr Khairil mentioned that there were neither warning lights displayed nor was there an abnormal rise in temperature throughout the period the Insured Vehicle was driven.
22. During the course of our investigations, we were able to obtain from Mr Myint the latest servicing and repair records of the Insured Vehicle. The last servicing before the incident was done on 24 November 2017 which had included the replacement of engine oil and oil filter. The other components were either adjusted or cleaned as per Veolia's Prevent Maintenance/ Inspect Report. Furthermore on 24 January 2018, the hydraulic fluid and battery water were topped up. The air filter was checked and the fan belt/tensioner was replaced. See invoices 1 & 2 below.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Service and Repair Report

Client: KCL Date: 24 Jan 2018 WO No: 34741

Location: Pan-Asia Zone: PARKS ON LOCKS ROAD

Type: DULVO DEER (PASS (ATV) KAR BUILDING NO. 04 (THUGA) RELIE ITS INURE (TRA CYCLE) LITTING ABOUTING PLANT (OTHER)

Vehicle No: Ym 94.3 Time-In: 17.30 Service-type: Scheduled Break Down/Workshop

Odometer/RH: Time-Out: 19.00

Feed Back: calibrated monthly inspection

Service and Repair for general

Engine oil/2T	Top Up/1	Oil Filter	R	Clutch	RRR	Tyre Replacement	
Hydraulic oil	Top Up/1	Fuel Filter	R	Brake (service/parking)	RRR	Front Right	RRR
Gear oil	Top Up/1	Air Filter	AC	Fan Belt/Tensioner	RRR	Front Left	RRR
Shock fluid	Top Up/1	Hydraulic Filter	R	Fuel pump/AC pump	RRR	Rear Right	RRR
Oil	Top Up/1	Horn/Winter	RRR	Fuel injection/Pipe	RRR	Rear Left	RRR
Coolant/Adhesive	Top Up/1	Pumps/Bulbs	R	Leaf spring	R	Rear End Right	RRR
Battery water	Top Up/1	Arrow/Beacon light	RRR	Ball Joint/Tie rod/Steering Pin	RR	Rear End Left	RRR
Greasing	R	Power window	R	Wheel nut/valve	R	AC system	RR
Water separator	R	Wiper	RR	Body Dented	RR	Brake L/R/GP	RRR

Hydraulic System (Body Discharge/Transmission/Suction/Sweeping/Lifting/Pulling)

Pump	RRR	Valve	RRR	Cylinder	RRR	Hose	RRR
Motor	RRR	Solenoid coil	RRR	Coupling/PTO	RRR	Seal	RRR

Pneumatic System (Narrow/Center brush/Flag/PTO/Vacuum)

Air tank	RRR	Valve	RRR	Adjuster	RRR	Hose	RRR
Lubricator	RRR	Solenoid coil	RRR	Cylinder	RRR	Seal	RRR

Water Sprayer / Jetting System

Pump	RRR	Valve	RRR	Nozzle	RRR	Hose	RRR
Coupling/PTO	RRR	Seal	R	Lubricator	RRR	Tank	RRR

Starting/Charging and Electrical System

Battery/Clip	RRR	Generator/Alternator	RRR	Fuel solenoid	RRR	Wiring/Switches	RRR

Suction System

Narrow/Rubber	RRR	Truck/Caster	R	Blade/Hooking	RRR	Roller/Folder	RRR

Tractor/Motorbike / Tricycle

Acc/Choke Cable	RRR	Brake/Clutch	RRR	Wiring/switches/plug	RRR	Frame/Drive Hub	RRR

Transmission Linkages

Throttle/Fur-Rev coil	RRR	Stop cable	RRR	Fabrication	DONE	Hot work	DONE

Other Repair

Part Used	
1- Castrol	375
2- Castrol	
3-	

Remark: replace Castrol oil

Mechanic: Sam

Please fill as shown online.

VEOLIA ENVIRONMENTAL SERVICES
7 Tuas Avenue 10 Singapore 639731
Tel: 655 885 0000 Fax: 655 885 1888
www.veolia-sg.com

VEOLIA ENVIRONMENTAL SERVICES

Invoice 1 shows the last repairs done to the Insured Vehicle on 24 January 2018 at the Veolia in-house workshop (arrowed) which included the topping up of hydraulic fluid and battery water. The air filter was checked and the fan belt/tensioner was replaced.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

VEOLIA **JOHNSTON 600 SWEEPER**
Prevent Maintenance / Inspection Report

Vehicle No: YM 9113 WO No: 24179
Type of Service: QRC Date: 24 11 17
Mileage: 76249 (2 Eng) Time in: 0045
Engine Hour: Time Out: 0215

Description	A/C	R	RR	TU	Remarks
1. Replace engine oil and filter		✓			engine oil oil
2. Replace fuel filter		✓			
3. Check Air filter and clean housing	✓				Care
4. Check fan drive - V belt, pulley and belt tension condition					Care
5. Check cooling system- radiator, hoses, pump and connections					Care
6. Clean radiator fan and check coolant level					Care
7. Check Engine - fuel pump, injectors, fuel line and mounting					Care
8. Check torque converter and impeller gear oil level					Care
9. Check brush plate, brush arm, motor, cylinder					Care
10. Check L&R suction nozzle assembly, cylinders and linkages					Care
11. Check centerbrush, cylinders, hoses and attachment					Care
12. Check Impeller fan, housing and control flap					Care
13. Check hopper, intake dust and sealing					Care
14. Check water sprinkler system- water pump, hoses and spray nozzles					Care
15. Check sys. System- pump, motor and hoses					Care
16. Check Electrical system- safety switch and wire					Care
17. Drain air reservoir and lubricator					Care
18. Greasing on all grease nipples, linkages and attachment					Care
19. Repair / replace and top up as necessary for above checked					Care
20. Run Engine and conduct all functional check					Care

(Note: Any found unusual and abnormality has required to report to Engineer.)

ABBS
A/C : ADJUST OR CLEAN
R : REPLACED
RR : REPAIRED
TU : TOP UP

Remarks : _____

Follow Up Action Remarks : _____

Attended By: Sing Iyotina Check By: Arya

VEOLIA ENVIRONMENTAL SERVICES
11 Tuas Avenue, 12 Singapore 639121
Tel: +65 62563561 Fax: +65 62563562
www.veolia-es.com

0000-0146-0147-24

Invoice 2 shows the last servicing package done on the Insured Vehicle on 24 November 2017 at the Veolia in- house workshop (arrowed) which included the replacement of engine oil and oil filter. The other components were either adjusted or cleaned as per Veolia's Prevent Maintenance/ Inspect Report.

23. To the best of Mr Myint's recollection, there has not been any major mechanical problem and/or electrical problem with the Insured Vehicle. He also informed us that ever since the Insured Vehicle was purchased, there has not been any modification(s) and/or additional electrical or electronic component(s) fitted to the Insured Vehicle.

Site Inspection

24. With the information gathered, we visited the incident location on 14 March 2018 taking the reports made by Mr Khairil and the information that we had gathered from him as references.
25. Firstly, we note that the incident had occurred at the traffic junction of Cantonment Road and Neil Road along the 1st lane.
26. There is a traffic camera affixed near the traffic lights at the left side of the traffic junction. However we were unable to view or obtain the footage for security reasons.
27. At the time of visit, we observed burn marks and/or burnt residual remains on the ground where the Insured Vehicle was positioned. Apart from the burn marks on the ground, we did not observe any other damaged or newly replaced government property at the time of our visit to the incident location. No further information could be gathered during our site inspection other than the observation that the area where the Insured Vehicle was positioned when the incident occurred was not a secluded location. See photos 18 - 21 below.



Photo 18 shows the traffic junction of Cantonment Road and Neil Road (arrowed) where the incident occurred along the 1st lane. There is a traffic camera affixed near the traffic lights at the left side of the traffic junction (circled).




Photo 19 shows a closer view of the traffic camera affixed near the traffic lights at the left side of the traffic junction (circled). However we were unable to view or obtain the footage for security reasons.



Photo 20 shows the burnt marks and/or burnt residual remains on the ground where the Insured Vehicle was positioned at the time of incident (circled). No further information could be gathered during our site inspection other than the observation that the area where the Insured Vehicle was positioned when the incident occurred was not a secluded location.



Photo 21 shows a closer view of the burnt marks and/or burnt residual remains on the ground where the Insured Vehicle was positioned at the time of incident (circled). Apart from the burn marks on the ground, we did not observe any other damaged or newly replaced government property at the time of our visit to the incident location.

Incident Scene Photographs

28. We were able to obtain photographs from Ms Myint taken by Mr Khairil at the incident location. The photographs were taken during the fire and after the fire to the Insured Vehicle were extinguished.
29. In general, the information that could be gathered from these photographs had corresponded to the events that were related to us by Ms Khairil. Our close examination of these photographs also showed no unusual foreign material(s) and/or object(s) found on the ground in the immediate area where the Insured Vehicle was positioned. See photos 22 – 25 below.



Photo 22 shows the left centre portion of the Insured Vehicle engulfed in flames before the arrival of the SCDF. In general, the information gathered from this photograph had corresponded to Ms Khairil's statement, which is the fire started from the left portion of the sub engine and that he tried to raise the sub engine compartment but it could not be raised fully (circled).



Photo 23 shows the SCDF attending to the fire.



Photo 24 shows firefighters ensuring that the fire was completely extinguished.



Photo 25 shows the Insured Vehicle after the fire was extinguished. In general, the information gathered from this photograph had corresponded to Ms Khairil's statement, which is the incident had occurred at the traffic junction of Cantonment Road (circled) and Neil Road along the 1st lane as well as police officers were present at the scene to re- direct traffic (arrowed).

30. Given the circumstances of the incident as reported, the possibility of the cause of fire to the Insured Vehicle being due to the sub engine overheating would seem unlikely as Mr Khairil had mentioned to us there were no indications of abnormally high temperatures on the Insured Vehicle when he was driving before the incident occurred.
31. The possibility of the fire being due to external factors (foreign material(s) stuck on hot surfaces, arson and sabotage amongst others) would also seem unlikely as the fire was confined to the centre portion, with no visible exterior damage to other parts of the Insured Vehicle. The location of where the Insured Vehicle was positioned was also observed to be not at a secluded location.
32. The possibility of the fire being due to electrical in nature would then seem more likely given that engine overheating and external factors would both seem unlikely. The fire being due to electrical nature is also supported by the condition of the wirings that were found beneath the sub engine compartment as well as the wirings leading from the battery of the Insured Vehicle, which was earlier discussed in paragraph 11 above.

33. Our checks with both local and international bodies and associations had revealed that at the time of writing this report, there was a manufacturer recall on 21 January 2009 for the insufficient Storage Management System of Materials (Zinc & Nylon) resulting in zinc oxidation becoming advanced and distended. However the fault was rectified on 25 March 2009. See search result from LTA below.

Enquiry on Vehicle Recall - Vehicle Specific

* ONLY INFORMATION ON VEHICLE RECALLS SUBMITTED FROM 9 APRIL 2007 IS AVAILABLE

Vehicle Owner Particulars

Owner ID Types: Company
Owner ID: 3106N

Vehicle Details

Vehicle Registration number: YM9113
Make: ISUZU
Vehicle Model: FTR34P
Engine No.: 6HK1466043
Chassis No.: JALFTR34P67000023

Recall Details

1 Recall No.: R2009030015
Manufacturer Recall Date: 21 Jan 2009
Estimated Completion Year of Recall: 2009
Brief Description (As Provided by Motor Dealer): The insufficient Storage Management System of Materials (Zinc & Nylon) and Zinc Oxidation becomes advanced and distended.
Date Rectified: 25 Mar 2009
For more details, contact TRIANGLE AUTO PTE LTD
Hotline Information: Winnie Tan at 68614800

OK


Please do not use your browser's Back or Forward buttons as this may result in information loss.

Conclusion

34. Having investigated and technically analysed the damages of burnt nature to the Insured Vehicle, we are of the view that the cause of fire to the Insured Vehicle was of electrical in nature. For this particular case, the fire had originated from the wirings from the sub engine of the Insured Vehicle. The wirings were original factory fitted wirings of the Insured Vehicle.
35. We did not find any evidence which had suggested that the cause of fire to the Insured Vehicle was due to poor maintenance and/or recurring electrical problem.
36. There were no modification(s) or additional electronic and/or electrical component(s) fitted on the Insured Vehicle at the time of our inspection of the Insured Vehicle.
37. Our investigations had also revealed that at the time of writing this report, there is no manufacturer recall of electrical nature to similar make and model vehicle as the Insured Vehicle that may possibly be related to this incident.
38. SCDF was activated to attend to the fire incident and a fire report pertaining to their findings will likely be forth coming. We have applied for this fire report and will forward a copy of the report once it is made available to us.

**Muhd Nazril**

Technical Investigator


Ang Bryan Tani

AMSOE, AMIRTE, AFF SAE, M.MATAI, AFF.Inst.AEA

Senior Technical Investigator

Technical Investigation & Reconstructionist (SAE-A)

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.