



Your Ref: TP/IP/39647/2018
Our Ref : CI/TPD18014220/Z

26th September 2018

Fatal Accident Investigation Team
Traffic Police Department
Singapore Police Force
10 Ubi Avenue 3
Singapore 408865

MECHANICAL INSPECTION REPORT OF MOTORCYCLE NCY 1262

1. We refer to your request dated 02nd August 2018 to conduct a physical inspection of a motorcycle bearing registration number NCY 1262 (herein referred to as "**Motorcycle**"), which was involved in a fatal road traffic accident on 12th July 2018.
2. The purpose of this inspection is to primarily determine if there was any possible mechanical failure to the Motorcycle that may have contributed to the accident.
3. Following the request, we had carried out a physical inspection of the Motorcycle on 31st August 2018 at the premises of Traffic Police vehicle pound, 517 Airport Road Singapore 539942. We now set out below our observations and comments with respect to this inspection.

General Condition

4. The mileage of the Motorcycle recorded at time of our inspection was 614973km.
5. The Motorcycle was observed to have sustained minor damages at the frontal portion. The body parts that were found to have been damaged include its front fairing cover, headlamp, wing mirror, front left signal lamp, front mudguard and rear tail lamp amongst others as a result of the accident.
6. This was likely due to the consistency of the accident's case facts that the Motor Cycle rider was travelling along PIE (Tuas), 36.5km on the left of a 2 lanes road when it suddenly collided onto the rear of a Motor Lorry that was travelling on the left lane. Due to impact, the motorcyclist skidded to the right side and encroached into the travel path of a Motor Taxi that was travelling on the right lane. As it was too sudden, the Motor Taxi was unable to brake in time hence collided into the motorcyclist. See photo 1 to 7 below.



Photo 1 shows a close-up view of the mileage meter at time of our inspection. The mileage was recorded at 61497.3km.



Photo 2 shows a general view of the front body of the Motorcycle at the time of our inspection. The Motorcycle was observed to have sustained relatively minor damages as a result of the accident's impact.



Photo 3 shows a general view of the right body of the Motorcycle at the time of our inspection. The Motorcycle was observed to have sustained relatively minor damages on the front right side fairing at time of our inspection.



Photo 4 shows a general view of the rear body of the Motorcycle at the time of our inspection. The Motorcycle was observed to be in good condition unaffected by the accident's impact collision.



Photo 5 shows a general view of the left body of the Motorcycle at the time of our inspection. The Motorcycle was observed to have sustained relatively minor damages on the front left side fairing at time of our inspection.




Photo 6 shows a closer view of the front fairing cover of the Motorcycle at the time of our inspection. The Motorcycle was observed to have sustained with relatively minor damages due to the accident collision.)



Photo 7 shows a closer view of the front headlamp of the Motorcycle at the time of our inspection. It was observed to have sustained with relatively minor damages due to the accident collision.

Tyres and Wheel Rims

7. The condition of the Motorcycle's 2 tyres was observed to be in serviceable condition. The tread pattern of the 2 tyres was clearly visible. We did not observe any tear, burst mark(s) and/or punctured hole(s) on the sidewalls as well as across the tread of the 2 tyres. The 2 tyres were both observed to be sufficiently inflated for vehicular operation. The tyre brand, tyre size and remaining tread depth of the 2 tyres were recorded as follows:-



Maxxis Diamond MA-3D 80/90 - R17 (3mm)

Maxxis Diamond MA-3D 70/90 - R17 (4mm)

8. The rear tyre was wrapped around alloy wheel rims that were found to be without any significant damage. See photo 8 & 9 below



Photo 8 shows the rear tyre of the Motorcycle. The rear tyre was observed to be in serviceable condition with remaining tread depth of approximately 3mm. The tyre was also observed to be sufficiently inflated for vehicular operation.



Photo 9 shows the front tyre of the Motorcycle. The front tyre was observed to be in serviceable condition with remaining tread depth of approximately 4mm. The tyre was also observed to be sufficiently inflated for vehicular operation.

Engine & Drive Train

9. Upon examination of the Motorcycle's engine area, we had observed that the various engine related parts and components were intact with no visible damage. There was also no sign(s) or indication(s) of fluid leak observed around the engine area of the Motorcycle.
10. The gear chain of the motorcycle was found to be intact without any misalignment. It was also adequately lubricated for operating purposes. Free play tension test was also conducted & found adequately acceptable. See photo 10 – 13 below.



Photo 10 shows no sign(s) or indication(s) of fluid leak observed around the underside of the engine area of the Motorcycle.



Photo 11 shows no sign(s) or indication(s) of fluid leakage stain observed around the engine area of the Motorcycle.



Photo 12 shows the general view of the gear train (arrowed) of the Motorcycle, which was observed to be intact with no misalignment. It was also adequately lubricated for operating purposes.



Photo 13 shows the general view of the gear train (arrowed) of the Motorcycle, which was observed to be intact with no misalignment. It was also adequately lubricated for operating purposes. Free play tension was also observed & found adequately acceptable.

Steering System & Braking System

11. Our checks on the various steering components of the Motorcycle had revealed that its steering system was not in serviceable condition. Its steering system (handle bar) was found to be stuck to the left side likely due to the accident's impact collision. We were unable to freely turn the handle bar to the left & right. However, we can only move the Motor Cycle forward & backward manually for the purpose of testing the braking system.
12. The brake system of the Motorcycle was of a semi-hydraulic type, where hydraulic (brake fluid) pressure controls the brake for the front wheel while the brake for the rear wheel is controlled by mechanical means (cables and springs). The brake for the front wheel is engaged by pulling the brake lever at the right side of the Motorcycle's handle bar while the brake for the rear wheel is engaged by stepping on the brake pedal at the right side foot rest of the Motorcycle.

13. Static brake tests conducted on the Motorcycle front & rear brakes had appeared to indicate that the braking system of the Motorcycle was in serviceable condition. The Motorcycle's braking system like the brake discs, brake callipers, brake lever, brake foot pedal and brake hoses revealed all to be intact and without damage. There was some resistance felt (spongy like feel) upon pressing the brake lever. This would indicate that there was no leakage of pressure/vacuum in the brake system. Our checks on the brake fluid had also indicated that the brake fluid was of sufficient level for operational purposes, and without contamination.

Operational Test

14. For this case, we were not able to carry out any operational tests to the steering system and braking system of the Motorcycle due to the unavailability of the key & also damages sustained that effects the Motorcycle's operational process, which had rendered the Motorcycle immobility for the operational tests. However, we were able to push the motorcycle manually forward and backward, simulating movement of the Motorcycle, for the operational tests. Both brakes were engaged simultaneously while conducting the manual movements and it was observed to be in serviceable condition.

In general, the observations gathered during the static brake test & manual movement test had indicated that the braking system of the Motorcycle was in serviceable condition. See photo 14 - 18 below.



Photo 14 shows our checks on the brake fluid (front) reservoir had also indicated that the brake fluid was of sufficient level for operational purposes, and without contamination.



Photo 15 shows our checks on the rear brake mechanical components. It was observed to be unaffected by the accident's impact.



Photo 16 shows testing of the braking of the front brake in progress. There was some resistance felt (spongy like feel) upon pressing the brake lever.



Photo 17 shows testing of the braking of the rear brake in progress. There was some resistance felt (spongy like feel) upon stepping on the brake pedal.



Photo 18 shows the front brake pad at time of our inspection. The frictional material was observed to be sufficient for operational purposes.

Conclusion

15. Basing on our physical inspection of the Motorcycle, it appears that the braking system of the Motorcycle were all in serviceable condition. Its steering system on the other hand was damaged as a result of the accident's impact collision. We did not find any evidence(s) to suggest that there was possible mechanical failure to the Motorcycle that may have caused and/or contributed to the accident.
16. The tyres of the Motorcycle were found to be in a serviceable condition. There was no tear, cut or burst mark(s) on the outer and the inner sidewalls as well as across the tread of the tyre. It was sufficiently inflated for vehicular operation with remaining tread depth of approximately 3 & 4mm.

17. Our findings were based solely on a static test, visual inspection and manual test of the Motorcycle simulating its movement. No operational test(s) could be carried out to the Motorcycle due the unavailability of the key & also the damages sustained that affects the Motorcycle's operational process, which had rendered the Motorcycle's immobility.



Rohaizal A. Rahim
Technical Investigator



Ang Bryan Tani
AMSOE, AMIRTE, AFF SAE, M.MATAI, AFF.Inst.AEA
Senior Technical Investigator
Technical Investigation & Reconstructionist (SAE-A)

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.