	11) Europe Je		NMENT (Office)	Date/T	ime: 16/8/188 6.200m
Estimated C		wa sana	Bill to:		
To Inspect V at Workshop of	/ehicle No: om/s	STU 25 Comfort Del 205 Prud	667	Insured:6	SH 7699X 3837362
Policy No:_ Sum Insured		200 Stud	Claim No:	D1800 6	6066 MFSH
Make of Veb (Client's Recor			Excess:	D.O.A.	8108 36 01
CA / REV Date/Time: 1	/ REP. / REV 24 1-490m 016 811	HRS (DS) Person Contact	ad Andrew	H.O.D	Endorsement:
Date/Time		( ) Estim			
भागाहर	11201- NEVISE	ld to Severe	16006614/1- Ler by em	~i .	80A: 7/4/16
	Lemete.	finelitied A. 16.64, 61%	mal STA \$ 14	52.24	+

ASS. REC. BY: REF: 18621	
300 M 14 St	ASSIGNMENT
From: Date:	Veh No: SLU 25667 Yr Regn: 11, 17
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD TP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	1 79
at Workshop m/s Con Del	Colour 2 C.c . 1476
of	So Date of Std / NI / NA
Insured:	Sp.Reading 150 49 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	Gen. Cond: Knod! Fair   Barrie   22 A 8 J 018 2572
Sum Insured: Excess:	Burnt
(Client's Record)	Steering: Inogeter / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inofder / Jammed / Leaked / Burnt or
	Modi: NII / S/RIm / STD A/RIm or
(Policy Condition)	Tyre Size: F: 205/60R16
Remark: The veh had commenced to	R:
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value: B 77/	TOYO / YOKO OF
	<u>Front</u> <u>Rear</u>
	R/Bal. 9 mm R/Bal. 9
The state of the s	UBal. 9 mm UBal.
200/0 168 01 140	D.O.A. 10/8/18 D.O.I. 18/8/118
	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OU	T   Rooftop or
- Ferson Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
A COOLLA HISTOCOOU	arrected due to collision.
18/1 File pass to Carriering	
RECEIVED 2 - NOV-	
HOY-	2018
*	
Data/Time, Fig Pass to? : Prell. Report	the second secon
1) 7/11 MMGY TILLIA	Days Of Repair: 2
Cote/Time, File Return to?	Resurvey No. of Trip:   Survey Fee: 130
7)	Transportation: 6-0
Add Fee:	: Site Insp (\$
Report Format :	: Interview (\$ ) Factors
Lump 9/ 11 D 1	Tech Invs (\$ ) Others
Lump Sum / I.B.I: (S 1452,74 1	Weekend (\$
158	10TAL 7/1 1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

EID/	T OADITAL INDIA		rnationale Des Experts En Auton	MANUAL PROPERTY OF THE PARTY OF			
FIR	ST CAPITAL INSUI	RANCE LTD	Ref : CS/FCI180149	63/Kqd3			
36 F	OBINSON ROAD						
		INGAPORE 068877	Date: 16-08-2018				
			Code: FCI2				
1.		Policy Particu	lars :- THIRD PARTY CLA	IM			
	Insured Veh.	SH 7699X	Veh. Inspected	SLU 2566T			
	Policy No.		Coverage (\$)	0.00			
	Claim No.	D18006066MFSH	Excess (\$)	0.00			
	Assign From	CWS (SERENE LER)	Assign Date	16/08/2018			
2.		Vehicle F	Particulars & Condition				
	Make & Model		c.c	0			
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer		Steering				
	Brakes		Modification				
	General						
3.		Co	nditions of Tyres				
		Size	Make	Balance			
	R/H Front Tyre			mm			
	L/H Front Tyre			mm			
	R/H Rear Tyre			mm			
	L/H Rear Tyre			mm			
4.		Desc	ription of Damages				
5.	Eliandian No.	Rupper A Ge	neral Information				
	Accident Date	10/08/2018	Inspection Date	16/08/2018			
	Survey held at	COMFORTDELGRO ENGI	NEERING PTE LTD				
		205 BRADDELL ROAD Blk C, 3rd Floor SINGAPORE 579701.					
		AND A PROPERTY AND ADDRESS OF THE PARTY OF T	Remarks				



MS First Capital Insurance Limited co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 069877 Tet: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

#### MOTOR SURVEY ASSIGNMENT

Date

13-08-2018

Our Ref No. D18006066MFSH

**Accident Date** 

10-08-2018

Claim Type. Third Party

Insured Vehicle

SH7699X

Third Party Vehicle. SLU2566T

Survey Location

205 BRADDELL ROAD BLOCK C CAR DEPT

Contact Person.

**ANDREW** 

Contact No.

63837362/0

Fax No. 62815767

Survey Type

DIRECT SETTLEMENT: EST. COR - \$2290.00

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

#### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

#### THIRD PARTY SURVEY REQUEST

Cc: Workshop

COMFORTDELGRO

ENGINEERING PTE LTD

Attention. NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SERENE

#### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

# Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 17 August 2018 3:58 PM

To:

'Claim Workflow System'; assignments

Cc:

SERENELER@MSFIRSTCAPITAL.COM.SG; SUR RE: SURVEY ASSESSMENT - D18006066MFSH/1

Subject:

Attachments:

CSFCI18014963Kqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SLU 2566T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 16 August 2018 2:10 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18006066MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

## LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 16 August 2018 8:19 AM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18006066MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey. Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards, Admin Team Claim Workflow System



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18006066MFSH

Date: 17 August 2018

Our Ref: CS/FCI18014963/Kqd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


#### INITIAL INSPECTION REPORT OF VEHICLE NO. SLU 2566T.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/08/2018 at the premises of M/s COMFORTDELGRO, and have the following to report:-

Workshop Estimate Amount	: S\$	3,768.88	
Revised Estimate Amount	: S\$	1,452.24	
"Check" Items Amount	: S\$	280.00	
Market Value	: S\$	=	
LTA Reimbursement Value	: S\$	<u> </u>	_
Nett Value	: S\$	2	- 63

Description of Damage:

<u>The vehicle sustained damages</u>
at the rear portion.



Yours faithfully

KONG SENG CHEONG Licensed Appraiser MBHH18103523-01 / Ajax Mars Pie Ltd - Bukit Merah ENTRY DATE & TIME: 11/08/2018 01:08 SUBMITTED BY: Victor Ang

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	м	DEK	т ет	ΓΑΤΕ	ᄥᄹᄃᅅ	п
AL	ωı	DEN		AIE	MEN	ш
	_					

11/08/2018 01:08 Date Of Report 10/08/2018 14:00 Date Of Accident

ALONG PUNGGOL EAST Exact Location Of Accident

SINGAPORE Country/State of Loss

#### DETAILS OF OWN VEHICLE

SLU2566T Vehicle Registration Number

Insured/Policyholder

COMFORTDELGRO RENT-A-CAR PTE. LTD Name Of Registered Owner

198105775H Co Reg No NOEMAIL Email Address

Mobile Phone No

OFFICE-68820888 Alternative Phone No

Vehicle Particulars

MAZDA Manufacturer MAZDA 3 Model

Exact Purpose for which vehicle was being used at PRIVATE time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

THIRD PARTY If No, Please state action to be taken PRIVATE CAR Vehicle Category

Insurance Company

INDIA INTERNATIONAL INSURANCE PTE LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

YES Fleet Policy M460802 Policy Number N.A. Cover Note Number

Driver

TAN BAN HONG Name of Driver

S7924122I NRIC No 17/08/1979 Date Of Birth INDOOR Occupation 01/04/2004 Date Of Driving Pass

14 YEARS AND 4 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-90118083 Mobile Number

Fax Number

OFFICE-90118083 Contact Number

EMail Address NOEMAIL Address

BLK 637A PUNGGOL DRIVE

#11-431

Postcode

821637

NO

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured Vehicle Registration Number of Driver's Own

Vehicle

OTHER - HIRER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes,Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

## Circumstances of Accident

I was traveling along Punggol East on the left lane. I braked my car to a stop when taxi SH7699X from behind collided onto the rear of my car. Damages to my car were on the rear portion. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

## DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SH7699X

Vehicle Make/Model/Colour

HYUNDA/I40 1.7L CRDI/BLU

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan

# The TRAIT PLAY POST TOTS 2. The second content of the American Colors and the

## Common Statement

I was traveling along Punggol East on th SH7699X from behind collided onto the rear portion. No injuries were involved.	e left lane. I braked my car to a stop when taxi rear of my car. Damages to my car were on the
Taxi Voucher No.	
DECLARATION	
VERIFIED BY AJAX MARS REPORTING OFFICER - MUHAMMAD FAIZAL BIN PABILA	ged above are true in every aspect
	4
MARS Officer	
Job Complete Date/Time	Registered Owner or Driver's Signature  Date/Time:
10 August 2018 at 5:41 PM	10 August 2018 at 5 41 PM



# 205 Braddell Road S(579701)

# ACCIDENT REPAIR ESTIMATE

Our Ref:					CL U2566T
Type of Claim	TP		Vehicle No.	100	SLU2566T
			Make & Model	1	MAZDA3 SEDAN 1.5 AT EU6_
			Year of Manufacture	0.0	2017
			Chassis No.	:	JM6BN22A8J0182572
Ins Company :1	II / FCI		Engine No.	:	
Excess :			Policy No.		W
Date of Accident : 10	/08/201	8	Time of Accident	1	·
Suggested Days of Repair :			In-house Vehicle Asses	SSOT	
Repair Estimate			Case Owner	:	Andrew
			Signature		
Parts (a) Cost/List Price Items	<u>s</u>	1,498.60	Contact No		
Plus/Less 20%	s	299.72	Frt Counter Operation	on	
rius/Less			6383 7466 - Patrick Tia		
Total of Cost / List	S	1,198.88	6383 7730 - Brenda Ng 6383 7890 - Rohani		
(b) Nett Price Items	S	*	braddell er@sparkearea	re.cor	n
Less			Workshop Operation 63837656 - Ngo Toh W		
Total of Nett Item			63837362 - Andrew Go		
		280.00	63838115 - William Wa	ang	
(c) Special Nett Items	<u>s</u>	280.00	braddell_operation@sps	arkear	rcare.com
Total Parts Cost (Appendix A)		1,478.88			NOT North ente
Labour (Appendix B)	S	2,290.00			Not Noth ante Meany B4 pains
Total Repair Cost	S	3,768.88			1 of pains
The above total will be subjected to	7% G.S.	<i>T</i> ,			
			Kenne		4
Name of Surveyor	93 90	-	CKIC		
Company			16/8/18 at		
Survey conducted on			at _		
Remarks By Surveyor					
(a) The repair of this vehicle is	aubertz	ed / is not autho	rized until further notice.		
(b) Recommended Days of Rep	air :		02 day(s)		
(c) Resurvey		; Required /	of Required		
(d) Excess		:\$	ο		1/101.0
(e) Signature of surveyor		1	se p	ate:	16/8/18

# Spark Car Care

# ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

## Spare Parts

Vehicle No	: SLU2566T	Case Owner	Andrew
Make & Model	: MAZDA3 SEDAN 1.5 AT EU	Year Manufacture	: 2017
Chassis No	: JM6BN22A8J0182572	Engine No	: <u>0</u>
Sales Order	d	Supplier	3/
Order By	#	Type of Claim	; <u>TP</u>

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	s		Disposition By Surveyor
1	Rear bumper	1	Pull Br	\$	1,074.80		_		
2	Rear bumper lower garnish	1	NN		TBA				
3	Rear bumper tow cover LH	1	Su	\$	15.70				X
4	Rear bumper tow cover RH	1	Sn	S	15.70				×
5	Rear bumepr reflector LH	1	Sh	\$	50.40				×
6	Rear bumper reflector RH	1	Sh	S	50.40		_		×
7	Rear bumper side retainer LH	1	14	S	36.10				×
8	Rear bumper side retainer RH	1	Sh	\$	36.10		-		X
9	Rear bumper clips	10	M	S	28.00				-
10	Bootlid emblem logo	1	n	\$	74.40		-		X
11	Bootlid emblem SKYACTIV	1	11	\$	63.60		-		×
12	Bootlid emblem MAZDA 3	1	12	S	53.40				(6)(4)
13	Reverse sensor	1					S	280.00	? XS
14	0	0							
15	0	0							
. 16	0	0							
17	0	0							
18	0	0		_			_		-
19	0	0					+		
20	0	0		1					
21	0	0		$\perp$					-
22	0	0		-					
23		0		1					
24	0	0		1					
25	0	0		1					
26	(2)	0		1			-		
27	0	0		+					
28	0	0		$\perp$		2			
25	0	0		1			_		
30		0							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

# ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

#### Labour

 Vehicle No. :
 SLU2566T
 Case Owner
 :
 Andrew

 Make & Model :
 IAZDA3 SEDAN 1.5 AT EU6
 Year of Manufacture
 :
 2017

/No	Labour Description	Esimated Price	Adjusted Price
1	To panel beat, repair rear end panel, bootlid and to replace damaged	\$720.00	2401
-	parts		
2	To install reverse sensor	\$120.00	801
3	To apply rust proofing on repair and replace panels	\$200.00	X
4	To putty and spray paint rear bumper, rear bumper lower garnish,	\$1,250.00	2501
5.50	bootlid, rear end panel and all affected areas		
	LKK Auto Consultants hence notify the Repairer of the following:		
	the Repairer of the following:  To resurvey before after spray painting  To display damaged part(s) during resurvey		
	Parts prices are subject to confirmation     Third party survey is on a "Without Prejudice" basis		
	No illegal modification(s) is allowed     Supplementary :tem(s) must be resurveyed and     is subject to final approval from insurance Company		
	Acknowledged by Repairer		
	Date:		
		1	
-			
$\vdash$			
-			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

# Spark Car Care

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

## Spare Parts

. · ·

Vehicle No	: <u>SLU2566T</u>	Case Owner	: Andrew
Make & Model	: MAZDA3 SEDAN 1.5 AT EL	Year Manufacture	: 2017
Chassis No	: JM6BN22A8J0182572	Engine No	: 0
Sales Order	1	Supplier	1
Order By		Type of Claim	: <u>TP</u>

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1	null Bu	\$	1,074.80	/		
-	Rear bumper lower garnish.	1			TBA			
3	Rear bumper tow cover LH	1	Su	\$	15.70			X
4	Rear bumper tow cover RH	1	Sn	\$	15.70			X
5	Rear bumepr reflector LH	1	Su	S	50.40			×
6	Rear bumper reflector RH	1	Sh	\$	50.40			*
7	Rear bumper side retainer LH	1	54	\$	36.10			X
8	Rear bumper side retainer RH	1	Sh	S	36.10			X
9	Rear bumper clips	10	M	\$	28.00	/		
10	Bootlid emblem logo	1	n	\$	74.40			X
11	Bootlid emblem SKYACTIV	1	22	\$	63.60			×
12	Bootlid emblem MAZDA 3	1	nn	S	53.40			X
13	Reverse sensor	1				Sn	\$ 280.00	*
14	0	0						
15	0	0						
16	0	0						
17	0	0						1
18	0	0						
19	0	0			need the street			
20	0	0		_				
21	0	0		_				
22	0	0		_				-
23	0	0		_				
24	0	0						
25	0	0						-
26	0	0						
27	0	0						
28	0	0		1				-
29	0	0		_				
70	0	0						1

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care ComfortDelGro Engineering Pte Ltd 205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No.	:	SLU2566T	Case Owner	4	Andrew	
Make & Model	:	IAZDA3 SEDAN 1.5 AT EU6	Year of Manufacture	1	2017	

S/No	Labour Description	Esimated Price	Adjusted Price
1	To panel beat, repair rear end panel, bootlid and to replace damaged	\$720.00	2401
	parts		
2	To install reverse sensor	\$120.00	801
3	To apply rust proofing on repair and replace panels	\$200.00	X
4	To putty and spray paint rear bumper, rear bumper lower garnish,	\$1,250.00	2501
= 710	bootlid, rear end panel and all affected areas		- Marian Marian
			-A-
			310
	LKK Auto Consultants hence notify the Repairer of the following:  • To resurvey before after spray painting  • To display damaged part(s) during resurvey  • Parts prices are subject to confirmation  • Third party survey is on a "Without Prejudice" basis  • No illegal modification(s) is allowed		
	Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from insurance Company		
	Acknowledged by Repairer Signatures	4	
	70 = Conneth Date:  Parts = 1100.50		
	- / A ( a) . H( )		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

## Shiau Chan (LKKAuto)

From:

Admin-D (LKKAuto)

Sent:

Wednesday, 21 November 2018 9:03 AM

To:

'CWS Motor Claims'; SUR

Cc:

'Serene Ler'; assignments

Subject:

RE: REQUEST OF SURVEY REPORT-OUR REF:D18006066MFSH;ACCIDENT

INVOLVING SH7699X AND SLU2566T ON 10-08-2018

Dear Sir / Madam,

Thank you for your email.

Dear Shiau Chan,

FYNA. Our Ref: CS/FCI18014963/Kqd3

Best Regards,

Catherine Chong | Admin

#### LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Tuesday, 20 November, 2018 9:33 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg> Subject: REQUEST OF SURVEY REPORT-OUR REF:D18006066MFSH;ACCIDENT INVOLVING SH7699X AND SLU2566T

ON 10-08-2018

Dear Sir,

We received LOD from workshop/solicitor.

Please let us have the Survey Report including Vehicle Inspection Photos & Survey Fees Invoice asap.

Kindly upload the survey report through CWS from document management screen by selecting option Survey report.

Thanks & Regards, Motor Claims Department MS First Capital Insurance Ltd cwsmotorclaims@msfirstcapital.com.sg



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014963/Kqd3e2		
86 RC	BINSON ROAD	NGAPORE 068877	Date: 22-11-2018 Code: FCI2		
		Policy Particula	rs :- THIRD PARTY CLAI	M	
_	Insured Veh.	SH 7699X	Veh. Inspected	SLU 2566T	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D18006066MFSH	Excess (\$)	0.00	
	Assign From	SERENE LER	Assign Date	16/08/2018	
2.		Vehicle Pa	articulars & Condition		
	Make & Model	MAZDA 3 (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JM6BN22A8J0182572	Colour	METALLIC GREY	
	Odometer	15078	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.		Con	ditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	YOKOHAMA	9 mm	
	L/H Front Tyre	205/60 R16	YOKOHAMA	9 mm	
	R/H Rear Tyre	205/60 R16	YOKOHAMA	9 mm	
	L/H Rear Tyre	205/60 R16	YOKOHAMA	9 mm	
4.			iption of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		Gen	eral Information		
	Accident Date	10/08/2018	Inspection Date	16/08/2018	
	Survey held at	COMFORTDELGRO ENGIN	EERING PTE LTD		
	7486	205 BRADDELL ROAD Blk C, 3rd Floor SINGAPORE 579701.			
5a.			Remarks		
	BITHE INSPECTI	NSISTENT TO ACCIDENT RE ON WAS CONDUCTED ON A ICE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BA	SIS. ISED REPAIRS.	
5b.		Estim	nate Days of Repair		
-	ESTIMATED NOR	RMAL PERIOD FOR REPAIR:	2 Working Da	iys	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 2566T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / BUCKLED	1,074.80	1,074.80
1	REAR BUMPER LOWER GARNISH (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER TOW COVER LH	SERVICEABLE	15.70	
1	REAR BUMPER TOW COVER RH	SERVICEABLE	15.70	
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	50.40	
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	50.40	1
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	36.10	
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	36,10	
10	REAR BUMPER CLIPS	NECESSARY	28.00	28.00
1	BOOTLID EMBLEM LOGO	NOT NECESSARY	74.40	8
1	BOOTLID EMBLEM SKYACTIV	NOT NECESSARY	63.60	18
1	BOOTLID EMBLEM MAZDA 3	NOT NECESSARY	53.40	
	LESS 20% DISCOUNT		-299.72	-220.56
			1,198.88	882.24
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	SERVICEABLE	280.00	8
			280.00	
	LABOUR			
	TO PANEL BEAT, REPAIR REAR END PANEL, BOOTLID AND TO REPLACE DAMAGED PARTS.		720.00	240.00
	TO INSTALL REVERSE SENSOR.		120.00	80.0
	TO APPLY RUST PROOFING ON REPAIR AND REPLACE PANELS.	NOT NECESSARY	200.00	
	TO PUTTY AND SPRAY PAINT REAR BUMPER, REAR BUMPER LOWER GARNISH, BOOTLID, REAR END PANEL AND ALL AFFECTED AREAS.		1,250.00	250.0
			2,290.00	570.0
	GRAND TOTAL		3,768.88	1,452.2
				1,452.2

Report Ref No. CS/FCI18014963/Kqd3e2





Report Ref No. CS/FCI18014963/Kqd3e2

KSC

KONG SENG CHEONG

Licensed Appraiser