

Your Ref: TP/IP/58303/2018  
Our Ref :CI/TPD18022204/Z

26<sup>th</sup> February 2019

**Fatal Accident Investigation Team**

Traffic Police Department  
Singapore Police Force  
10 Ubi Avenue 3  
Singapore 408865

**MECHANICAL INSPECTION REPORT OF MOTORCYCLE FW 8717X**

1. We refer to your request dated 28<sup>th</sup> November 2018 to conduct a physical inspection of a motorcycle bearing registration number FW 8717X (herein referred to as "**Motorcycle**"), which was involved in a fatal road traffic accident on 12<sup>th</sup> October 2018.
2. The purpose of this inspection is to primarily determine if there was any possible mechanical failure to the Motorcycle that may have contributed to the accident.
3. Following the request, we had carried out a physical inspection of the Motorcycle on 21<sup>st</sup> December 2018 at the premises of Traffic Police vehicle pound, 517 Airport Road Singapore 539942. We now set out below our observations and comments with respect to this inspection.

**General Condition**

4. The mileage of the Motorcycle was not recorded due to the damages sustained to the ignition system as a result of the accident.
5. The Motorcycle was observed to have sustained minor damages at the frontal, left and right portion. The body parts that were found to have been damaged include its front right wing mirror, rear bracket, dislodged seat, middle bucket compartment and left mudguard amongst others as a result of the accident.
6. This was likely due to the consistency of the accident's case facts that the Motor Cycle rider was travelling along Ubi Avenue 3 towards Kaki Bukit where at the signalised junction of Eunus Link, he was being hit by a Motor Car (SGK 2283X) coming from his left side. See photo 1 to 7 below.



**Photo 1** shows a close-up view of the mileage meter at time of our inspection. It was unable to be operated likely due to the accident's impact which affects the ignition system.



**Photo 2** shows a general view of the front body of the Motorcycle at the time of our inspection. The Motorcycle was observed to have sustained relatively minor damages at time of inspection. The damages were observed to be confined to its frontal, left & right side of the Motor Cycle.





**Photo 3** shows a general view of the right body of the Motorcycle at the time of our inspection. The Motorcycle was observed to have sustained relatively minor damages on the right side of the Motor Cycle at time of our inspection.



**Photo 4** shows a general view of the rear body of the Motorcycle at the time of our inspection. The Motorcycle was observed to have sustained relatively minor damage on the rear compartment bracket at time of our inspection.



**Photo 5** shows a general view of the left body of the Motorcycle at the time of our inspection. The Motorcycle was observed to have sustained relatively minor damages on the left side of the Motor Cycle at time of our inspection.



**Photo 6** shows a closer view of the front right portion of the Motorcycle at the time of our inspection. The Motorcycle was observed to have sustained with relatively minor damages due to the accident collision. (Circled)






**Photo 7** shows a closer view of the middle bucket compartment of the Motorcycle at the time of our inspection. The Motorcycle was observed to have sustained with relatively minor damages due to the accident collision. (Circled)

## Tyres and Wheel Rims

7. The condition of the Motorcycle's 2 tyres was observed to be in serviceable condition. The tread pattern of the 2 tyres was clearly visible. We did not observe any tear, burst mark(s) and/or punctured hole(s) on the sidewalls as well as across the tread of the 2 tyres. The 2 tyres were both observed to be sufficiently inflated for vehicular operation. The tyre brand, tyre size and remaining tread depth of the 2 tyres were recorded as follows:-



Dunlop TT900  
80/80 - R17 (4mm)

Dunlop TT900  
80/90 - R17 (4mm)

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

8. The rear tyre was wrapped around alloy wheel rims that were found to be without any significant damage. See photo 8 & 9 below



**Photo 8** shows the rear tyre of the Motorcycle. The rear tyre was observed to be in serviceable condition with remaining tread depth of approximately 4mm. The tyre was also observed to be sufficiently inflated for vehicular operation.



**Photo 9** shows the front tyre of the Motorcycle. The front tyre was observed to be in serviceable condition with remaining tread depth of approximately 4mm. The tyre was also observed to be sufficiently inflated for vehicular operation.

## Engine & Drive Train

9. Upon examination of the Motorcycle's engine area, we had observed that the various engine related parts and components were intact with no visible damage. There was also no sign(s) or indication(s) of fluid leak observed around the engine area of the Motorcycle.
10. The gear chain of the motorcycle was found to be intact without any misalignment. It was also adequately lubricated for operating purposes. Free play tension test was also conducted & found adequately acceptable. See photo 10 – 12 below.



**Photo 10** shows no sign(s) or indication(s) of fluid leak observed around the underside of the engine area of the Motorcycle.





**Photo 11** shows no sign(s) or indication(s) of fluid leakage stain observed around the engine area of the Motorcycle.



**Photo 12** shows the general view of the gear train (arrowed) of the Motorcycle, which was observed to be intact with no misalignment. It was also adequately lubricated for operating purposes.



## **Steering System & Braking System**

11. Our checks on the various steering components of the Motorcycle had revealed that its steering system was in serviceable condition. Its front fork was found to be intact and undamaged not affected by the accident's impact.
12. The brake system of the Motorcycle was of a semi-hydraulic type, where hydraulic (brake fluid) pressure controls the brake for the front wheel while the brake for the rear wheel is controlled by mechanical means (cables and springs). The brake for the front wheel is engaged by pulling the brake lever at the right side of the Motorcycle's handle bar while the brake for the rear wheel is engaged by stepping on the brake pedal at the right side foot rest of the Motorcycle.
13. Static brake tests conducted on the Motorcycle front & rear brakes had appeared to indicate that the braking system of the Motorcycle was in serviceable condition. The Motorcycle's braking system like the brake discs, brake callipers, brake lever, brake foot pedal and brake hoses revealed all to be intact and without damage. There was some resistance felt (spongy like feel) upon pressing the brake lever. This would indicate that there was no leakage of pressure/vacuum in the brake system. Our checks on the brake fluid had also indicated that the brake fluid was of sufficient level for operational purposes, and without contamination.


## **Operational Test**

14. For this case, we were not able to carry out any operational tests to the steering system and braking system of the Motorcycle due to the damages sustained that effects the Motorcycle's ignition system, which had rendered the Motorcycle immobility for the operational tests. However, we were able to push the motorcycle manually forward and backward, simulating movement of the Motorcycle, for the operational tests. Both brakes were engaged simultaneously while conducting the manual movements and it was observed to be in serviceable condition.

In general, the observations gathered during the static brake test & manual movement test had indicated that the steering system & braking system of the Motorcycle was in serviceable condition. See photo 13 - 17 below.



**Photo 13** shows our checks on the brake fluid (front) reservoir had also indicated that the brake fluid was of sufficient level for operational purposes, and without contamination.



**Photo 14** shows our checks on the rear brake components had also indicated that the rear braking system was in serviceable condition at time of our inspection.





**Photo 15** shows testing of the braking of the front brake in progress. There was some resistance felt (spongy like feel) upon pressing the brake lever.



**Photo 16** shows testing of the braking of the rear brake in progress. There was some resistance felt (spongy like feel) upon stepping on the brake pedal.



**Photo 17** shows the front brake pad at time of our inspection. The frictional material was observed to be sufficient for operational purposes.

## Conclusion

15. Basing on our physical inspection of the Motorcycle, it appears that the steering system and braking system of the Motorcycle were all in serviceable condition. We did not find any evidence(s) to suggest that there was possible mechanical failure to the Motorcycle that may have caused and/or contributed to the accident.
16. The tyres of the Motorcycle were found to be in a serviceable condition. There was no tear, cut or burst mark(s) on the outer and the inner sidewalls as well as across the tread of the tyre. It was sufficiently inflated for vehicular operation with remaining tread depth of approximately 4mm each.



17. Our findings were based solely on a static test, visual inspection and manual test of the Motorcycle simulating its movement. No operational test(s) could be carried out to the Motorcycle due the damages sustained that affects the Motorcycle's ignition system, which had rendered the Motorcycle's immobility.

**Rohaizal A. Rahim**

*Technical Investigator*

**Ang Bryan Tani**

*AMSOE, AMIRTE, AFF SAE, M.MATAI, AFF.Inst.AEA*

*Senior Technical Investigator*

*Technical Investigation & Reconstructionist (SAE-A)*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.