

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19003334/EVD3E2

Date: 10/10/2019

REFERENCE

Insured/Claimant: PERFORMANCE MOTORS LTD
Date of Loss: 15/01/2019

Policy No: 27392999MTR
Nature of Claim: OD Claim No: 587593

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	4758S	Engine No:	HIDDEN
Make & Model:	BMW 216I, 1.5 (A)	Chassis No:	WBA2X92060VD11506
Reg. Date:	(Man. Year:)	Odometer:	0 km
Colour:	Brown		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,688.45	19,688.45	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,161.00	10,419.00	742.00	6.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,849.45	30,107.45	742.00	2.41
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
Nett Amount (S\$)	29,349.45	28,607.45	742.00	2.53

INSPECTION

Date of Assignment: 15/03/2019

Date Inspected: 22/02/2019 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Vehicle Value (Un-register):\$29,536.00

OMV : \$-

PARF Rebate (1) : \$-

Quota Premium Paid : \$-

COE Rebate (2) : \$-

Total Rebate (1) + (2) = : \$-

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2019)
Parts:	M1-MPV	BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for 4758S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*BASIC CONTROL UNIT DME 83T1 (CODED)	Short Circuit	2,769.75 FS	*2,769.75 FS
3	1		*EXCH STEERING BOX ELECTR.	Short Circuit	3,811.95 FS	*3,811.95 FS
4	1		*REPAIR KIT CONTROL UNIT DSC	Short Circuit	1,912.00 FS	*1,912.00 FS
5	1		*BOOT LID / TAILGATE PUSH BOTTON ICAM	Short Circuit	48.40 FS	*48.40 FS
6	1		*(DG/SL) BMW AGM BATTERY (70 AH)	Short Circuit	581.95 FS	*581.95 FS
7	1		*SHIFTBOX GEAR SELECTOR SWITCH	Short Circuit	1,146.60 FS	*1,146.60 FS
8	1		*BODY DOMAIN CONTROLLER BDC (CODED)	Short Circuit	1,348.80 FS	*1,348.80 FS
9	1		*SEAT MODULE	Short Circuit	501.00 FS	*501.00 FS
10	1		*CONTROL UNIT TAILGATE FUNCTION MODU	Short Circuit	494.60 FS	*494.60 FS
11	2		*CONTROL UNIT FRT LIGHT ELECTRONICS	Short Circuit	1,787.80 FS	*1,787.80 FS
12	1		*CONTROL UNIT AIRBAG	Short Circuit	1,024.75 FS	*1,024.75 FS
13	1		*CONTROL UNIT PARKING ASSISTANT	Short Circuit	526.10 FS	*526.10 FS
14	1		*CONTROL UNIT CAM BASED DRIVER SUPP	Short Circuit	920.60 FS	*920.60 FS
15	1		*REVERSING CAMERA (VALEO)	Short Circuit	684.20 FS	*684.20 FS
16	1		*CONTROL UNIT DUAL CLUTCH TRANSMISSI	Short Circuit	1,979.95 FS	*1,979.95 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **19,688.45** **19,688.45**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR ROOF PANEL	New	1,275.00	1,200.00
2	PAINTING ROOF PANEL	New	1,298.00	1,233.00
3	TO REPLACE ALL CONTROL UNITS	New	5,100.00	4,675.00
4	TO REPLACE ELECTROMECHANICAL POWER STEERING INCLUDING PROGRAM, INITIALIZE STEERING COLUMN ADJUSTMENT AND CONDUCT CHECKS FOR PROPER FUNCTION	New	885.00	850.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (1X)	New	531.00	504.00
6	TO REMOVE AND INSTALL FRONT DASHBOARD PANEL TO FACILITATE REPAIRS	New	797.00	757.00
7	DIAGNOSS AND PROGRAMMING THE CONTROL UNITS	New	1,275.00	1,200.00
Gross Labour Cost (S\$)			11,161.00	10,419.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >