

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19003346/R1GA3Q2

Date: 03/09/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00015390

Claimant
Vehicle No : PC6199R **Insured Vehicle No :** SLT4533E

Date of Loss: 08/01/2019 Nature of Claim: TP Claim No: 1201900001535

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC6199R		
Make & Model:	MITSUBISHI AIRTREK, 2.0 TURBO (A)	Engine No:	4P10C58030
Reg. Date:	18/09/2017 (Man. Year: 2017)	Chassis No:	BE641JK30357
Colour:	Multi-colour	Odometer:	87208 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	7.00 R16LT	Rear Tyre Size:	7.00 R16LT (A)
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7/7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,473.08	405.00	2,068.08	83.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,110.00	830.00	280.00	25.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,583.08	1,235.00	2,348.08	65.53
+ GST 7.00/7.00% (S\$)	250.82	86.45	164.37	65.53
Nett Amount (S\$)	3,833.90	1,321.45	2,512.45	65.53
+ Loss of Use (6.0 x S\$150.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,228.45		

INSPECTION

Date of Assignment: 22/02/2019

Date Inspected: 22/02/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2020)
Parts:	M1-SUV	mitsubishi Airtrek 2.0 Turbo (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC6199R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,588.97 F	*- FL
2	1		*FRONT BUMPER ADVERTISEMENT STICKER	Necessary	450.00 F	*450.00 FL
3	1		*FRONT BUMPER SIDE BRACKET LH	Not Necessary	113.60 F	*- FL
4	1		*FRONT SIDE LAMP LH	Not Necessary	205.16 F	*- FL
5	1		*FRONT SIDE DOOR SIGNAL LAMP LH	Not Necessary	115.35 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,473.08	450.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	45.00
Total Parts (\$\$)	2,473.08	405.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS,REPLACE AND REALIGN HYDRAULIC AND ALIGNED ALL PARTS	New	500.00	300.00
2	TO RESPRAY AFFECTED AREAS	New	400.00	400.00
3	TO REMOVE/REFIT WIRING CHECK	New	60.00	30.00
4	TO REMOVE/REPLACE ADVERTISEMENT STICKER	New	150.00	100.00
Gross Labour Cost (\$\$)			1,110.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >