

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19013193/KBA3Q2

Date: 13/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800041531

Claimant
Vehicle No : SLJ9029P **Insured Vehicle No :** SLZ856T

Date of Loss: 24/07/2019 Nature of Claim: TP Claim No: 2856414594SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ9029P		
Make & Model:	MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A)	Engine No:	P520416206
Reg. Date:	29/12/2016 (Man. Year: 2016)	Chassis No:	JM6BN22A8H0131524
Colour:	Metallic Grey	Odometer:	172593 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	AGENDA 9 mm	Rear Left Side:	AGENDA 9 mm
Front Right Side:	AGENDA 9 mm	Rear Right Side:	AGENDA 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,395.20	2,681.36	1,713.84	38.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	1,185.00	305.00	20.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,885.20	3,866.36	2,018.84	34.30
Approved Total (Overridden) (S\$)		3,050.00		
Nett Amount (S\$)	5,885.20	3,050.00	2,835.20	48.18
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,412.00		
Global Sum Settlement (S\$)		3,300.00		

INSPECTION

Date of Assignment: 25/07/2019

Date Inspected: 26/07/2019 Inspected At:

Supreme Auto Service Pte Ltd (HQ)
176 Sin Ming Drive #02-01, Sin Ming
Autocare
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	1,018.30 FL	*1,018.30 FL
2	1		*REAR BOOT EMBLEM LOGO	Necessary	82.60 FL	*82.60 FL
3	1		*REAR BOOT EMBLEM MAZDA	Necessary	63.80 FL	*63.80 FL
4	1		*REAR BOOT EMBLEM SKYACTIVE TECHMOLOGY	Necessary	75.60 FL	*75.60 FL
5	1		*REAR BOOT LOCK	Repair	291.30 FL	*- FL
6	1		*REAR BOOT WEATHERSTRIP	Serviceable	326.80 FL	*- FL
7	2		*REAR BOOT LAMP	Serviceable	593.60 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Bent	583.60 FL	*556.10 FL
9	1		*REAR BUMPER	Buckled	1,178.60 FL	*1,102.30 FL
10	1		*END PANEL GARNISH	Mtg Distorted	328.60 FL	*203.00 FL
11	1		*END PANEL	Repair	369.20 FL	*- FL
12	1		*SET REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,132.00	3,301.70
- List Item Discount on L Items 15.00/20.00% (\$)	736.80	620.34
Total Parts (\$)	4,395.20	2,681.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	600.00	500.00
2	TO INSTALL REVERSE SENSOR	New	80.00	50.00
3	TO CHECK WIRING SYSTEM	New	50.00	15.00
4	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	600.00	540.00
5	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	80.00	20.00
6	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	80.00	60.00
Gross Labour Cost (\$)			1,490.00	1,185.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >