

ASS. REC. BY:

REF:

es/CTI19022870/Dy03n2

Special Instruction:

Survey: Ben Tan

## ASSIGNMENT (Office)

From (Person): Ben Tan

of

CTI

Date/Time:

27/12/19 @ 5:27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SHA 9414E

Insured:

SJP 9938H

at Workshop in/s

Chunni Motor

Tel:

6542519

of

10 Amk Ind. Park # 01-05/06

Policy No.:

Claim No.:

SNM19D206130/SJP9938H/BEN

Sum Insured:

Excess:

Make of Veh.:

D.O.A.

25/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:11am @ 30/12/19

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction

To/From

SHA 9414E - CS/CTI/7047015 / Avb02

D.O.A. 29/08/2017

SJP 9938H - CS/CTI/19022870 / Uv03

D.O.A. 25/12/2019

From: Bryan

REF:

# ASSIGNMENT

COE Jan 2025

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHA9414E

Regn: 2017 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make:

Hyundai 140

c.c: 1685

Colour:

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

319680

T/Radio: Insured / Std / NI / NA

Eng/No:

D4FDGU707080

C/No:

KMHLB4UMHU098312

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Good / Jammed / Leaked / Burnt or

Brake: ☒ Good / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

25/12/2019

D.O.I.

30/12/2019

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

China T-ping SSP9938H

03/02/2020 Jmann 2/5 8200/- in 7 days of rev (Red \$14364-84,63)

RECEIVED 24 FEB 2020

Date/Time, File Path: 147

☐

: Prel. Report

0

☐

: Final Report

Date/Time, File Path: 147

7

7/2/20 Typist

Report Format:

Yump Sum

UP: 8200/-

Days Of Repair:

7

Resurvey No. of Trip:

3

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wheel end (\$

Survey Fee:

Transportation:

5 + RS 24

Fuel:

Others:

TOTAL

220

## Nivitha (LKK Auto)

---

**From:** Ben Tang <Ben.Tang@sg.cntaiping.com>  
**Sent:** Friday, 27 December 2019 5:27 PM  
**To:** assignments@lkkauto.com  
**Subject:** FW: OUR REF: SNM19D206130/SJP9938H/BEN & YOUR REF: SHA9414E-PRS - Accident involving veh no: SHA 9414E & SJP 9938H on 25.12.19

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SHA9414E.

Thank you.

Best Regards  
Ben Tang  
Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #XX-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6175 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Chunni Motor <chunnimotor@gmail.com>  
**Sent:** Friday, December 27, 2019 4:59 PM  
**To:** Ben Tang <Ben.Tang@sg.cntaiping.com>  
**Cc:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Subject:** Re: OUR REF: SNM19D206130/SJP9938H/BEN & YOUR REF: SHA9414E-PRS -Accident involving veh no: SHA 9414E & SJP 9938H on 25.12.19

Dear Sir,

We appoint LKK.

Thank you

Regards,  
Chunni Motor Work P/L

On Fri, Dec 27, 2019 at 4:42 PM Ben Tang <[Ben.Tang@sg.cntaiping.com](mailto:Ben.Tang@sg.cntaiping.com)> wrote:

**WITHOUT PREJUDICE**

Dear Sir,

We refer to your email dated 27 December 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI

**Sent:** Friday, December 27, 2019 4:33 PM

**To:** Ben Tang <[Ben.Tang@sg.cntaiping.com](mailto:Ben.Tang@sg.cntaiping.com)>; [chunnimotor@gmail.com](mailto:chunnimotor@gmail.com)

**Subject:** OUR REF: SNM19D206130/SJP9938H/BEN & YOUR REF: SHA9414E-PRS -Accident involving veh no: SHA 9414E & SJP 9938H on 25.12.19

Dear Ben,

Please conduct PRS- SHA9414E soonest possible.

File with officer in charge –Ben Tang –DID: 6389 6175.

Dear Lynn/Irene,

*\*\*\* kindly quote our reference number when replying.*

Regards

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Website:[www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Chunni Motor [<mailto:chunnimotor@gmail.com>]  
**Sent:** Friday, December 27, 2019 10:11 AM  
**To:** Claims Dept of CTI  
**Subject:** Accident involving veh no: SHA 9414E & SJP 9938H on 25.12.19

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

**Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.**

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

MCD619185800 / ComfortDelGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 26/12/2019 15:39  
 SUBMITTED BY: Janet Lim Slang Gek

Your NCD will be affected due to late reporting  
 Actual e-Filing Submission Date & Time: 27/12/2019 08:51

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report 26/12/2019 15:39  
 Date Of Accident 25/12/2019 14:45  
 Exact Location Of Accident ANG MO KIO AVE 3 YIO CHU KANG RD  
 Country/State of Loss SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA9414E  
**Insured/Policyholder**  
 Name Of Registered Owner CITYCAB PTE LTD  
 Co Reg No 1XXXXX839G  
 Email Address FLEETSAFETY@CDGTAXI.COM.SG  
 Mobile Phone No  
 Alternative Phone No OFFICE-65508768

#### Vehicle Particulars

Manufacturer HYUNDAI  
 Model i40

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

#### Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD  
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy YES  
 Policy Number D-18088937MFSH

Cover Note Number

#### Driver

Name of Driver TAY HOCK TECK  
 NRIC No SXXXX907E  
 Date Of Birth 13/06/1953  
 Occupation OUTDOOR  
 Date Of Driving Pass 29/08/1973  
 Driving Experience 46 YEARS AND 3 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-98731353  
 Fax Number  
 Contact Number  
 Email Address NOEMAIL

Address BLK 332 SEMBAWANG CLOSE  
#08-407

Postcode 750332

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-

#### General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 3

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 4

Passenger 1  
NAME: : -  
GENDER: : MALE

Passenger 2  
NAME: : -  
GENDER: : FEMALE

Passenger 3  
NAME: : -  
GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] SERANGOON NORTH NPP

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER POLICE REPORT NO: T/20191225/2081

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJP9938H

Vehicle Make/Model/Colour TOYOTA

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver UNKNOWN



NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage FRONT

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SJW5115E

Vehicle Make/Model/Colour MERCEDES

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage RH REAR

No. Of Passenger (Including Driver)



**SKETCH PLAN**

A-SHA 9414E  
B-SJP 9938H  
C-SJW 5115E

Along Ang Mo Kio Ave 3 x Yio Chu Kang Rd

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

As Attached Police Report:T/20191225/2081

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD  
CO. REG. NO. 199502839G

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 26.12.2019@ 13:40hrs

Lisa  
Reporting Centre Personnel's Signature  
Name:-  
NRIC/FIN No.: -



# SINGAPORE POLICE FORCE



T/20191225/2081

1 of 3

Report No. T/20191225/2081

Police Station Of Origin:  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No: 1800-2849999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/12/2019 18:13		Vide Report No.: F/20191225/0167		Station Diary No.: 22	
<b>Informant Details</b>					
Name of Informant: TAY HOCK TECK			Address: APT BLK 332 SEMBAWANG CLOSE #08-407 SINGAPORE 750332		
ID Type / ID No.: NRIC NO / S0011907E			Contact No.: Home/Office: Mobile: 98731353		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 66	Date of Birth: 13/06/1953	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi Driver			Driving Licence Information: Class: 3 Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 25/12/2019 14:45	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 YIO CHU KANG ROAD ANG MO KIO AVENUE 3 Junction of Yio Chu Kang Rd, Ang Mo kio Ave 3 and Hougang Ave 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 60 Km/h
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

<b>Details of Vehicles Involved</b>						
Vehicle No.	Type	Make	Model	Color	Damage	Count
SHA9414E	Taxi				Seriously Damaged	3
SJP9938H	Car				Seriously Damaged	0
SJW5115E	Car				Seriously Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20191225/2081

Police Station Of Origin:  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No: 1800-2849999

2 of 3

Report No. T/20191225/2081

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	TAY HOCK TECK	ID No.	S0011907E
Related Vehicle	SHA9414E (Taxi)	Contact No.	98731353
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 25/12/2019 @1445hrs, I was driving my taxi (SHA9414E) along Ang Mo Kio Ave 3 towards Hougang Ave 2 with 3 passengers inside my vehicle and I was travelling on the extreme left lane. When I reached the junction of Ang Mo Kio Ave 3 and Yio Chu Kang Road, I stopped my vehicle as the traffic light was 'red' and there was another car (SJW5515E) on my right. As the traffic light turned 'green' I began to move my car forward and before I could make a right turn into Yio Chu Kang Road towards Serangoon, a m/car (SJP9938H) which was travelling along Yio Chu Kang Road towards Upper Thomson collided onto the other car (SJW5115E) which was beside mine and due to the impact which was so great, it caused the car (SJW5115E) to swirl and the said car (SJP9938H) then hit onto my vehicle. I could see that 2 of the passengers from the other 2 cars were injured but I could not actually tell from which vehicle they were from or how serious their injuries were. ~~The 2 injured passengers were conveyed to hospital by ambulance.~~ Traffic Police personnel were also at the accident scene attending to the case (F/20191225/0167). My vehicle was badly damaged in the accident and had to be towed away. I and my passengers were not injured in the accident.

**SINGAPORE  
POLICE FORCE**

T/20191225/2081

Police Station Of Origin:  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No: 1800-2849999

3 of 3

Report No. T/20191225/2081

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

SI ABDUL RASHID BIN ABDULLAH

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

25/12/2019 18:13

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt NORAMEERA BINTE MOHAMED  
HUSSEIN

Classification Of Case:

Contact No.: 65476238

SN 151

Authentication Stamp  
NP168

Signature

Singapore Police Force

**CHUNNI MOTOR WORK PTE LTD**

### REPAIR ESTIMATE\*

VEHICLE NO : SHA 9414E

DATE : 26.12.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40



**FAX : 6542 6039**

Chen Zhiping

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (RH) <i>bnc</i>			\$ 566.30 ✓
	Front Fender Shield (RH) <i>deformed</i>			\$ 174.90 ✓
	Front Door (RH) <i>Bnc</i>			\$ 2,256.40 ✓
	Front Door Rubber <i>SVC</i>			\$ 290.50 X
	Front Door Gear / Regulator (RH) <i>NH</i>			\$ 250.60 X
	Front Door Hinge Upper (RH) <i>NH</i>			\$ 36.10 X
	Front Door Hinge Lower (RH) <i>NH B-1</i>			\$ 36.10 ✓
	Front Door Check (RH) <i>NH</i>			\$ 39.20 X
	Front Door Inner Lock (RH) <i>NH</i>			\$ 290.80 X
	Front Door Outer Handle (RH) <i>NH</i>			\$ 36.30 X
	Front Door Outer Moulding (RH) <i>NH</i>			\$ 47.10 X
	Front Door Power Motor, RH <i>NH</i>			\$ 296.40 X
	Front Door Trim Board (RH) <i>NH</i>			\$ 973.50 X
	Door Centre Pillar Outer (RH) <i>Dented</i>			\$ 2,527.80 ✓
	Rocker Panel Outer Garnish <i>1st &amp; mainly cracked</i>			\$ 341.40 ✓
	Front Windscreen Moulding <i>NH</i>			\$ 113.30 <i>wm X</i>
	Front Windscreen Pillar Outer (RH) <i>Dented</i>			\$ 1,745.50 ✓
	Front Wheel Rim (RH) <i>distorted</i>			\$ 325.30 ✓
	Front Wheel Hub Cap (RH) <i>Cut / distorted</i>			\$ 107.10 ✓
	Front Wheel Bearing <i>Distorted</i>			\$ 540.50 ✓
	Front Shock Absorber (Assy) (RH) <i>distorted</i>			\$ 342.20 ✓
	Front Shock Absorber Mounting (RH) <i>NH</i>			\$ 108.80 X
	Front Drive Shaft (RH) <i>NH</i>			\$ 1,030.80 X
	Rack & Pinion Assy <i>NH</i>			\$ 969.60 X
	STG Tie End <i>NH</i>			\$ 62.60 ✓ X
	Front Suspension Lower Arm (RH) <i>distorted</i>			\$ 529.30 ✓
	Knuckle Arm (RH) <i>distorted</i>			\$ 552.00 ✓
	Engine Crossmember <i>NH</i>			\$ 2,094.40 X
	ABS Sensor <i>NH</i>			\$ 234.00 X
	Electric Power Steering <i>NH</i>			\$ 3,641.00 X
	<b>SUB TOTAL</b>			\$ 20,559.80
	<b>LESS 20%</b>			\$ 4,111.96
	<b>DISCOUNTED TOTAL</b>			\$ 16,447.84
	Front Fender Advertisement Logo (RH) <i>NH</i>			\$ 100.00 Nett ✓
	Front Door Comfort Logo (RH) <i>NH</i>			\$ 75.00 Nett ✓
	Front Door Advertisement Logo (RH) <i>NH</i>			\$ 100.00 Nett ✓
	Front Windscreen Sealant <i>Ligne NH</i>			\$ 46.00 Nett <i>X</i>
	Front Tyre (RH) <i>SVC</i>			\$ 216.00 Nett X
				\$ 537.00



SHA 9414E

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	<b>Labour Charge</b>			
	Panel Beating			\$ 2,000.00
	Spray Painting Charge			\$ 1,250.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Towing Charge			\$ 50.00
	Transfer of Door			\$ 120.00
	Remove/Refix Undercarriage (FRT)			\$ 200.00
	FRT Wheel Alignment			\$ 120.00
	Remove/Refix Aircon & Refill Gas		1960.00	\$ 150.00
	Remove/Refix Dashboard			\$ 450.00
	Remove/Refix Front Windscreen Glass			\$ 120.00
	Remove/Refix Cushion & Upholstery Front			\$ 90.00
	Re-set Frt ABS System			\$ 200.00
	Re-set Frt Power Window System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	<b>TOTAL LABOUR</b>			<b>\$ 5,580.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 22,564.84</b>
	30/12/2019 @ 1230hrs Not Authored 2/3 hrs 7 days  LKK Auto 		10270.84 L/S 8200/-	
	<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p> </div>			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			



NAME  
ADDRESS

Home Tel.:

VIN:

Registration: SHA 9414 E

Technician:

Mileage: 319679

Time Printed 27.12.19 11:00 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°35'		-3°00' 3°00'
3°31'		-0°19' 5°41'
-0°09'		-1°30' 1°30'
14°19'		
13°44'		

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-1°10'		-3°00' 3°00'
3°42'		-0°19' 5°41'
-4°35'		-1°30' 1°30'
14°35'		
13°25'		

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°35'		-3°00' 3°00'
-0°12'		-3°00' 3°00'
-0°16'		-3°00' 3°00'
-4°44'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-0°23'		-3°30' 2°30'
0°44'		-1°30' 1°30'

Camber  
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°10'		-3°30' 2°30'
0°04'		-1°30' 1°30'

Rear

Cross Camber  
Total Toe  
Thrust Angle

Actual	BEFORE	Specified Range
-0°12'		-3°00' 3°00'
0°48'		-3°00' 3°00'
0°20'		-3°00' 3°00'

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022870/DYD3N2  
Date: 27/02/2020

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN1619871903  
Claimant Vehicle No: SHA9414E Insured Vehicle No: SJP9938H  
Date of Loss: 25/12/2019 Nature of Claim: TP Claim No: SNM19D206130/SJP9938H/BEN

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHA9414E  
Make & Model: HYUNDAI I40, 2.0 (A) Engine No: D4FDGU707080  
Reg. Date: 11/01/2017 (Man. Year: 2016) Chassis No: KMHLB41UMHU098312  
Colour: Yellow Odometer: 319680 km  
Engine Capacity: 1685 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16  
Front Left Side: Hankook 5 mm Rear Left Side: Hankook 5 mm  
Front Right Side: Hankook 5 mm Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,984.84	8,310.84	8,674.00	51.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,580.00	1,960.00	3,620.00	64.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,564.84</b>	<b>10,270.84</b>	<b>12,294.00</b>	<b>54.48</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,200.00</b>		
<b>(S\$)</b>	22,564.84	8,200.00	14,364.84	63.66
<b>+ GST 7.00/7.00% (S\$)</b>	1,579.54	574.00	1,005.54	63.66
<b>Nett Amount (S\$)</b>	<b>24,144.38</b>	<b>8,774.00</b>	<b>15,370.38</b>	<b>63.66</b>

## INSPECTION

Date of Assignment: 21/02/2020  
Date Inspected: 30/12/2019 Inspected At: Chunni Motor Work Pte Ltd (HQ)  
Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK  
Autopoint  
Singapore 568047  
Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2020)
<b>Parts:</b>	143	HYUNDAI I40 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA9414E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER (RH)	Buckled	566.30 FL	*566.30 FL
2	1		*FRONT FENDER SHIELD (RH)	Deformed	174.90 FL	*174.90 FL
3	1		*FRONT DOOR (RH)	Buckled	2,256.40 FL	*2,256.40 FL
4	1		*FRONT DOOR RUBBER	Serviceable	290.50 FL	*- FL
5	1		*FRONT DOOR GEAR/REGULATOR (RH)	Not Necessary	250.60 FL	*- FL
6	1		*FRONT DOOR HINGE UPPER (RH)	Not Necessary	36.10 FL	*- FL
7	1		*FRONT DOOR HINGE LOWER (RH)	Bent	36.10 FL	*36.10 FL
8	1		*FRONT DOOR CHECK (RH)	Not Necessary	39.20 FL	*- FL
9	1		*FRONT DOOR INNER LOCK (RH)	Not Necessary	290.80 FL	*- FL
10	1		*FRONT DOOR OUTER HANDLE (RH)	Not Necessary	36.30 FL	*- FL
11	1		*FRONT DOOR OUTER MOULDING (RH)	Not Necessary	47.10 FL	*- FL
12	1		*FRONT DOOR POWER MOTOR,RH	Not Necessary	296.40 FL	*- FL
13	1		*FRONT DOOR TRIM BOARD (RH)	Not Necessary	973.50 FL	*- FL
14	1		*DOOR CENTRE PILLAR OUTER (RH)	Dented	2,527.80 FL	*2,527.80 FL
15	1		*ROCKER PANEL OUTER GARNISH	Bent/Mounting Cracked	341.40 FL	*341.40 FL
16	1		*FRONT WINDSCREEN MOULDING	Not Necessary	113.30 FL	*- FL
17	1		*FRONT WINDSCREEN PILLAR OUTER (RH)	Dented	1,745.50 FL	*1,745.50 FL
18	1		*FRONT WHEEL RIM (RH)	Distorted	325.30 FL	*325.30 FL
19	1		*FRONT WHEEL HUB CAP (RH)	Cut/Distorted	107.10 FL	*107.10 FL
20	1		*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
21	1		*FRONT SHOCK ABSORBER (ASSY)(RH)	Distorted	342.20 FL	*342.20 FL
22	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	108.80 FL	*- FL
23	1		*FRONT DRIVE SHAFT (RH)	Not Necessary	1,030.80 FL	*- FL
24	1		*RACK & PINION ASSY	Not Necessary	969.60 FL	*- FL
25	1		*STG TIE END	Not Necessary	62.60 FL	*- FL
26	1		*FRONT SUSPENSION LOWER ARM (RH)	Distorted	529.30 FL	*529.30 FL
27	1		*KNUCKLE ARM (RH)	Distorted	552.00 FL	*552.00 FL
28	1		*ENGINE CROSSMEMBER	Not Necessary	2,094.40 FL	*- FL
29	1		*ABS SENSOR	Not Necessary	234.00 FL	*- FL
30	1		*ELECTRIC POWER STEERING	Not Necessary	3,641.00 FL	*- FL
31	1		*FRONT FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
32	1		*FRONT DOOR COMFORT LOGO (RH)	Necessary	75.00 FS	*75.00 FS
33	1		*FRONT DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
34	1		*FRONT WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS
35	1		*FRONT TYRE (RH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>21,096.80</b>	<b>10,319.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>4,111.96</b>	<b>2,008.96</b>
<b>Total Parts (S\$)</b>	<b>16,984.84</b>	<b>8,310.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,000.00	700.00
2	SPRAY PAINTING CHARGE	New	1,250.00	800.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	TRANSFER OF DOOR	New	120.00	60.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
8	FRT WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
10	REMOVE/REFIX DASHBOARD	New	450.00	0.00
11	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	0.00
12	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	0.00
13	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	150.00
14	RE-SET FRT ABS SYSTEM }	New	200.00	0.00
15	RE-SET FRT POWER WINDOW SYSTEM }	New	200.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,580.00</b>	<b>1,960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >