

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20001360/ACF3E2

Date: 28/01/2021

REFERENCE

Insured/Claimant:	FREDERICK BENJAMIN KOH	Policy No:	1800154340	
Date of Loss:	17/01/2020	Nature of Claim:	OD	Claim No: 4598330648SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG5453C		
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Engine No:	CHZB22414
Reg. Date:	24/12/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V2K1008001
Colour:	Blue	Odometer:	19975 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$95,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,442.00	1,689.84	1,752.16	50.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,322.00	1,522.00	2,800.00	64.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,764.00	3,211.84	4,552.16	58.63
+ GST 7.00/7.00% (S\$)	543.48	224.83	318.65	58.63
Nett Amount (S\$)	8,307.48	3,436.67	4,870.81	58.63

INSPECTION

Date of Assignment:	22/01/2020		
Date Inspected:	22/01/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,851.00 FS	*1,480.80 FS
2	4		*REAR BUMPER STICKY PAD	Not Necessary	22.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	182.00 FS	*- FS
4	2		*WHEEL HOUSING LINER ADAPTER - LH / RH	Not Necessary	72.00 FS	*- FS
5	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	30.00 FS	*- FS
6	2		*REAR BUMPER LOCKING MECHANISM	Not Necessary	55.00 FS	*- FS
7	1		*REAR BUMPER SPOILER - LH	Cut	223.00 FS	*178.40 FS
8	2		*REAR LIGHT REFLECTOR - LH / RH	Not Necessary	78.00 FS	*30.64 FS
9	1		*REAR BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	538.00 FS	*- FS
10	1		*REAR BUMPER BRACKET - LH	Not Necessary	26.00 FS	*- FS
11	1		*REAR BUMPER BRACKET - RH	Not Necessary	27.00 FS	*- FS
12	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	124.00 FS	*- FS
13	2		*REAR PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
14	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
15	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					3,442.00	1,689.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER AND LOWER SPOILER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER, RHS REAR FENDER AND LHS REAR FENDER	New	2,800.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,322.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >