Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20001362/ADA3Q2

Date: 14/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700063346

Claimant

SFF380A

Insured Vehicle No: SLT256G

Vehicle No: SEF380A Insured vehicle No: SEF280G

Date of Loss: 18/01/2020 Nature of Claim: TP Claim No: 1679314127SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFF380A

 Make & Model:
 BMW 216I, 1.5 D GT LED (A)
 Engine No:
 39205059B38A15A

 Reg. Date:
 16/11/2017 (Man. Year: 2017)
 Chassis No:
 WBA2D920905E91427

Colour: White Odometer: 16895 km

Engine Capacity: 1499 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,405.36	1,249.50	2,155.86	63.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,240.00	490.00	750.00	60.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,645.36	1,739.50	2,905.86	62.55
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	4,645.36	1,400.00	3,245.36	69.86
+ GST 7.00/7.00% (S\$)	325.18	98.00	227.18	69.86
Nett Amount (S\$)	4,970.54	1,498.00	3,472.54	69.86
+ Loss of Use (3.0 x S\$6	180.00			
+ Doc/Se	7.45			
Nett Liability (S\$)		1,685.45		
Global Sum S	1,680.00			

INSPECTION

Date of Assignment: 21/01/2020

Date Inspected: 21/01/2020 Inspected At: MG Solution Pte Ltd (HQ)

23 Kaki Bukit Avenue 4 #02-03B,

VICOM Inspection Centre Singapore 415933

Estimated Period of Repair: 2.0 days

Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,599.20 FL	*1,180.00 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Cracked	190.00 FL	*67.00 FL
3	1		*REAR BUMPER BEAM	Not Necessary	280.00 FL	*-FL
4	1		*REAR BUMPER REFLECTOR RH	Cracked	180.00 FL	*65.00 FL
5	1		*REAR BUMPER TOWING COVER	Cut	113.00 FL	*43.00 FL
6	1		*REVERSE SENSOR	Not Necessary	388.20 FL	*- FL
7	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	3,780.40	1,385.00
- List Item Discount on L Items 10.00/10.00% (S\$)				375.04	135.50	
				Total Parts (S\$)	3,405.36	1,249.50
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	400.00	200.00
2	SPRAY PAINTING TO AFFECTED AREA	New	400.00	200.00
3	TUFF COAT	New	80.00	0.00
4	WIRING CHECK	New	60.00	30.00
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
6	REMOVE AND REFIX REAR SENSOR AND DISTANCE SETTING	New	120.00	60.00
	Gross Labour Cost (S\$)		1,240.00	490.00
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >