

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 67414108

Operational Behaviour of the Motor Car

15. Operational test by driving the Motor Car to primarily determine whether there was any abnormality to the engine system, transmission system and braking system of the Motor Car could not be conducted given the extent of damage that it had sustained had render it unsafe for operation. (Undercarriage component as the rear axle was damaged).

Conclusion

- 16. Although an operational test by driving the Motor Car was not able to be conducted, my static and visual inspection of the Motor Car appears that its engine system, transmission system, steering system and braking system were all in serviceable condition at the material time of accident.
- 17. The 4 tyres of the Motor Car were also found to be in serviceable condition. I did not find any tear, cut or burst mark(s) on the outer and the inner sidewalls as well as across the tread of the 4 tyres. The 4 tyres were also observed to be sufficiently inflated for vehicular operation with remaining tread depth of approximately 5.6mm to 6.1mm.

Sherwin Beh

Technical Investigator

Ang Bryan Tani

AMSOE, AMIRTE, AFF SAE, M.MATAI, AFF.Inst.AEA

Senior Technical Investigator

Technical Investigation & Reconstructionist (SAE-A)

DISCLAIMER OF LIABILITY TO THIRD PARTIES: - This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part does so at his or her own risk.