

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|--------------------------|------------------------------|------|------------|--|
| AXA INSURANCE PTE LTD | | | Ref : CC4/ASM20002036/Upa3q2 | | | |
| 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG | | | Date: 29-09-2 | 2020 | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| Insured V | /eh. | SKK 3693S | Veh. Inspecte | d | SMQ 6926X | |
| Policy No |). | VPA/P1398851 | Coverage (\$) | | 0.00 | |
| Claim No. | | S0M02F8X | Excess (\$) | | 0.00 | |
| Assign Fı | rom | | Assign Date | | 05/02/2020 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| Make & M | lodel | TOYOTA COROLLA ALTIS (A) | c.c | | 1598 | |
| Engine N | 0. | HIDDEN | Year of Reg. | | 2011 | |
| Chassis N | No. | MR053REE104103177 | Colour | | SILVER | |
| Odomete | r | 74623 | Steering | | IN ORDER | |
| Brakes | | IN ORDER | Modification | | SPORTS RIM | |
| General | | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| R/H Front | | 195/65 R15 | YOKOHAMA | | 6 mm | |
| L/H Front | | 195/65 R15 | YOKOHAMA | | 6 mm | |
| R/H Rear | | 195/65 R15 | YOKOHAMA | | 6 mm | |
| L/H Rear | Tyre | 195/65 R15 | YOKOHAMA | | 6 mm | |
| 4. Description of Damages | | | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. | | | | | | |
| DAMAGES SEE DETAILS. 5. General Information | | | | | | |
| Accident | Date | 03/02/2020 | Inspection Da | nto. | 05/02/2020 | |
| | rvey held at ASIA MOTORSPORTS SOLUTION PTE LTD | | | | | |
| | 37A EVERITT ROAD SINGAPORE 428586 | | | | | |
| 5a. Remarks | | | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | | |
| 5b. Estimate Days of Repair | | | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | | | |