

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20003533/EGA3Q2

Date: 11/08/2020

REFERENCE

| | | |
|---|-----------------------------|-----------------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No: | MCOM0015 |
| Claimant | | |
| Vehicle No : SME9490D | Insured Vehicle No : | SHC1715D |
| Date of Loss: 28/02/2020 | Nature of Claim: TP | Claim No: MCT20020585 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SME9490D | | |
| Make & Model: | BMW X3, 2.0 I SDRIVE (A) | Engine No: | H4613070B48B20A |
| Reg. Date: | 24/10/2018 (Man. Year: 2018) | Chassis No: | WBATR12050LC94449 |
| Colour: | Grey | Odometer: | 21375 km |
| Engine Capacity: | 1998 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 245/50 R19 | Rear Tyre Size: | 245/50 R19 |
| Front Left Side: | Pirelli 5 mm | Rear Left Side: | Pirelli 5 mm |
| Front Right Side: | Pirelli 5 mm | Rear Right Side: | Pirelli 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-----------------------------|-----------------|-----------------|--------------|
| Parts | 2,842.10 | 2,019.75 | 822.35 | 28.93 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,490.00 | 1,934.00 | 556.00 | 22.33 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 5,332.10 | 3,953.75 | 1,378.35 | 25.85 |
| + GST 7.00/7.00% (S\$) | 373.25 | 276.76 | 96.49 | 25.85 |
| Nett Amount (S\$) | 5,705.35 | 4,230.51 | 1,474.84 | 25.85 |
| + Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$) | | 385.20 | | |
| | Nett Liability (S\$) | 4,615.71 | | |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 16/03/2020 | |
| Date Inspected: | 16/03/2020 Inspected At: | Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: CHEN TSUE YEE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 23 Jul 2020) |
| Parts: | M1-SUV | BMW X3 2.0 I SDRIVE (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SME9490D) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER CARRIER | Not Necessary | 743.50 FS | *- FS |
| 2 | 1 | | *REAR BUMPER BOTTOM REINFORCEMENT | Not Necessary | 78.85 FS | *- FS |
| 3 | 1 | | *REAR BUMPER PANEL PRIMED (M/PMA) | Dented | 1,555.40 FS | *1,555.40 FS |
| 4 | 1 | | *REAR BUMPER BOTTOM TRIM PANEL (M) | Dented | 370.35 FS | *370.35 FS |
| 5 | 1 | | *SUNDRIES | Necessary | 80.00 FS | *80.00 FS |
| 6 | 10 | | *EXPANDING RIVET BLACK | Necessary | 14.00 FS | *14.00 FS |

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,842.10** **2,019.75**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | REPALCING REAR BUMPER AND ATTACHMENT REPLACE DAMAGED PART | New | 1,275.00 | 850.00 |
| 2 | SPRAY REAR BUMPER | New | 1,038.00 | 934.00 |
| 3 | TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION | New | 177.00 | 150.00 |
| Gross Labour Cost (\$\$) | | | 2,490.00 | 1,934.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >