

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20005868/T1TF3E2

Date: 11/09/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00022852001
Claimant Vehicle No :	SJZ7901Z	Insured Vehicle No :	GBH8096E
Date of Loss:	19/05/2020	Nature of Claim:	TP
		Claim No:	SNM20D201962/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ7901Z	Engine No:	P520615062
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BP2SAAK1100938
Reg. Date:	13/11/2019 (Man. Year: 2019)	Odometer:	4328 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,831.70	4,553.30	278.40	5.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,745.00	7,840.00	4,905.00	38.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,576.70	12,393.30	5,183.40	29.49
+ GST 7.00/7.00% (S\$)	1,230.37	867.53	362.84	29.49
Nett Amount (S\$)	18,807.07	13,260.83	5,546.24	29.49

INSPECTION

Date of Assignment:	28/05/2020	Inspected At:	Trans Eurokars Pte Ltd (Ubi)
Date Inspected:	27/05/2020		5 Ubi Close
			Singapore 408605
Estimated Period of Repair:	10.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$208.40 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2020)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ7901Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	997.40 FS	*997.40 FS
2	1		*RETAINER RHS	Necessary	33.20 FS	*33.20 FS
3	1		*BRACKET CENTER	* Check	5.40 FS	*- FS
4	4		*GROMMET, REAR BUMPER	Necessary	9.60 FS	*9.60 FS
5	4		*GROMMET, SCREW	Necessary	10.80 FS	*10.80 FS
6	8		*FASTENER, REAR BUMPER	Necessary	24.00 FS	*24.00 FS
7	2		*BRACKET CENTER, SENSOR	Necessary	46.80 FS	*46.80 FS
8	1		*RETAINER SIDE LHS, SENSOR	Necessary	25.10 FS	*25.10 FS
9	1		*RETAINER SIDE RHS, SENSOR	Necessary	25.10 FS	*25.10 FS
10	1		*PLATE SET RHS, MONITOR	* Check	95.40 FS	*- FS
11	3		*TAPE PROTECTOR, SENSOR	Necessary	14.10 FS	*14.10 FS
12	1		*REAR FENDER RHS	Buckled	1,565.30 FS	*1,565.30 FS
13	1		*PANEL LWR RHS	* Check	107.60 FS	*- FS
14	1		*REAR WINDSCREEN MOULDING	Necessary	49.90 FS	*49.90 FS
15	2		*SPACER, REAR WINDSCREEN	Necessary	23.80 FS	*23.80 FS
16	3		*SPACER, REAR WINDSCREEN	Necessary	38.40 FS	*38.40 FS
17	11		*CLIP, SPOILER ROCKER PANEL	Necessary	30.80 FS	*30.80 FS
18	1		*CLIP, SPOILER ROCKER PANEL	Necessary	3.70 FS	*3.70 FS
19	3		*CLIP, SPOILER ROCKER PANEL	Necessary	30.00 FS	*30.00 FS
20	1		*TAILLAMP RHS	Cut	538.40 FS	*538.40 FS
21	2		*GROMMET, TAILLAMP	Necessary	5.60 FS	*5.60 FS
22	3		*GROMMET, TAILLAMP	Necessary	9.90 FS	*9.90 FS
23	4		*GASKET RHS, TAILLAMP	Necessary	9.60 FS	*9.60 FS
24	1		*REAR WHEEL RIM RHS	Cut	1,031.80 FS	*1,031.80 FS
25	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					4,831.70	4,553.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, REAR FENDER RH, PANEL LOWER RH. TO REPAIR REAR WHEEL ARCH INNER LH, REAR DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENT	New	4,620.00	2,640.00
2	TO RESPRAY REAR BUMPER, REAR FENDER RH, PANEL LOWER RH, REAR WHEEL ARCH INNER LH AND REAR DOOR RH (TO BLEND ROCKER PANEL RH)	New	3,465.00	1,890.00
3	TO SUPPLY SEALER ON THE WINDSCREEN GLASS	New	120.00	120.00
4	TO TRANSFER REVERSE SENSORS	New	330.00	330.00
5	TO SUPPLY 1 PC TYRE	New	480.00	0.00
6	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	120.00
7	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	560.00
8	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	990.00	660.00
9	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	New	350.00	180.00
10	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	150.00
11	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
12	TTO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
13	TO SUPPLY BRILA PREMIUM COATING	New	300.00	300.00
14	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	560.00	560.00
Gross Labour Cost (S\$)			12,745.00	7,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >