Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20007262/GVF3E2

Date: 29/07/2020

REFERENCE

Date of Loss:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00026332001

GBC2681G

Claimant Vehicle SMJ3339Y

13/07/2020

Insured Vehicle No:

No:

Nature of ΤP Claim:

Claim

SNM20D202423/C02/TANGHL2 No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ3339Y**

Make & Model: VOLKSWAGEN GOLF, 2.0 GTI (A) Engine No: CCZ073831

Reg. Date: 24/08/2011 (Man. Year: 2010) Chassis No: WVWZZZ1KZAW424165

Colour: Odometer: 118586 km Red

Engine Capacity: 1984 cc Market Value/New Car

Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Engine Modification: Pre-accident Condition: Handbrake (Serviceable): Yes

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 225/40Z R18 Rear Tyre Size: Front Left Side: Rear Left Side: Goodyear 5 mm Goodyear 5 mm Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,487.90	2,556.25	2,931.65	53.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	400.00	1,400.00	77.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,287.90	2,956.25	4,331.65	59.44
Approved Total (Overridden) (S\$)		1,750.00		
Nett Amount (S\$)	7,287.90	1,750.00	5,537.90	75.99

INSPECTION

Date of Assignment: 16/07/2020

Date Inspected: 15/07/2020 Inspected At: Otto Car Pte Ltd (HQ)

176 Sin Ming Drive, #02-16 Sin Ming

Autocare

Singapore 575721

Estimated Period of Repair: 2.0 days Adjuster Report Page 2 of 4

Adjuster: XING GUO QIANG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jul 2020)

Parts: 144 VOLKSWAGEN GOLF 2.0 GTI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMJ3339Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,267.95 F	*1,267.95 F
2	1		*REAR BUMPER SIDE RETAINER, LH & RH	I N/S Deformed / O/SNotNecessary	90.00 F	*45.00 F
3	2		*REAR BUMPER CORNER RETAINER, LH & RH	Not Necessary	100.00 F	*- F
4	1		*REAR BUMPER CENTRE SUPPORT	Not Necessary	126.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	483.00 F	*- F
6	1		*REAR BUMPER ABSORBER	Not Necessary	88.50 F	*- F
7	1		*REAR BUMPER REFLECTOR, LH	Scratched	68.00 F	*68.00 F
8	1		*TAIL LAMP, LH	Scratched	780.30 F	*780.30 F
9	1		*TAILGATE REFLECTOR LAMP, LH	Not Necessary	552.60 F	*- F
10	1		*REAR FENDER - LH	Not Necessary	1,355.00 F	*- F
11	1		*REAR MUDGUARD, LH	Not Necessary	181.55 F	*- F
12	1		*REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
13	1		*SET REVERSE SENSOR	Not Working	350.00 FS	*350.00 FS
r=Fra	anchise	part. S=S	рсмет.	Total Parts (S\$	5,487.90	2,556.25

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR TO REMOVE / REFIT / RENEW / REPLACE AFFECTED PARTS	New	900.00	200.00
2	SPRAY PAINT	New	900.00	200.00
	Gross Labour Cost (S\$)		1,800.00	400.00
	B			
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >