

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008105/KES3Q2

Date: 07/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800153673

Claimant
Vehicle No : SJR2463X **Insured Vehicle No :** SMF8976X

Date of Loss: 31/07/2020 Nature of Claim: TP Claim No: 4108516347SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR2463X	
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No: 3ZZ4894492
Reg. Date:	16/06/2009 (Man. Year: 2009)	Chassis No: MR053ZEE106146493
Colour:	Metallic Pearl White	Odometer: 204363 km
Engine Capacity:	1598 cc	
Market Value/New Car Price:	N/A	
Sum Insured (\$\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	RADAR 8 mm	Rear Left Side:	RADAR 8 mm
Front Right Side:	RADAR 8 mm	Rear Right Side:	RADAR 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,228.89	517.57	1,711.32	76.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	415.00	705.00	62.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,348.89	932.57	2,416.32	72.15
+ GST 7.00/7.00% (\$\$)	234.42	65.28	169.14	72.15
Nett Amount (\$\$)	3,583.31	997.85	2,585.46	72.15
+ Car Rental (2.0 x S\$100.00/day) (\$\$)		200.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		1,199.85		

INSPECTION

Date of Assignment: 05/08/2020

Date Inspected: 06/08/2020 Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A,
#01-09 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Serviceable	608.70 FL	*- FL
2	1		*FRONT BUMPER	Cracked	581.70 FL	*581.70 FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	63.40 FL	*63.40 FL
4	10		*FRONT BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	334.50 FL	*- FL
6	1		*FOGLAMP RH	Serviceable	298.60 FL	*- FL
7	1		*FOGLAMP COVER R	Serviceable	105.67 FL	*- FL
8	1		*FRONT FENDER RH	Repair	712.10 FL	*- FL
9	1		*FRONT FENDER COWLING RH	Serviceable	196.50 FL	*- FL
10	1		*FRONT FENDER COWLING CLIPS	Not Necessary	25.68 FL	*- FL
11	1		*SPORT RIM RHR (NPA)	Serviceable	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,971.85	690.10
- List Item Discount on L Items 25.00/25.00% (\$)	742.96	172.53
Total Parts (\$)	2,228.89	517.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS .TO KNOCK & REPAIR RADIATOR SUPPORT PANEL ,INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	500.00	200.00
4	TO SPRAY FRONT BUMPER ,FRONT FENDER RH ,RADIATOR SUPPORT PANEL	New	500.00	200.00
Gross Labour Cost (\$\$)			1,120.00	415.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >