Page 1 of 5 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS20008112/R1TF3E2

Date: 04/09/2020

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle SKE9660D No:

Insured Vehicle No:

SLX9865T

Date of Loss:

Reg. Date:

29/07/2020

Nature of Claim:

ΤP

Claim No:

DMPC2000121H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKE9660D Reg No:

VOLKSWAGEN JETTA, 1.4 TSI (A) Make & Model:

20/04/2012 (Man. Year: 2012)

Engine No: Chassis No: Odometer:

CAX976164 WVWZZZ16ZCM093707

111297 km

Colour:

Engine Capacity: 1390 cc Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 225/40 R18 Rear Tyre Size: Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Rear Right Side: Front Right Side: Pirelli 6 mm Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,139.34	0.00	2,139.34	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	600.00	460.00	43.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,199.34	600.00	2,599.34	81.25
+ GST 7.00/7.00% (S\$)	223.95	42.00	181.95	81.25
Nett Amount (S\$)	3,423.29	642.00	2,781.29	81.25

INSPECTION

Date of Assignment: 05/08/2020

Date Inspected: 07/08/2020 Inspected At: Avantage Vag (HQ) 48 Toh Guan Road East

Singapore 608586

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

(REPAIR COST NOT CONCLUDE)

Page 4 of 5 Adjuster Report

REPAIR DETAILS

Reference Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Sep 2020)

Parts: 143 VOLKSWAGEN JETTA 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SKE9660D)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	761.25 FL	*- FL
2	1		*REAR LOWER SPOILER	Not Necessary	507.50 FL	*- FL
3	1		*FOAM INSERT	Not Necessary	141.89 FL	*- FL
4	1		*REINFORCEMENT	Not Necessary	451.50 FL	*- FL
5	1		*CENTRE GUIDE PC	Not Necessary	80.85 FL	*- FL
6	1		*LH GUIDE PC	Not Necessary	89.25 FL	*- FL
7	1		*RH GUIDE PC	Not Necessary	89.25 FL	*- FL
8	1		*SUNDRIES	Not Necessary	30.00 FS	*-FS
9	1		*REVERSE SENSOR	Not Necessary	200.00FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	2,351.49	0.00
	- List Item Discount on L Items 10.00/10.00% (S\$)				212.15	0.00
Total Parts (S\$)				2,139.34	0.00	

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	REMOVE AND REFIT REAR BUMPER, LOWER SPOILER, FOAM INSERT, REINFORCEMENT, GUIDE PCE AND OTHER ASSOCIATED COMPONENTS	New	560.00	250.00				
2	SURFACE PREPARATION AND POLISH REAR BUMPER AND OTHER AFFECTED AREAS	New	400.00	250.00				
3	REMOVE AND REFIT REVERSE SENSORS TO ASSIST REPAIR	New	20.00	20.00				
4	DIAGNOSTIC CHECK AND ERASE FAULT CODES AFTER THE REPAIR	New	80.00	80.00				
	Gross Labour Cost (S\$)		1,060.00	600.00				
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >