Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20009720/T1SF3E2

Date: 22/09/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MG000514 Claimant Vehicle SHC7345Z

Insured Vehicle No: YN8315U No:

ΤP Date of Loss: 10/09/2020 Nature of Claim: Claim No: M2004465

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC7345Z

Make & Model: HYUNDAI I40, 1.7 D CRDi (A) Engine No: D4FDHU730647

Reg. Date: 15/12/2017 (Man. Year: 2016) Chassis No: KMHLB41UMHU100069

Colour: Odometer: 469960 km Yellow

Engine Capacity: 1685 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16 Front Left Side: Rear Left Side: **DURATURN 6 mm DURATURN 6 mm** Rear Right Side: Front Right Side: **DURATURN 6 mm** DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,480.64	1,110.40	1,370.24	55.24
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,200.00	710.00	490.00	40.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,691.64	1,831.40	1,860.24	50.39
+ GST 7.00/7.00% (S\$)	258.41	128.20	130.21	50.39
Nett Amount (S\$)	3,950.05	1,959.60	1,990.45	50.39

INSPECTION

Date of Assignment: 10/09/2020 Present Location: ComfortDelGro Engineering Pte Ltd

(Loyang)

Date Inspected: 10/09/2020 Inspected At: ComfortDelGro Engineering Pte Ltd

> (Loyang) 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Hiew May Fung Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference			
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 22 Sep 2020)	
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	int Code: (Unsubmitted, no print-code for SHC7345Z)		
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER	Repair	1,025.20 FL	-	*- FL
2	1		*FRONT FENDER RH	Repair	663.00 FL	-	*- FL
3	1		*HEADLAMP ASSY RH	Cut	1,388.00 FL	-	*1,388.00 FL
4	1		*FRONT BUMPER BRACKET RH	Not Necessary	24.60 FL	_	*- FL
F=Fra	inchise	part. L=ListIt	emDisc List Item Discount on L Items	Sub Total (S\$) s 20.00/20.00% (S\$)	3,100.80 620.16	1,388.00 277.60	
				Total Parts (S\$)	2,480.64		1,110.40
			Report was unsubmitted d	uring this print-out.]

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellar	neous Items			
1	1	OD/TP Case (Insurer)		11.00	11.00
			Sub Total (S\$)	11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	600.00	280.00
2	SPRAY PAINTING	New	500.00	400.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	0.00
		Gross Labour Cost (S\$)	1,200.00	710.00
Г		Report was unsubmitted during this print-out		

< END OF ESTIMATES >