LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Tokio Marine Insurance Singapore Ltd Our File No: CS4/TMI20010785/NCD3E2

20 McCallum Street, #09-01 Tokio Marine Centre
Singapore 069046

Date: 16/03/2021

REFERENCE

Insured/Claimant: TANGLIN CORPORATION PTE LTD Policy No: MU013224

Date of Loss: 30/09/2020 Nature of Claim: OD Claim No: M2004905

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XE3905J

 Make & Model:
 MAN TGS 35.360, 10.5 D 8X4 BB (M)
 Engine No:
 50546182524618

 Reg. Date:
 26/12/2017 (Man. Year: 2016)
 Chassis No:
 WMA37SZZ0HM729564

Colour: White Odometer: 0 km

Engine Capacity: 10518 cc
Market Value/New Car Price: \$\$100,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5 Rear Tyre Size: 315/80 R22.5 (D)
Front Left Side: Continental 4 mm Rear Left Side: HIFLY 6/7 mm
Front Right Side: Continental 4 mm Rear Right Side: HIFLY 6/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		21,374.69	20,527.69	847.00	3.96
Miscellaneous Items		1,370.47	1,316.57	53.90	3.93
Labour		3,000.00	3,520.30	-520.30	-17.34
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calcu	lated Gross Total (S\$)	25,745.16	25,364.56	380.60	1.48
Approved 1	Total (Overridden) (S\$)		25,363.78		
	- Excess (S\$)	0.00	4,500.00	-4,500.00	
	Nett Amount (S\$)	25,745.16	20,863.78	4,881.38	18.96

INSPECTION

Date of Assignment: 27/10/2020 Present Location: Lee Kuan Hwa Motor Service (Gul Crescent)

Lee Kuan Hwa Motor Service (Gul Crescent)

Date Inspected: 28/10/2020 Inspected At: 20 Gul Crescent

Singapore 629529

Estimated Period of Repair: 30.0 days

Adjuster: Muhammad Nazril Bin Abdullah Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Mar 2021)

Parts: N/A MAN TGS 35.360 10.5 D 8X4 BB (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XE3905J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition I	Repairer's	Reference	Amount
1	2		*ADAPTER (WCP)	Burnt	11.76 F	-	*11.76 F
2	1		*COVER PLATE (WCP)	Burnt	12.12 F	-	*12.12 F
3	1		*EQUIPMENT HOLDER (WCP)	Burnt	48.68 F	-	*48.68 F
4	1		*TOOL SUPPORT (WCP)	Necessary	25.88 F	-	*25.88 F
5	1		*CABLE HARNESS MANUAL GEARBOX (WCP)	Burnt	143.14 F	-	*143.14 F
6	1		*CABLE HARNESS EBS-5 (WCP)	Burnt	440.62 F	-	*440.62 F
7	1		*CABLE HARNESS SYSTEM CARRIER (WCP)	Burnt	1,619.92 F	-	*1,619.92 F
8	1		*ELECTRONIC CONTROL UNIT PTM (WCP)	Burnt	1,025.98 F	-	*1,025.98 F
9	1		*ELECTRONIC CONTROL UNIT	Burnt	4,017.34 F	-	*4,017.34 F
10	1		*TRIM (WCP)	Burnt	23.70 F	-	*23.70 F
11	1		*INSTR.PANEL CTR PART (WCP)	Burnt	73.70 F	-	*73.70 F
12	1		*CARRIER CENTRE ART (WCP)	Burnt	71.26 F	-	*71.26 F
13	1		*INSTRUMENT PANEL (WCP)	Burnt	775.84 F	-	*775.84 F
14	1		*HOUSING BOTTOM PART (WCP)	Burnt	137.20 F	-	*137.20 F
15	1		*HOUSING UPPER PART (WCP)	Burnt	345.58 F	-	*345.58 F
16	2		*AIR DUCT (WCP)	Burnt	6.36 F	-	*6.36 F
17	1		*AIR DUCT (WCP)	Burnt	29.52 F	-	*29.52 F
18	1		*AIR OUTLET (WCP)	Burnt	107.50 F	-	*107.50 F
19	1		*SEALING STRIP (WCP)	Necessary	11.62 F	-	*11.62 F
20	1		*PACKING NARROW (WCP)	Burnt	45.62 F	-	*45.62 F
21	1		*PACKING (WCP)	Burnt	27.90 F	-	*27.90 F
<u>Sup</u>	<u>oleme</u>	<u>entary</u>					
	1		*SNAP NUT (WCP)	Necessary	18.24 F	-	*18.24 F
23	1		*CONTACT BUSH	Deformed	63.90 F	-	*63.90 F
24	1		*BLADE TERMINAL (WCP)	Burnt	13.20 F	-	*13.20 F
25	1		*UNLOCKING TOOL (WCP)	Necessary	118.32 F	-	*118.32 F
26	1		*CRIMPING PLIERS HEAD (WCP)	Necessary	880.18 F	-	*880.18 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
27	1		*CONNECTOR HOUSING (WCP)	Burnt	14.30 F	-	*14.30 F
28	1		*CONNECTOR HOUSING (WCP)	Burnt	14.30 F	-	*14.30 F
29	1		*CABLE HARNESS (WCP)	Burnt	95.04 F	-	*95.04 F
30	1		*CABLE HARNESS OWER TAKEOFF (WCP)	Burnt	115.60 F	-	*115.60 F
31	1		*CABLE HARNESS CAN DATA BUS	Burnt	70.24 F	-	*70.24 F
32	1		(WCP) *CABLE HARNESS EDC7 (WCP)	Burnt	96.14 F	-	*96.14 F
33	1		*CABLE HARNESS ENGINE	Burnt	200.38 F	-	*200.38 F
34	1		(WCP) *CABLE HARNESS RETARDER (WCP)	Necessary	27.66 F	-	*27.66 F
35	1		*TOOL SUPPORT CO DRIVE SIDE	Burnt	28.06 F	-	*28.06 F
36	1		(WCP) *MOLDINGCO DRIVER SIDE (WCP)	Burnt	155.02 F	-	*155.02 F
37	1		*CAB FILTER	Burnt	95.70 F	-	*95.70 F
38	1		(WCP) *AIR DUCT RIGHT (WCP)	Burnt	23.58 F	-	*23.58 F
39	1		*AIR DUCT	Burnt	12.98 F	-	*12.98 F
40	1		(WCP) *AIR DUCT (WCP)	Burnt	18.00 F	-	*18.00 F
41	1		*AIR DUCT	Burnt	26.18 F	-	*26.18 F
42	1		(WCP) *AIR DUCT OUTER (WCP)	Burnt	33.54 F	-	*33.54 F
43	1		*AIR DUCT	Burnt	12.68 F	-	*12.68 F
44	1		(WCP) *HEATER FLAP (WCP)	Burnt	126.96 F	-	*126.96 F
45	1		*LEVER (WCP)	Burnt	7.92 F	-	*7.92 F
46	1		*CABLE HARNESS (WCP)	Burnt	21.42 F	-	*21.42 F
		entary	#2				
47	1		*PANELLING FOR FRONT PANEL NARROW (WCP)	Burnt	83.76 F	-	*83.76 F
		<u>entary</u>					
48	1		*INSTRUMENT CLUSTER AND DO UP SYSTEM REPROGRAM & REPLACEMENT (PARTS ONLY) (WCP)	Not Working	3,363.40 F	-	*3,153.40 F
49	1		*RADIO SYSTEM MMT STARTER AND DO UP SYSTEM REPROGRAM & REPLACEMENT (PARTS ONLY) (WCP)	Not Working	1,289.88 F	-	*1,219.88 F
		<u>entary</u>	<u>#4</u>				
50	1		*ZBR CONTROL UNIT AND DO U SYSTEM PROGRAMMING (REPLACEMENT (PARTS ONLY) (WCP)	& Not Working	2,780.24 F	-	*2,570.24 F
51	1		*CLIMATE CONTROL UNIT & REPLACEMENT (PARTS ONLY) (WCP)	Not Working	623.48 F	-	*343.48 F
F=Fra	nchise	part.	•	.b Total (04)	40 404 54	40 004 54	
			+ Margin on L,N Items 10.00/	ib Total (S\$) 10.00% (S\$)		18,661.54 1,866.15	
			Tota	al Parts (S\$)	21,374.69		20,527.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Misc	cellan	eous Items			
1	1	7% GST FROM SUPPLIER		630.08	630.08
2	1	OD/TP Case (Insurer)		11.77	11.77
<u>Sup</u>	<u>pleme</u>	entary #1			
3	1	7% GST FROM SUPPLIER		158.77	158.77
<u>Sup</u>	<u>pleme</u>	entary #2			
4	1	7% GST FROM SUPPLIER		5.86	5.86
Sup	<u>pleme</u>	entary #3			
5	1	7% GST FROM SUPPLIER		325.73	306.13
<u>Sup</u>	<u>pleme</u>	entary #4			
6	1	7% GST FROM SUPPLIER		238.26	203.96
			Sub Total (S\$)	1,370.47	1,316.57

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	LABOUR FOR REMOVE, INSTALL AND TROUBLESHOOT WIRE HARNESS OF CABIN DASHBOARD, REPLACE PTM AND EBS CONTROL UNIT AND THE FOLLOWING PARTS AND DO-UP SYSTEM REPROGRAM	New	3,000.00	2,520.00
2	TO CHECK AND REPLACE INSTRUMENT CLUSTER AND DO-UP SYSTEM REPROGRAM	New	-	210.00
3	TO CHECK AND REPLACE RADIO SYSTEM AND DO-UP SYSTEM REPROGRAM	New	-	70.00
4	TO CHECK AND REPLACE ZBR CONTROL UNIT AND DO-UP SYSTEM PROGRAMMING	I New	-	210.00
5	TO CHECK AND REPLACE CLIMATE CONTROL UNIT	New	-	280.00
6	7% GST FROM SUPPLIER (LABOUR)	New	-	230.30
	Gross Labour	r Cost (S\$)	3,000.00	3,520.30
	Report was unsubmitted during this	print-out.		

3 1

< END OF ESTIMATES >