Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20010977/T1CD3Q2

Date: 19/02/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: ML000134

Claimant SHC7437S Insured Vehicle No: SLF7250A

Vehicle No: SHC/4375 Insured vehicle No: SLF/250A

Date of Loss: 08/10/2020 Nature of Claim: TP Claim No: M2004986

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC7437S

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2B87249

Reg. Date: 13/12/2018 (Man. Year: 2018) Chassis No: JTDKB3FU503078075

Colour: Yellow Odometer: 221482 km

Engine Capacity: 1798 cc
Market Value/New Car
N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Davanti 6 mm Rear Left Side: Davanti 6 mm
Front Right Side: Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,469.10	1,054.60	414.50	28.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,010.00	430.00	580.00	57.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,479.10	1,484.60	994.50	40.12
+ GST 7.00/7.00% (S\$)	173.54	103.92	69.62	40.12
Nett Amount (S\$)	2,652.64	1,588.52	1,064.12	40.12

INSPECTION

Date of Assignment: 09/10/2020

Date Inspected: 12/10/2020 Inspected At: Ding Auto Pte Ltd (corporation Road)

(HQ)

31 Corporation Road Singapore 649825

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Different 1 cents -Finalise confirm amount: \$1,484.59

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2021)		
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code: (Unsubmitted, no print-code for SHC7437S)				
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

	*REAR BUMPER *REAR BUMPER DIFFUSER	Deformed Deformed	490.50 FL 582.30 FL		*490.50 FL
		Deformed	582 30 EI		
	*DEAD TOW 64D		302.301 L	-	*582.30 FL
	*REAR TOW CAP	Not Necessary	37.10 FL	-	*-FL
	*REAR BUMPER REINFORCEMENT	Not Necessary	328.90 FL	-	*-FL
	*SET REAR BUMPER REVERSE SENSOR	Not Working	230.00 FS	-	*200.00 FS
	*SET REAR BUMPER CLIP	Necessary	50.00 FS	-	*30.00 FS
	*REAR NUMBER PLATE WITH FRAME	Not Necessary	60.00 FS	-	*-FS
	*SUNDRIES	Necessary	50.00 FS	-	*20.00 FS
hise	part. S=SpcNett. L=ListItemDisc.				
		Sub Total (S\$)	1,828.80	1,322.80	
	- List Item Discount on L Items 25.	00/25.00% (S\$)	359.70	268.20	
	т	otal Parts (S\$)	1,469.10		1,054.60
h	ise	*SET REAR BUMPER REVERSE SENSOR *SET REAR BUMPER CLIP *REAR NUMBER PLATE WITH FRAME *SUNDRIES ise part. S=SpcNett. L=ListItemDisc List Item Discount on L Items 25.0	*SET REAR BUMPER REVERSE SENSOR Not Working *SET REAR BUMPER CLIP Necessary *REAR NUMBER PLATE WITH FRAME Not Necessary *SUNDRIES Necessary ise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$)	*SET REAR BUMPER REVERSE SENSOR Not Working *SET REAR BUMPER CLIP Necessary *REAR NUMBER PLATE WITH FRAME Not Necessary *SUNDRIES Necessary *SUNDRIES Necessary ise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 1,828.80 - List Item Discount on L Items 25.00/25.00% (S\$) 359.70	*SET REAR BUMPER REVERSE SENSOR Not Working 230.00 FS - *SET REAR BUMPER CLIP Necessary 50.00 FS - *REAR NUMBER PLATE WITH FRAME Not Necessary Necessary 50.00 FS - *SUNDRIES Necessary 50.00 FS - *SUNDRIES Sub Total (S\$) 1,828.80 1,322.80 - List Item Discount on L Items 25.00/25.00% (S\$) 359.70 268.20

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	STRAIGHT AND PANEL BEAT ACCIDENT AREA	New	500.00	200.00
2	DIAGNOSTIC (CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	New	180.00	0.00
3	R&R REVERSE SENSOR	New	80.00	30.00
4	RESPRAY REAR BUMPER	New	250.00	200.00
	Gross Labou	r Cost (S\$)	1,010.00	430.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.