

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

20-11-9598

Date:

10/11/2020

INVOICE NO. 9598

Chern Ling Jye c/o Triple-T Automobile Blk 6 Defu Lane 10 #01-556 Singapore 539187

Registration No.

SMR6655Y

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 898.00
		Total amount	\$ 898.00

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

L. L. Tan (Ms)

Principal Consultant



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

Our reference:

20-11-9598

Date:

10/11/2020

c/o Triple-T Automobile Blk 6 Defu Lane 10 #01-556 Singapore 539187

Dear Sirs

RE:

Road Traffic Accident on 7/10/2020

Chern Ling Jye

In accordance with your instructions received in this office or examine the vehicle on

20/10/2020

20/10/2020

, we made arrangements to

at above-mentioned address. The following data was

recorded:

Vehicle details

Make	Honda	Registration	SMR6655Y
Model	Civic	Chassis	JHMFD16306S208690
Colour	Black	Gearbox	Auto
Odometer	170023km	Paintwork	Good
Steering	Good	Brakes	Good
Condition	Good		

Tyre Depths

Front left	205/55R16	85% Acenda
Front right	205/55R16	85% Acenda
Rear left	205/55R16	85% Acenda
Rear right	205/55R16	85% Acenda

Status	REPAIRABLE		
Magnitude	Medium		
Legal status	Unroadworthy		

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$10,500.00 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385** 11**71**

Our reference

20-11-9598

Date

10/11/2020

Page

2

Section A: Damaged Parts Assessment

Section A: Dai	nageu	Parts Assessine	arc	
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items:				
Front bumper	1	multple-cut	732.50	732.50
Front bumper side retainer Ih	1	Ih damaged	25.50	25.50
Front bumper fog lamp lh	1	cracked	330.00	330.00
Front bumper fog lamp garnish lh	1	deformed	65.00	65.00
Headlamp ih	1	damaged	986.70	986.70
Headlamp lower bracket Ih	1	necessary	137.00	137.00
Headlamp panel Ih	2	repair	185.60	0.00
Front fender Ih	1	bent	584.20	584.20
Front fender inner shield lh	1	damaged	65.00	65.00
Front shock absorber stopper Ih	1	damage	56.00	56.00
Front shock absorber mounting Ih	1	damage	75.00	75.00
Front shock absorber cover lh	1	damage	30.00	30.00
Front shock absorber lh	1	bent	467.40	467.40
Front lower arm lh	1	bent	265.21	265.21
Front knuckle arm Ih	1	bent	365.10	365.10
Front knuckle arm bearing lh	1	necessary	132.40	132.40
Front knuckle arm bearing hub lh	1	necessary	201.50	201.50
Front lower arm link lh	1	bent	75.80	75.80
Front side mirror assy Ih	1	broken/distorted	551.20	551.20
Front door Ih	1	bent	808.00	808.00
Front door lock Ih	1	damaged	203.30	203.30
Front door outer handle Ih	1	grazed	110.20	110.20
Front door regulator gear Ih	1	bent	295.00	295.00
Front door regulator motor lh	1	ceased	115.00	115.00
Front door protector Ih	1	damaged/nec	95.50	95.50
Rear door lh	1	bent	808.00	808.00
Rear door lock lh	1	bent	203.30	203.30

Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd

 [◆] IA Accounting & Consultancy Pte Ltd
 ◆ Infoknights International Services (Philippines)
 ◆ IABN Pte Ltd
 www.iaconsultingsg.com



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

Rear door regulator gear Ih 1 bent 295.00 295. Rear door regulator motor Ih 1 ceased 115.00 115. Rear door protector Ih 1 damaged/nec 95.50 95. Rear door glass moulding Ih 1 necessary 150.50 150. Rocker panel Ih 1 repair 498.70 0. Side skirt Ih 1 bent 596.50 596. Rear fender Ih 1 repair_respray 896.50 0. Rear bumper 1 repair_respray 711.00 0. Centre door pillar Ih 1 repair_respray 711.00 0. Sub-Total costs 11750.81 9146. 9146. Sub-Total costs for parts 9400.65 7317. Special Nett Items: Front wheel tyre Ih @85% 1 abraded 300.00 255. Front bumper clips set necessary 50.00 50. Front fender sealant Ih 1 necessary 40.00<	Our reference	20-11-9598				
Rear door regulator gear Ih 1 bent 295.00 295. Rear door regulator motor Ih 1 ceased 115.00 115. Rear door protector Ih 1 damaged/nec 95.50 95. Rear door glass moulding Ih 1 necessary 150.50 150. Rocker panel Ih 1 repair 498.70 0. Side skirt Ih 1 bent 596.50 596. Rear fender Ih 1 repair_respray 896.50 0. Rear bumper 1 repair_respray 711.00 0. Centre door pillar Ih 1 repair_respray 711.00 0. Sub-Total costs 11750.81 9146. 9146. Sub-Total costs for parts 9400.65 7317. Special Nett Items: Front wheel tyre Ih @85% 1 abraded 300.00 255. Front bumper clips set necessary 50.00 50. Front fender sealant Ih 1 necessary 40.00<	Date	10/11/2020				
Rear door regulator gear Ih 1 bent 295.00 295. Rear door regulator motor Ih 1 ceased 115.00 115. Rear door protector Ih 1 damaged/nec 95.50 95. Rear door glass moulding Ih 1 necessary 150.50 150. Rocker panel Ih 1 repair 498.70 0. Side skirt Ih 1 bent 596.50 596. Rear fender Ih 1 repair_respray 896.50 0. Rear bumper 1 repair_respray 711.00 0. Centre door pillar Ih 1 repair_respray 711.00 0. Sub-Total costs 11750.81 9146. 9146. Sub-Total costs for parts 9400.65 7317. Special Nett Items: Front wheel tyre Ih @85% 1 abraded 300.00 255. Front bumper clips set necessary 50.00 50. Front fender sealant Ih 1 necessary 40.00<						
Rear door regulator motor Ih 1 ceased 115.00 115.	Rear door outer ha	ndle lh	1	grazed	110.20	110.20
Rear door protector h	Rear door regulator	r gear lh	1	bent	295.00	295.00
Rear door glass moulding Ih 1 necessary 150.50 150.	Rear door regulator	r motor lh	1	ceased	115.00	115.00
Rocker panel lh	Rear door protecto	r lh	1	damaged/nec	95.50	95.50
Side skirt lh	Rear door glass mo	ulding Ih	1	necessary	150.50	150.50
Rear fender lh	Rocker panel Ih		1	repair	498.70	0.00
Rear bumper 1 repair.respray 711.00 0.0 Centre door pillar lh 1 repair 312.50 0.0 Sub-Total costs 11750.81 9146. Sub-Total costs for parts 2350.16 1829. Sub-Total costs for parts 9400.65 7317. Special Nett Items: Front wheel tyre lh @85% 1 abraded 300.00 255. Front wheel rim lh (sport) 1 cut 750.00 750. Front bumper clips set necessary 50.00 50. Front fender sealant lh 1 necessary 40.00 40. Sub-Total costs for parts 1140.00 1095. Parts Repair * * * 0.00 0. Sub-Total costs 0.00 0.	Side skirt lh		1	bent	596.50	596.50
Sub-Total costs 11750.81 9146.	Rear fender Ih		1	repair.respray	896.50	0.00
Sub-Total costs 11750.81 9146.	Rear bumper		1	repair.respray	711.00	0.00
Percentage discount : 20% 2350.16 1829.	Centre door pillar lh	1	1	repair	312.50	0.00
Special Nett Items: 9400.65 7317. Front wheel tyre Ih @85% 1 abraded 300.00 255. Front wheel rim Ih (sport) 1 cut 750.00 750. Front bumper clips set necessary 50.00 50. Front fender sealant Ih 1 necessary 40.00 40. Sub-Total costs for parts 1140.00 1095. Parts Repair * * * 0.00 0. Sub-Total costs 0.00 0.			Sub- Total	costs	11750.81	9146.51
Special Nett Items: Front wheel tyre Ih @85% 1 abraded 300.00 255. Front wheel rim Ih (sport) 1 cut 750.00 750. Front bumper clips set necessary 50.00 50. Front fender sealant Ih 1 necessary 40.00 40. Sub-Total costs for parts 1140.00 1095. Parts Repair * * * 0.00 0. Sub-Total costs 0.00 0.		Perc	entage discount :	20%	2350.16	1829.30
Front wheel tyre Ih @85% 1 abraded 300.00 255. Front wheel rim Ih (sport) 1 cut 750.00 750. Front bumper clips set necessary 50.00 50. Front fender sealant Ih 1 necessary 40.00 40. Sub-Total costs for parts 1140.00 1095. Parts Repair * * * 0.00 0. Sub-Total costs 0.00 0.			Sub-Total cost:	s for parts	9400.65	7317.21
Front wheel tyre Ih @85% 1 abraded 300.00 255. Front wheel rim Ih (sport) 1 cut 750.00 750. Front bumper clips set necessary 50.00 50. Front fender sealant Ih 1 necessary 40.00 40. Sub-Total costs for parts 1140.00 1095. Parts Repair * * * 0.00 0. Sub-Total costs 0.00 0.	Special Nett Items:					
Front wheel rim lh (sport) 1 cut 750.00 750. Front bumper clips set necessary 50.00 50. Front fender sealant lh 1 necessary 40.00 40. Sub-Total costs for parts 1140.00 1095. Parts Repair * * * 0.00 0. Sub-Total costs 0.00 0.			1	abraded	300.00	255.00
Front fender sealant lh 1 necessary 40.00 40. Sub-Total costs for parts 1140.00 1095. Parts Repair * * * 0.00 0. Sub-Total costs 0.00 0.			1	cut	750.00	750.00
Sub-Total costs for parts 1140.00 1095.	Front bumper clips		set	necessary	50.00	50.00
Parts Repair *	Front fender sealan	t lh	1	necessary	40.00	40.00
*			Sub-Total costs	s for parts	1140.00	1095.00
Sub- Total costs 0.00 0.	Parts Repair					
	*		*	*	0.00	0.00
			Sub- Total	costs	0.00	0.00
Total costs for parts 10540.65 8412.			Total costs fo	or parts	10540.65	8412.21

Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd



Our reference 20-11-9598

Date 10/11/2020

Page 3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 48.00	26	\$ 1,248.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material. (front door, side skirt, bonnet, front bumper / lower lid, front fender)	Sub-contract work.		\$ 1,600.00
Apply rust proofing on the adjacent panels.	Sub-con	tract work.	\$ 120.00
Remove and refix front undercarriage works Ih	\$ 48.00	6	\$ 288.00
Transfer of existing door mechanism to new door (2 nos).	\$ 48.00	3.6	\$ 172.80
Specialist charges - Computerized wheel alignment	-	-	\$ 120.00
Specialist charges - Dignostic fault code / reset			\$ 200.00
Wiring and bulb checking	\$ 48.00	1	\$ 48.00
	Total la	bour cost	\$ 3,796.80

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

20-11-9598

Date

10/11/2020

Section C: Summary Table of Total Repair Cost

Desc	ription	Cost	
Asses	sed Parts ssment ection A)	\$8,412.21	
Further discount	20%	\$1,682.44	
Recommended cost of parts		\$6,729.77	(1)
	t Calculation ection B)	\$3,796.80	(2)
	epair Cost to hundred)	\$10,500.00	(1) + (2)

We would recommend a sum of	\$10,500.00	and	8	working days for repair.
No further items will be approved	without our expres	sed written agree	ement. Any si	gnificant additional
items will be subject to a supplem	entary report.			

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

Enterprise Singapore - Recognised Certification for Management Consultants

IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

Subsidiaries of Impact Analysis Consultant:

[•] Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd















