Adjuster Report 10/14/21, 3:40 PM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/III20014412/QPA3Q2

Date:

14/10/2021

REFERENCE

Date of Loss:

Handling Insurer: India International Insurance Pte Ltd Policy No:

MCOM0015 SHD7221S

Claimant Vehicle No:

SME9050R 18/12/2020

Insured Vehicle No:

Nature of Claim:

ΤP

Claim No:

MCT20120357

MR053ZEE106155972

3ZZ4934779

0 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME9050R**

TOYOTA COROLLA ALTIS, 1.6 (A) Make & Model:

02/10/2009 (Man. Year: 2009) Reg. Date:

Colour: Blue 1598 cc

Engine Capacity: Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

CONDITION OF TYRES

Front Left Side:

Front Tyre Size: 195/65 R15

Rear Tyre Size: Goodyear 6 mm Rear Left Side:

195/65 R15 Goodyear 6 mm Goodyear 6 mm

Front Right Side: Goodyear 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,450.00	0.00	2,450.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	980.00	1,590.00	61.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,020.00	980.00	4,040.00	80.48

Rear Right Side:

+ Loss of Use (4.0 x S\$60.00/day) (S\$)

240.00

(S\$)	1,220.00
Liable Amount (50.00%) (S\$)	610.00
Global Sum Settlement (S\$)	600.00

INSPECTION

Date of Assignment: 23/12/2020

Auburn Auto Pte Ltd (HQ) Date Inspected: Inspected At: 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE 24/12/2020

Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster:	OI SUN PIN	Manager:	CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Aug 2021)

TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0) Parts: 143

(Price-denominated Standard List) Labour: Repairer's

(Unsubmitted, no print-code for SME9050R) **Print Code:**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR R/H FENDER	Repair	800.00 F	*- F
2	1	*REAR BUMPER	Repair	800.00 F	*- F
3	1	*REAR R/H DOOR CHROME STRIP	Serviceable	200.00 F	*-F
4	1	*REAR R/H RIMS	Serviceable	500.00 F	*- F
5	1	*REAR L/H PANEL CLIP	Serviceable	150.00 FS	*- FS
F=Fra	anchise part. S=SpcNett.				
			Total Parts (S\$)	2,450.00	0.00

Report was unsubmitted during this print-out.

10/14/21, 3:40 PM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>			
1 REMOVE AND REFIT PANELS	New	800.00	300.00
2 APPLY TUFF KOTE	New	300.00	50.00
3 REMOVE ,REFIT AND REPLACED DAMAGE AND CHECK UP REAR ELECTRICAL WIRING	New	150.00	0.00
4 REMOVE AND REFIT INNER GARNISHES TRIM TO ASSIST REPAIR	New	200.00	0.00
5 TO APPLY UNDERCOATING ON REPLACED PANEL	New	120.00	30.00
6 TO RESPRAY PAINTING	New	1,000.00	600.00
	Gross Labour Cost (S\$)	2,570.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >