

Blk 406 Tampines St 41 #03-31 Singapore 520406 Co. Regn. No. 53153313E Fax: 6384 3688 Hotline: 8282 1100

Our reference:

20-08-9349

Date:

10/8/2020

INVOICE NO.

9349

Caldron Tan Heng Kiat

c/o Majesty Car Leasing 39 Woodlands Close #01-36 Mega@ Woodlands Singapore 737856

Registration No.

SGS184U

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	-	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$	798.00
	inspection, priorographic	Total amount	\$	798.00

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

~

L. L. Tan (Ms)
Principal Consultant





Blk 406 Tampines St 41 #03-31 Singapore 520406 Co. Regn. No. 53153313E Fax: 6384 3688 Hotline: 8282 1100

Our reference:

20-08-9349

Date:

10/8/2020

c/o Majesty Car Leasing 39 Woodlands Close #01-36 Mega@ Woodlands Singapore 737856

Dear Sirs

RE:

Road Traffic Accident of 25/7/2020

Caldron Tan Heng Kiat

In accordance with your instructions received in this office on

28/7/2020

, we made arrangements to

examine the vehicle on

28/7/2020

at above-mentioned address. The following data was

recorded:

Vehicle details

Make	Audi	Registration	SGS184U	
Model	A5	Chassis	WAUZZZ8T2BA088656	
Colour	Black	Gearbox	Auto	
Odometer	157650km	Paintwork	Good	
Steering	In order	Brakes In order		
Condition	Good			

Tyre Depths

Front left	255/35ZR19	85% / Kinforest
Front right	255/35ZR19	85% / Kinforest
Rear left	255/35ZR19	85% / Kinforest
Rear right	255/35ZR19	85% / Kinforest

Status	REPAIRABLE		
Magnitude	Medium		
Legal status	Unroadworthy		

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$11,700.00 and 9 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.





51 Ubi Ave 1 Blk 406 Tampines St 41 #03-31 Singapore 520406 Co. Regn. No. 53153313E

Fax: 6384 3688 Hotline: 8282 1100

Our reference

20-08-9349

Date

10/8/2020

Page

2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items:				
Front bumper	1	repair.respray	1652.40	0.00
Front bumper side retainer lh	1	necessary	55.20	55.20
Wiper tank	1	dented	135.70	135.70
Front fender Ih	1	bent/cut	925.40	925.40
Front fender inner garnish Ih	1	damaged	166.20	166.20
Front fender inner shield Ih	1	damaged	99.80	99.80
Front shock absorber Ih	. 1	bent	412.00	412.00
Front knuckle arm Ih	1	bent	585.00	585.00
Front knuckle bearing/ hub lh	1	necessary	510.00	510.00
Front cross arm (oil leak)	1	bent	296.80	296.80
Front lower arm long	1	bent	288.00	288.00
Front lower arm short	1	bent	245.00	245.00
Front side mirror assy Ih	1	intact	758.45	0.00
Front door Ih	1	bent/deep-cut	1885.50	1885.50
Front door weatherstrip lh	1	ripped	342.40	342.40
Front door inner lock lh	1	damaged	352.00	352.00
Front door inner board Ih	1	torn/deformed	612.40	612.40
Front door hinge @\$85.00	2	distorted	170.00	170.00
Front door channel (chrome) lh	1	necessary	155.70	155.70
Front door outer handle lh	1	intact	144.80	0.00
Front door window gear regulator Ih	1	bent	233.50	233.50
Front door window gear motor lh	1	ceased	277.00	277.00
Rear door Ih	1	repair.repaint	1866.50	0.00
Rear door inner lock lh	1	damaged	352.00	352.00
Rear door inner board lh	1	serviceable	612.40	0.00
Front door hinge @\$85.00	2	serviceable	170.00	0.00
Front door channel (chrome) lh	1	necessary	155.70	155.70
Front door outer handle lh	1	intact	144.80	0.00





51 Ubi Ave 1 Blk 406 Tampines St 41 #03-31 Singapore 520406 Co. Regn. No. 53153313E Fax: 6384 3688

Hotline: 8282 1100

		Total costs f	or parts _	17271.58	10763.61
		Sub- Total		0.00	0.00
*		•	*	0.00	0.00
Parts Repair					
		Sub-Total costs	s for parts =	1817.60	1742.60
Rear tyre Ih @\$85	5%	1	abraded/cut _	250.00	212.50
Front tyre Ih @85	%	1	abraded/cut	250.00	212.50
Front tyre rim lh		1	cut	658.80	658.80
Rear tyre rim lh		1	cut	658.80	658.80
Special Nett Items	<u>s:</u>				
		Sub-Total costs	for parts =	15453.98	9021.01
	Pero	entage discount :	5%	813.37	474.79
		Sub- Total	costs	16267.35	9495.80
Rear knuckle arm l	bearing / hub Ih	1	necessary	510.00	510.00
Rear kunckle arm l	h	1	bent	85.00	85.00
Rear shock absorb	er Ih	1	bent	412.00	412.00
Rear fender Ih		1	repair.respray	1145.20	0.00
Front door window gear motor lh		1	serviceable	277.00	0.00
Front door window gear regulator lh		1	bent	233.50	233.50
Date	10/8/2020				
Our reference	20-08-9349				





Blk 406 Tampines St 41 #03-31 Singapore 520406 Co. Regn. No. 53153311E Fax: 6384 3688 Hotline: 8282 1100

Our reference

20-08-9349

Date

10/8/2020

Page

3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	26	\$ 1,170.00
To apply undercoating, putty and spray painting to adjacent panels. Job allowance. Paint / material.	Sub-conf	tract work.	\$ 1,300.00
Wiring / bulb checking	\$ 45.00	0.5	\$ 22.50
Remove and refix front undercacrriage work Ih	\$ 45.00	5	\$ 225.00
Transfer of existing rear door mechanism to new door lh	\$ 45.00	1.8	\$ 81.00
Remove and refix rear undercacrriage work lh	\$ 45.00	5	\$ 225.00
Transfer of existing front door mechanism to new door lh	\$ 45.00	1.8	\$ 81.00
Specialist charges - Wheel alignment	-		\$ 60.00
	Total la	bour cost	\$ 3,164.50

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.





Blk 406 Tampines St 41 #03-31 Singapore 520406 Co. Regn. No. 53153311E Fax: 6384 3688 Hotline: **8282 1100**

Our reference

20-08-9349

Date

10/8/2020

Page

4

Section C: Summary Table of Total Repair Cost

Description Damaged Parts Assessment (See section A)		Cost	190
		\$10,763.61	
Further discount	20%	\$2,152.72	
Recommended cost of parts replacement		\$8,610.89	(1)
	et Calculation	\$3,164.50	(2)
Total Repair Cost (Round off to hundred)		\$11,700.00	(1) + (2)

We would recommend a sum of	\$11,700.00	and	9	working days for repair.
No further items will be approved v	vithout our expresse	ed written agreem	ent. Any signi	ficant additional
items will be subject to a suppleme	ntary report.			

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

SPRING- Recognised Certification for Management Consultants













































































































































