LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III20013534/GTF3E2-1

Date: 05/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: 199303821R

Claimant Vehicle SLE1874U Insured Vehicle No: SHA3564U

No:

Date of Loss: 05/12/2020 Nature of Claim: TP Claim No: MCT20120122

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE1874U

 Make & Model:
 TOYOTA SIENTA, 1.5 G (A)
 Engine No:
 2NR8534271

 Reg. Date:
 12/07/2016 (Man. Year: 2015)
 Chassis No:
 NSP1707008583

 Colour:
 Blue
 Odometer:
 68687 km

Colour: Blue Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm
Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		11,182.21	2,553.59	8,628.62	77.16
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,420.00	1,150.00	3,270.00	73.98
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	15,602.21	3,703.59	11,898.62	76.26
	Approved Total (Overridden) (S\$)		2,950.00		
	Nett Amount (S\$)	15,602.21	2,950.00	12,652.21	81.09

INSPECTION

Date of Assignment: 08/12/2020

Sau Hock Motor Services (HQ)

Date Inspected: 14/12/2020 Inspected At: 10 Ang Mo Kio Industrial Park 2A, #02-14 AMK

Autopoint

Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG Manager: DENISE TAY KWEE CHENG

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Feb 2021)

Parts: M1-MPV TOYOTA SIENTA 1.5 G (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLE1874U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Squashed	1,218.20 F	*788.70 FL
2	2		*REAR BUMPER CORNER RETAINER RH / LH	Serviceable	263.40 F	*- FL
3	2		*REAR BUMPER SIDE GARNISH RH / LH	Deformed / Fractured	302.00 F	*302.00 FL
4	2		*REAR BUMPER REFLECTOR RH / LH	Serviceable	166.20 F	*- FL
5	2		*REAR BUMPER SIDE RETAINER RH / LH	Serviceable	282.80 F	*- FL
6	6		*REAR BUMPER SIDE SHIELD CLIP	Serviceable	39.00 F	*- FL
7	2		*REAR BUMPER SIDE SHIELD RH / LH	Serviceable	375.44 F	*- FL
8	1		*REAR BUMPER TOW HOOK COVER	Serviceable	43.20 F	*- FL
9	1		*REAR END PANEL - INNER	Repair	581.24 F	*- FL
10	1		*REAR END PANEL - OUTER	Repair	480.85 F	*- FL
11	1		*REAR END PANEL INNER TOP GARNISH	Fractured	289.74 F	*289.74 FL
12	6		*REAR END PANEL INNER TOP GARNISH CLIP	Necessary	39.00 F	*39.00 FL
13	1		*REAR END PANEL LOCK STRIKER	Serviceable	56.00 F	*- FL
14	2		*REAR FENDER INNER AIR VENT RH / LH	Reuse	343.60 F	*- FL
15	1		*REAR ANTENNA SENSOR	Serviceable	127.00 F	*- FL
16	1		*TAILGATE	Buckled	1,217.80 F	*1,217.80 FL
17	1		*TAILGATE LOGO TOYOTA	Necessary	79.20 F	*68.35 FL
18	1		*TAILGATE EMBLEM SIENTA	Serviceable	61.70 F	*- FL
19	2		*TAILGATE DAMPER RH / LH	Serviceable	583.40 F	*- FL
20	2		*TAILGATE HINGE RH / LH	Serviceable	543.60 F	*- FL
21	1		*TAILGATE INNER HANDLE	Serviceable	137.40 F	*- FL
22	1		*TAILGATE MECHANISM LOCK	Bent	591.40 F	*489.00 FL
23	2		*REAR NUMBER PLATE LAMP RH / LH	Serviceable	83.70 F	*- FL
24	1		*TAILGATE OUTER GARNISH	Serviceable	281.80 F	*- FL
25	4		*TAILGATE OUTER GARNISH CLIP	Serviceable	26.00 F	*- FL
26	1		*TAILGATE OUTER HANDLE	Serviceable	171.47 F	*- FL
27	1		*TAILGATE WEATHERSTRIP	Serviceable	281.40 F	*- FL
28	1		*TAILGATE WINDSCREEN MOULDING	Necessary	192.40 F	*130.20 FL
29	1		*TAILGATE WIPER MOTOR	Serviceable	581.72 F	*- FL
30	1		*SPARE TYRE PANEL	Serviceable	791.55 F	*- FL
31	1		*REAR NUMBER PLATE C/W HOLDER	Serviceable	50.00 FS	*- FS
32	1		*TAILGATE REVERSE CAMERA	Serviceable	550.00 FS	*- FS
33	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
34	1		*SPARE TYRE PANEL INSULATOR MAT	Serviceable	250.00 FS	*- FS
F=Fra	anchise	nart S=Sncl	Nett. L=ListItemDisc.			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) - List Item Discount on L Items 0.00/25.00% (S\$)	11,182.21 0.00	3,384.79 831.20
Total Parts (S\$)	11,182.21	2,553.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	TO STRAIGHTEN AND PANEL BEATING REAR FENDER RH / LH, REAR BOOT, FLOOR PANEL, SPARE TYRE PANEL AND REAR FRAME MEMBERS. TO CUT AND WELD REAR END PANEL. TO REMOVE AND REFIT ABOVE PARTS	New	2,000.00	400.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS	New	2,000.00	600.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	120.00	30.00
4	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO RUST PROOF AFFECTED AREAS	New	150.00	0.00
	Gross Labor	ur Cost (S\$)	4,420.00	1,150.00
	Report was unsubmitted during this p	print-out.		

< END OF ESTIMATES >