

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

Our reference:

20-06-9263

Date:

15/6/2020

c/o AKA Auto Pte Ltd No. 25 Kaki Bukit Road 4 #05-37 Synergy@KB Singapore 417800

Dear Sirs

RE:

Road Traffic Accident on 23/5/2020

Ho Lee Chean

In accordance with your instructions received in this office on

27/5/2020

, we made arrange

examine the vehicle on

27/5/2020

at above-mentioned address. The following da

recorded:

Vehicle details

Make	Mercedes	Registration	SKN3548M	
Model	CLA200	Chassis	WDD1173432N09	
Colour	Grey	Gearbox	Auto	
Odometer	123782km	Paintwork	Good	
Steering	In order	Brakes	In order	
Condition	Good			

Tyre Depths

Front left	225/40R18	85% Bridgestone
Front right	225/40R18	85% Bridgestone
Rear left	225/40R18	85% Bridgestone
Rear right	225/40R18	85% Bridgestone

Status	REPAIRABLE			
Magnitude	Medium			
Legal status	Unroadworthy			

Impact Direction & Area of Da



Following our examination of the accident damage, we have calculated repair times and method, whic detailed on page 2 & 3. We would recommend a sum of \$11,400.00 and 9 for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
 Infoknights International Services (Philippines)
 IABN Pte Ltd www.iaconsultingsg.com



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

20-06-9263

Date

15/6/2020

Page

2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As	Repairer's	Our
raits bescription	Qty	inspected	Estimate	Adjustment
List Items:				3 = 10 4.
Front bumper	1	deformed	1742.00	1742.00 1554
Front bumper upper bracket	1	damaged	155.00	155.00
Front bumper "Mercedes " badge	1	damaged	120.00	120.00
Front bumper upper grille mercedes logo	1	necessary	85.00	85.00 /
Front bumper tow cover	1	missing	42.50	42.50
Front license plate holder	1	damaged	89.40	89.40× SVC
Front bumper reinforcement	1	bent	688.00	688.00 585/
Front bumper reinforcement bracket @\$115.00	2	damaged	230.00	230.00 X SVC
Front bumper sponge centre	1	damaged	223.00	223.00
Front bumper sponge side @\$123.00	2	damaged	246.00	246.00 ≠ 5VC
Front bumper side bracket @\$65.00	2	necessary	130.00	130.00 /
Front bumper headlamp nozzzle cover @\$45.00	2	intact	90.00	0.00
Front bumper fog lamp cover @\$102.50	2	intact	205.00	0.00
Front radiator grille	1	cracked	577.00	577.00 /
Front radiator grile outer chrome moulding	1	broken	324.50	324.50 /
Front bumper lower grille (mesh)	1	damaged	241.00	241.00
Headlamp @\$2250.00 166	2	damaged	4500.00	4500.00
Front support panel assy	1	bent-in/warped	856.10	856.10 664 /
Front fender @\$795.00	2	repair.respray	1590.00	0.00
Bonnet lock	1	damaged	155.00	155.00 X SVC
Aircon condenser sid air guide @\$98.00	2	damaged	196.00	196.00 /
Front sensor	1	malfunction	412.00	412.00 X SVC
Front distance sensor control module	1	damaged	557.80	557.80 ⊀ SVC
Front distance sensor bracket	1	damaged	123.15	123.15 L SK

Subsidiaries of Impact Analysis Consultant:

Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd

[•] IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd www.iaconsultingsg.com

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

Our reference

20-06-9263

Date

15/6/2020

Front coolant sensor	1	malfunction _	288.70	288.70 X SVC
	Sub- Total costs		13867.15	11982.15
	Percentage discount :	10%	1386.72	1198.22
	Sub-Total costs	for parts =	12480.44	10783.94
Special Nett Items:				
Front bumper clips	set	necessary	55.00	55.00 30/
Front number plate (special type)	1	bent	100.00	100.00 🕇
Front coolant (top up)	1	necessary	50.00	50.00 30 /
Front support panel sealant	1	necessary	30.00	30.00 × SVC
	Sub-Total costs	for parts =	235.00	235.00
Parts Repair				
*	*	*	0.00	0.00
	Sub- Total	costs	0.00	0.00
	Total costs for parts		12715.44	11018.94

Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd

[■] IA Accounting & Consultancy Pte Ltd ■ Infoknights International Services (Philippines) ■ IABN Pte Ltd www.iaconsultingsg.com



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

20-06-9263

Date

15/6/2020

Page

3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total	
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	25	\$ 1,125.00	700
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	els. Job allowance. Paint / material. Sub-contract work.		\$ 1,150.00	1000
Apply rust proofing on the adjacent panels.	Sub-con	tract work.	\$ 100.00	30
Wiring and bulb checking	\$ 45.00	0.5	\$ 22.50	X
Remove / replace aircon condenser and refill aircon gas	\$ 45.00	2.5	\$ 112.50	/
Remove and replace front distance sensor & conduct distance safety setting.	\$ 45.00	1.7	\$ 76.50	5 0
	Total la	abour cost	\$ 2,586.50	

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.





No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

Our reference

20-06-9263

Date

15/6/2020

Section C: Summary Table of Total Repair Cost

Description		Cost	
Damaged Parts Assessment (See section A)		\$11,018.94	
Further discount	20%	\$2,203.79	
Recommended cost of parts replacement		\$8,815.15	(1)
Labour Cost Calculation (See section B)		\$2,586.50	(2)
Total Repair Cost (Round off to hundred)		\$11,400.00	(1) + (2)

We would recommend a sum of	\$11,400.00	and	9	working days for repair
No further items will be approved v	vithout our expresse	d written agreeme	ent. Any signi	ficant additional
items will be subject to a suppleme	ntary report.			

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma. Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

SPRING- Recognised Certification for Management Consultants

Subsidiaries of Impact Analysis Consultant:

Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd







































































































































