

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005882/KGS3Q2
Date: 26/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900115294
Claimant Vehicle No :	SKV6223M	Insured Vehicle No :	SMM5968C
Date of Loss:	10/05/2021	Nature of Claim:	TP
		Claim No:	0593152501SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV6223M	Engine No:	26492080074795
Make & Model:	MERCEDES-BENZ GLC300, 2.0 4MATIC (R18 LED) (A)	Chassis No:	W1N2533842F838838
Reg. Date:	29/09/2020 (Man. Year: 2020)	Odometer:	12746 km
Colour:	Metallic Red		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/50 R19	Rear Tyre Size:	255/50 R19
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,052.80	3,337.80	3,715.00	52.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,150.00	1,360.00	54.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,562.80	4,487.80	5,075.00	53.07
+ GST 7.00/7.00% (S\$)	669.40	314.15	355.25	53.07

Nett Amount (\$\$)	10,232.20	4,801.95	5,430.25	53.07
+ Loss of Use (4.0 x S\$80.00/day) (\$\$)		320.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		5,129.40		

INSPECTION

Date of Assignment: 17/05/2021

Date Inspected: 18/05/2021

Inspected At:

Tong Luck Auto Pte Ltd (HQ)
 160 Sin Ming Drive, #07-01 Sin Ming AutoCity
 Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR -LH	Bent	2,980.00 FN	*2,980.00 FN
2	1		*REAR DOOR WEATHERSTRIP -LH	Necessary	328.00 FN	*328.00 FN
3	1		*REAR DOOR TRIMBOARD RIVETS -LH	Necessary	162.00 FS	*60.00 FS
4	1		*REAR FENDER -LH	Repair	3,970.00 FN	*- FN
5	1		*REAR WHEEL ARCH GARNISH LH	Cut	244.00 FN	*244.00 FN
6	10		*REAR WHEEL ARCH GARNISH CLIPS- LH	Necessary	90.00 FN	*90.00 FN
7	1		*REAR TRIANGLE GLASS SEALANT-LH	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	7,814.00	3,702.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	761.20	364.20
Total Parts (\$\$)	7,052.80	3,337.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT LH REAR TAINGLE GLASS	New	60.00	0.00
2	TO TRANSFER LH REAR DAMAGED DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR	New	150.00	80.00
3	TO REMOVE AND REFIT LH REAR FENDER INTERIOR GARNISHES AND TRIMBPARD TO FACILITATE THE REPAIRS	New	180.00	100.00
4	TO PANEL BEAT AND STRIAGHTEN LH REAR FENDER INNER PANEL ,LH REAR CHASSIS FRAME ,TO CUT AND WELD LH REAR FENDER ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY ,TO REFIT AND ADJUST THE SAME	New	1,000.00	500.00
5	TO PUTTY AND SPRAY ON AFFECTED AREAS	New	1,000.00	440.00
6	TO APPLY RUST PROOFING ON REPLACEMENT AND REPAIRED PANELS	New	120.00	30.00
Gross Labour Cost (\$\$)			2,510.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >