

Our reference:

21-7236

Date:

21/1/2021

c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #03-46 Premier@KB Singapore 415875

Dear Sirs

RE:

Road Traffic Accident on 9/1/2021

Liang Shunguan

In accordance with your instructions received in this office or

12/1/2021 , we made arr

, we made arrangements to

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

examine the vehicle on

12/1/2021

at above-mentioned address. The following data was

recorded:

#### Vehicle details

Make	Toyota	Registration	SJT1365S	
Model	Vios E	Chassis	MR053HY9305131182	
Colour	Blue	Gearbox	Auto	
Odometer	230662km	Paintwork Good		
Steering	In order	Brakes	In order	
Condition	Good	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		

### **Tyre Depths**

Front left	205/45ZR16	85% Tourador	
Front right	205/45ZR16	85% Tourador	
Rear left	205/45ZR16	85% Tourador	
Rear right	205/45ZR16	85% Tourador	

Status	REPAIRABLE	
Magnitude	Medium	
Legal status	Unroadworthy	

#### Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$2,000.00 and 4 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd ◆ Impact Analysis Academy Pte Ltd ◆ IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
   Infoknights International Services (Philippines)
   IABN Pte Ltd
  www.iaconsultingsg.com



Our reference

21-7236

Date

21/1/2021

Page

2

# Section A: Damaged Parts Assessment

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

		en a Constitution of the C		
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items :				
Front bumper	1	holder damaged	485.20	485.20
Front bumper side retainer rh	1	damaged	56.20	56.20
Front bumper fog lamp ring rh	1	refix	98.40	0.00
Front fender rh	1	bent	468.25	468.25
Front fender cowling rh	1	damaged	122.50	122.50
Front fender emblem 'VVTi' rh	1	necessary	36.50	36.50
Front head lamp rh	1	defaced	523.50	523.50
VS.31.35 S. 12 V .	Sub- Tota	Sub- Total cost		1692.15
	Percentage discount :	25%	447.64	423.04
	Sub-Total cost	s for parts	1342.91	1269.11
Special Nett Items:				
Front bumper clips	set	necessary	45.00	45.00
Front tyre rim rh	1	refinish	550.00	0.00
	s for parts	595.00	45.00	
Parts Repair				
*	*	*	0.00	0.00
	Sub- Tota	l costs	0.00	0.00
	Total costs for parts			1314.11

Subsidiaries of Impact Analysis Consultant:

 <sup>■</sup> Impact Analysis Consulting Pte Ltd ■ Impact Analysis Academy Pte Ltd ■ IA Racking Solutions Pte Ltd

 <sup>■</sup> IA Accounting & Consultancy Pte Ltd
 ■ Infoknights International Services (Philippines)
 ■ IABN Pte Ltd
 www.iaconsultingsg.com



Our reference

21-7236

Date

21/1/2021

Page

3

## Section B: Labour Cost Calculation

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

	Hourly rate		Manhr. Req.	Total	
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$	45.00	15	\$	675.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$	500.00	
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$	20.00	
Specialist charges - Wheel alignment		-	-	\$	60.00
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$	45.00	0.8	\$	36.00
		Total la	bour cost	\$	1,291.00

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

Subsidiaries of Impact Analysis Consultant:

<sup>●</sup> Impact Analysis Consulting Pte Ltd ● Impact Analysis Academy Pte Ltd ● IA Racking Solutions Pte Ltd

<sup>•</sup> IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd www.iaconsultingsg.com



Our reference

21-7236

Date

21/1/2021

# Section C: Summary Table of Total Repair Cost

Description		Cost		
Damaged Parts Assessment (See section A)		\$1,314.11		
Labour Cost Calculation (See section B) Total cost		\$1,291.00 \$2,605.11		
Total Repair Cost		\$2,000.00		

We would recommend a sum of	\$2,000.00	and	4	working days for repair.
No further items will be approved	without our expr	essed written agre	ement. Any sign	nificant additional
items will be subject to a suppleme	entary report.			

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma, Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

Enterprise Singapore - Recognised Certification for Management Consultants

IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
   Infoknights International Services (Philippines)
   IABN Pte Ltd www.iaconsultingsg.com

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171





















































































