
REF: CS3/A14 210055 70/BVf3-1 ASSIGNMENT

Varon

From: Date: 7/5/2021 . Estimated Cost:	Veh No: SLR 430E Yr Regn: 3-8/7/2017 Type: M:Cal / M.Cycle / Bus / Ven / Lorry / Text / Prime Mover/
OD / TH/ WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer of
To Inspect Vehicle No: SLR 430E	Make: Horse Swittle 159 cc 1496
at Workshop m/s Yap notor	Colour Black A/C: Insured / Std / NI / NA
or DET Sin Mingladest Sect C # 01-80	Sp.Reading 67638 T/Radio: Insured / Std / NI / NA
Insured SLQ 7432J	Eng/No: LIS B3539005
Policy No. 1700030505	C/No. <+K8/807687
Claims No. 5323674857SG	Gen. Cond: Good / Fair / Poor / Burnt
Sum insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: lander / Jammed / Leaked / Burnt or
Make of Veh;	Modi: Nii S/Rim / STD A/Rim or
	Tyre Size: F: 195/55/15 Habibad
(Policy Condition)	R: 195/55/16 BS
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of Inspection.	TOYO / YOKO or
24 - Mary Value (2 a 2 C)	Front Rear
Ball or Market Value: 60,008 > Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
DATE PRODUCTION OF THE	L/Bal. 5 mm L/Bal. 5 mm
OIN TTN OWN	D.O.A. 18/4/2021 D.O.L. 7/5/2011
a Vol. Vee or No	Survey held at Hap Noty
Luin dunt.	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS WP	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
12/7/21 Submit LS \$2400 (Red 2600, 52	
Photos taken on 7/5/2021 @	J:64:20pm
Resurry shotos taken and 10/5/2	201 (3/1.26,22)
PV 35,682/2	Tora bil
NV 243181x	815/204
	Days Of Repair: 5
	Rosurvoy No. of Trip: Survey Fee:
1)	Transportation:
n 12/7/21-Typist Add Fee	
a 12/7/21-Typist Add Fee	Interview (\$) Pisstos
Report Format : TP	Toch. Invs (\$) Ohers
Lump Sum H.B.I: (\$ 2400)	Weekend (\$)
Lump dam (12-100	TOTAL
	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE



Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

Our reference:

21-7751

Date:

15/5/2021

c/o Yap Motor Service Pte Ltd Blk 7 Sin Ming Industrial East Sector C #01-82 Singapore 575642

Dear Sirs

RE:

Road Traffic Accident on 18/4/2021

Seah Tian Sze

In accordance with your instructions received in this office or

6/5/2021

, we made arrangements to

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

examine the vehicle on

6/5/2021

at above-mentioned address. The following data was

recorded:

Vehicle details


Make	Honda	Registration	SLR430E	
Model	Shuttle	Chassis	GK81007687	
Colour	Black	Gearbox	Auto	
Odometer	67638km	Paintwork	Good	
Steering	In order	Brakes	In order	
Condition	Good			

Tyre Depths

Front left 195/55R15		85% Habilead
Front right	195/55R15	85% Habilead
Rear left	195/55R15	80% Bridgestone
Rear right	195/55R15	80% Bridgestone

Status	REPAIRABLE			
Magnitude	Medium			
Legal status	Unroadworthy			

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$5,000.00 and 5 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Ptc Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- ◆ IA Accounting & Consultancy Pte Ltd
 ◆ Infoknights International Services (Philippines)
 ◆ IABN Pte Ltd
 www.iaconsultingsg.com



Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

Our reference

21-7751

Date

15/5/2021

Page

2

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

> 217 SLR 430

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment	
List Items:					
Rear door Ih	1	repair.respray	1025.60	0.00	
Rear fender Ih	1	crushed	996.80	✓ 996.80 ;	DDV V
Rear fender inner shield Ih	1	torn	145.10	145.10	DISV 110.00/
Rear bumper	1	holder torn	854.10	854.10	BRV 580.30
Rear bumper side retainer Ih	1	damaged.nec	36.10	36.10	NEC \30.00/
Rear shock absorber Ih	1	bent	265.30	265.30	
Rear wheel bearing Ih	and the consequences	necessary	165.10		JM/ 14.00/
Rear axle	1	bent	1325.80	1325.80	NDX
	Sub- Total	costs	4813.90	3788.30	1826 - 80
Pe	ercentage discount :	20%	962.78	757.66	3 65 . 36
	Sub-Total costs	for parts	3851.12	3030.64	1461.44
Special Nett Items:					
Rear tyre lh	1	abraded	250.00	200.00	NDX
Rear tyre rim lh	1	damaged	566.00	566.00	CUT / 300.00
Rear fender sealant Ih	1	necessary	30.00	30.00 6	JEL V
	Sub-Total costs	for parts =	846.00	796.00	330.00
Parts Repair					
			0.00	0.00	
	Sub- Total	costs	0.00	0.00	
	Total costs fo	r parts =	4697.12	3826.64	

Subsidiaries of Impact Analysis Consultant:


[■] Impact Analysis Consulting Pte Ltd ■ Impact Analysis Academy Pte Ltd ● IA Racking Solutions Pte Ltd

■ Impact Analysis Consulting Pte Ltd

■ Impact Analysis Academy Pte Ltd

[■] IA Accounting & Consultancy Pte Ltd → Infoknights International Services (Philippines) → IABN Pte Ltd

www.iaconsultingsg.com



Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

Our reference

21-7751

Date

15/5/2021

Page

3

Section B: Labour Cost Calculation

To dismostly cools and the last state of the las	Hourly rate	Manhr. Req.	Total		
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	18	\$	810:00	600-00,
Putty & Spray painting to adjacent panels. Job allowance. Paint / material (3 panels)	Sub-contract work.		\$	700.00	400.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$	20.00	
Remove and replace rear undercarriage works Ih	\$ 45.00	5	\$	225.00	120.00
Remove and refix inner trim to facilitate the replacment of rear fender lh	\$ 45.00	1.5	\$	67.50	45.00
Remove and refix fuel tank, pipes to facilitate the repair works	\$ 45.00	1.5	\$	-67.50	45.00/
Conduct water leak test for rear portion associated repair works	\$ 45.00	1	\$	45.00	NNX
Wiring and bulb checking	\$ 45.00	0.8	\$	36.00	NNX
	Total la	bour cost	\$:	1,971.00	Mark III

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and In-house@ IA Research Guidelines respectively.

1230.00

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

cor 4/s 2150/2 Repair days 5 Parts 1,461.44 Labour 1230.00 2691.44 @2090 538.29 2153.15

7atim Min_ 12/7/2021

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd