

ASS. REC. BY:

REF: TMI /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop n/y's Trans Cab

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____
(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 40,750

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S11D 78k Yr Regn: 08, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude C.C. 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 371207 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL15AUC 283326

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Sailun

Front

Rear

R/Bal. 8 mm

R/Bal. 7 mm

L/Bal. 8 mm

L/Bal. 7 mm

D.O.A. 13/10/21

D.O.I. 14/10/2021

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

FR OK

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>CAA not ready, get video.</u>
	<u>11 Rm @ 2250</u>

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

1)

: Final Report

Date/Time, File Return to?

Transportation: _____
S - RS. \$ _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Fuel: _____

Others: _____

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD78K

AAD2110-

*Not Authored
11 Sep @ 2250h*

Vehicle No.:
Chassis No.:
Vehicle Make: **14 OCT 2021**
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD78K
VF1ABL15AUC283326
RENAULT
LATITUDE
13/10/2021
TOKIO
31/08/2016

PART	LIST
1 BUMPER COVER FRT	\$ Bu 747.20 ✓
1 BUMPER ABSORBER FRT	\$ In 394.68 X
1 BUMPER BEAM FRT	\$ N 663.70 X
1 BUMPER BRACKET KIT FRT RH	\$ Dri 101.40 ✓
1 HEADLAMP RH	\$ My car 743.60 ✓
1 WIPER RESERVOIR	\$ Bu 179.60 X
1 FENDER PANEL FRT RH	\$ Bu 437.10 ✓
1 WHEELARCH FRT RH	\$ In 191.40 X
	\$ 3,267.28
	10% \$ 326.73
	\$ 2,940.55

Special Nett	
1SET BUMPER BRACKET CTR CLIP	\$ na na 33.00 X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$ na 10.00 X
1SET BUMPER RETAINER RH CLIP RR	\$ na 20.00 X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$ na 10.00 X
1SET BUMPER RETAINER CLIP LH RR	\$ na 20.00 X
1 BUMPER CLIP FRT	\$ NRC 85.00 ✓
1 FENDER CLIP	\$ in 65.00 X
1 FENDER LINER CLIP	\$ na 60.00 X
TOTAL	\$ 303.00
TOTAL PARTS	\$ 3,243.55

LABOUR

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *440*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD78K

AAD2110-

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	4000
To Rust-Proofing Of The Affected Areas.	\$	170.00	300
To reinstall rear bumper parking sensor.	\$	na 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na 170.00	X
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	na 170.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	200

TOTAL \$ 7,580.00

Over All Total \$ 13,764.10

(LUMP SUM)

Repair Days

10 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey - s on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: