

Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800

Hotline: 6385 1171

Our reference:

21-8357

Date:

8/12/2021

c/o Triple-T Automobile Blk 6 Defu Lane 10 #01-556 Singapore 539187

examine the vehicle on

Dear Sirs

RE:

Road Traffic Accident on 12-10-2021

H Klassic Design Pte Ltd

In accordance with your instructions received in this office on

29-11-2021 , we made arrangements to

29-11-2021 at above-mentioned address. The following data was

recorded:

Vehicle details

Make	Fiat	Registration	GBG8690U
Model	Doblo	Chassis	ZFA26300006H31333
Colour	Grey	Gearbox	Auto
Odometer	120376km	Paintwork	Good
Steering	Good	Brakes	Good
Condition	Good		*

Tyre Depths

Front left	195/60R16	85% Bridgestone
Front right	195/60R16	85% Bridgestone
Rear left	205/60R16	85% Habilead
Rear right	205/60R16	85% Habilead

Status	REPAIRABLE Medium		
Magnitude			
Legal status	Unroadworthy		

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$4,000.00 and 5 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
 Infoknights International Services (Philippines)
 IABN Pte Ltd www.iaconsultingsg.com

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171**

Our reference

21-8357

Date

8/12/2021

Page

2

Section A: Damaged Parts Assessment

occion,	Damagea	1 al (3 A33C33111	Circ	
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items:				
Rear bumper	1	torn.deformed	600.50	600.50
Rear bumper reinforcement	1	inconsistent	683.48	0.00
Rear bumper side retainer Ih	1	damaged.nec	65.10	65.10
Tail lamp Ih	1	cracked	345.40	345.40
Rear fender Ih	1	crushed	1589.00	1589.00
Sliding door lh	1	repair.respray	2451.00	0.00
Tail lamp panel lh	1	bent	172.10	172.10
Rear door hinge Ih	1	damaged	65.80	65.80
Rear door Ih	1	repair.respray	1758.00	0.00
Rear door emblem 'Doblo max" Ih	1	necessary	79.80	79.80
Rear door "90 multijet 2" lh	1	necessary	64.10	64.10
Rear end panel	1	repair	612.00	0.00
	Sub- Total	costs	8486.28	2981.80
Percent	age discount :	10%	848.63	298.18
	Sub-Total costs	for parts =	7637.65	2683.62
Special Nett Items:				
Rear bumper reverse sensor	set	refix	250.00	0.00
Rear fender sealant Ih	1	necessary	40.00	40.00
Rear door sticker 70km/h lh	1	necessary	15.00	15.00
Rear bumper clips	10	necessary	60.00	60.00
	Sub-Total costs	for parts =	365.00	115.00
Parts Repair				
*	*	*	0.00	0.00
	Sub- Total costs		0.00	0.00
	Total costs fo	r parts	8002.65	2798.62

Subsidiaries of Impact Analysis Consultant:

[■] Impact Analysis Consulting Pte Ltd ■ Impact Analysis Academy Pte Ltd ● IA Racking Solutions Pte Ltd

■ Impact Analysis Academy Pte Ltd ■ Impact Analysis Academy Pte Ltd ■ IA Racking Solutions Pte Ltd

■ Impact Analysis Academy Pte Ltd ■ Imp

[•] IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd www.iaconsultingsg.com

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800

Hotline: 6385 1171

Our reference

21-8357

Date

8/12/2021

Page

3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	17	\$ 765.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material. (rear fender lh, sliding door lh, rear bumper, rear door lh)		tract work.	\$ 850.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 50.00
Conduct water leak test for rear portion associated repair works	\$ 45.00	1	\$ 45.00
Remove and refix rear reverse sensor & conduct distance safety setting	\$ 45.00	1.7	\$ 76.50
Wiring and bulb checking	\$ 45.00	0.8	\$ 36.00
	Total la	bour cost	\$ 1,822.50

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800

Hotline: 6385 1171

Our reference

21-8357

Date

8/12/2021

Section C: Summary Table of Total Repair Cost

CANCELL CONTRACTOR OF THE PARTY	CONTRACTOR OF THE PARTY OF THE PARTY.		
Description Damaged Parts Assessment (See section A)		Cost	
		\$2,798.62	
er nt	20%	\$559.72	
Recommended cost of parts		\$2,238.90	(1)
Labour Cost Calculation (See section B)		\$1,822.50	(2)
tal Repa		\$4,000.00	(1) + (2)
(Round off to hundred)		34,000.00	(1) + (2)

We would recommend a sum of	\$4,000.00	and	5	working days for repair.
No further items will be approved w	ithout our express	sed written agre	eement. Any	 significant additional
items will be subject to a supplement	ntary report			

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

Enterprise Singapore - Recognised Certification for Management Consultants

IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd Infoknights International Services (Philippines) IABN Pte Ltd www.iaconsultingsg.com













































































































