

ASS. REC. BY:

Kenneth

REF:

LAW/ 22001145/Kt

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S114 58126Yr Regn: 11, 16Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Honda

c.c

1496Colour: M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading: 110387

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU31218255Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD / Rlm or

Tyre Size: F: 215/80R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 8 mmL/Bal. 6 mmL/Bal. 8 mmD.O.A. 1/12D.O.I. 10/3/2022

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) S + RS \$

) Fuel \$

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

# PAR Automotive Consultancy

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 64531173, Fax : 64536131.  
Consultants: Vehicle appraisal & inspection, accident investigation, expert witness

Regn. No: 52986974L

Report No: 0046-20-HLm

30 October 2020

## ACCIDENT VEHICLE SURVEY REPORT

Tan Shen Ching (Chen Xianjun)  
c/o 160 Sin Ming Drive #05-17 Sin Ming Autocity  
Singapore 575722

### VEHICLE INFORMATION:

|                  |                                                 |                                |            |
|------------------|-------------------------------------------------|--------------------------------|------------|
| Vehicle Reg No.: | SLH5812G                                        | Odometer:                      | 093238km   |
| Make & Model:    | Honda Vezel Hybrid 1.5X A                       | Colour:                        | White      |
| Chassis number:  | RU31218255                                      | Date of accident:              | 12/08/2020 |
| Year of Regn.:   | 10/11/2016                                      | Date inspected:                | 13/08/2020 |
| Repairer at:     | Hiap Lek Automobile Trading                     | Date inspected (After Repair): | 25/08/2020 |
|                  | c/o 160 Sin Ming Drive #05-17 Sin Ming Autocity |                                |            |
|                  | Singapore 575722                                |                                |            |

### STATIC CHECKS, where applicable:

|                     |             |
|---------------------|-------------|
| Steering :          | serviceable |
| Footbrake :         | serviceable |
| Handbrake :         | serviceable |
| Paintwork :         | Good        |
| General condition : | Good        |

### TIRE CONDITION:

|        | <u>LH / Make</u> | <u>RH / Make</u> | <u>Size</u> |
|--------|------------------|------------------|-------------|
| Front: | 5mm/Dunlop       | 5mm/Dunlop       | 215/60R16   |
| Rear:  | 5mm/Dunlop       | 5mm/Dunlop       | 215/60R16   |

### POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front LH portion.  
Please see details as described in the Annex for parts and labour.

### REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

# PAR Automotive Consultancy

ANNEX A: Page 1  
Report No: 0046-20-HLm-SLH5812G

## Parts and Labour Assessment

Report No: 0046-20-HLm

Vehicle No: SLH5812G

| Description of part                    | Qty           | Condition as inspected | Repairer's estimate | Our adjustment     |
|----------------------------------------|---------------|------------------------|---------------------|--------------------|
| Front bonnet                           | 1             | buckled                | 1,020.00            | 1,020.00           |
| Front bonnet side moulding RH/LH       | 2             | necessary              | 75.00               | 75.00              |
| Front bonnet centre moulding           | 1             | necessary              | 85.00               | 85.00              |
| Front bonnet insulator clip            | 10            | necessary              | 35.00               | <i>NA</i> 35.00 X  |
| Front bonnet hinge                     | 2             | bent                   | 100.00              | 100.00             |
| Front bonnet lock                      | 1             | bent                   | 128.00              | <i>N</i> 128.00 X  |
| Front bonnet lock bracket              | 1             | bent                   | 76.00               | 76.00              |
| Front radiator grille                  | 1             | fractured              | 270.00              | 270.00             |
| Front radiator grille garnish          | 1             | fractured              | 285.00              | 285.00             |
| Front radiator grille emblem 'H' logo  | 1             | necessary              | 28.20               | 28.20              |
| Front radiator grille support bracket  | 1             | bent                   | 52.00               | <i>N</i> 52.00 X   |
| Front head lamp (HID) RH/LH            | <i>1839</i> 2 | fractured <i>N/S</i>   | 3,718.80            | 3,718.80 <i>CH</i> |
| Front head lamp lower bracket RH/LH    | 2             | bent                   | 70.00               | 70.00 <i>CH</i>    |
| Front head lamp clip RH/LH             | 6             | necessary              | 23.40               | 23.40 <i>CH</i>    |
| Front bumper                           | 1             | deformed               | 927.50              | 927.50             |
| Front bumper tow cover                 | 1             | deformed               | 20.00               | 20.00              |
| Front bumper LED daylight LH           | 1             | fractured              | 587.10              | 587.10 <i>180m</i> |
| Front bumper fog lamp cover LH         | 1             | deformed               | 45.00               | 45.00              |
| Front bumper fog lamp LH               | 1             | fractured              | 327.70              | 327.70             |
| Front bumper lower grille              | 1             | fractured              | 150.00              | 150.00             |
| Front bumper lower moulding            | 1             | deformed               | 146.30              | 146.30             |
| Front bumper lower diffuser            | 1             | deformed               | 195.50              | 195.50             |
| Front bumper side retainer RH/LH       | 2             | necessary              | 46.00               | 46.00 <i>CH</i>    |
| Front bumper inner garnish             | <i>CH</i> 2   | deformed               | 70.00               | 70.00 <i>CH</i>    |
| Front bumper reinforcement             | 1             | bent                   | 321.00              | 321.00             |
| Front fender LH                        | 1             | buckled                | 580.00              | 580.00             |
| Front fender emblem 'Hybrid' RH        | 1             | necessary              | 42.50               | 42.50              |
| Front fender wheel arch garnish LH     | 1             | deformed               | 153.00              | 153.00             |
| Front support panel                    | 1             | bent                   | 520.00              | <i>N</i> 520.00 X  |
| Horn                                   | 2             | distortion             | <i>UB</i> 110.00    | <i>Mc</i> 110.00 X |
| Radar sensor                           | 1             | shorted                | <i>Mc</i> 2,887.00  | 2,887.00 X         |
| Radar sensor bracket                   | 1             | bent                   | 45.60               | <i>N</i> 45.60 X   |
| Air intake duct                        | 1             | deformed               | <i>UB</i> 65.00     | <i>Mc</i> 65.00 X  |
| Air con condenser                      | 1             | bent                   | <i>UB</i> 750.00    | <i>Mc</i> 750.00 X |
| Air con condenser side air guide RH/LH | 2             | deformed               | <i>UB</i> 50.00     | <i>N2</i> 50.00 X  |
| Air con fan blade                      | 1             | warped                 | <i>UB</i> 58.00     | <i>N2</i> 58.00 X  |

# PAR Automotive Consultancy

Annex A: Page 2  
Report No: 0046-20-HLm-SLH5812G

|                                    |   |           |            |           |     |
|------------------------------------|---|-----------|------------|-----------|-----|
| Air con fan motor                  | 1 | shorted   | N/C 298.00 | 298.00    | X   |
| Radiator assy                      | 1 | bent      | ↖ 1,250.00 | 1,250.00  | X   |
| Radiator top mounting              | 2 | bent      | ↖ 18.00    | 18.00     | X   |
| Radiator fan cowling               | 1 | deformed  | ↖ 125.00   | 125.00    | X   |
| Radiator fan blade                 | 1 | warped    | ↖ 60.00    | 60.00     | X   |
| Radiator fan motor                 | 1 | shorted   | ↖ 298.00   | 298.00    | X   |
| Radiator spare tank                | 1 | deformed  | ↖ 60.00    | 60.00     | X   |
| Front chassis LH                   | 1 | repair    | 514.00     | 0.00      |     |
| Subtotal before discount           |   |           | 16,686.60  | 16,172.60 |     |
| Percentage discount 0% and 20%     |   |           | 0.00       | 3,234.52  |     |
| Sub-total 1                        |   |           | 16,686.60  | 12,938.08 |     |
| Front bumper chrome cover trim set | 1 | fractured | 250.00     | 250.00    | 150 |
| Front bumper clip set              | 1 | necessary | 35.00      | 35.00     |     |
| Front tyre LH                      | 1 | abraded   | N/C 350.00 | 350.00    | X   |
| Subtotal before discount           |   |           | 635.00     | 635.00    |     |
| Percentage discount 0% and 0%      |   |           | 0.00       | 0.00      |     |
| Sub-total 2                        |   |           | 635.00     | 635.00    |     |
| Parts-total                        |   |           | 17,321.60  | 13,573.08 |     |

## LABOUR

|                                                                                                                                                                                 |           |           |     |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------|-----|
| 1. To straighten and panel beating LH front fender inner panel, LH front door pillar and front frame members. To cut/weld front support panel. To remove and refit above parts. | 1,500.00  | 1,250.00  | 750 |
| 2. To putty, re-spray painting and polish affected areas.                                                                                                                       | 1,250.00  | 1,000.00  | 800 |
| 3. To check and rectify wiring system.                                                                                                                                          | 80.00     | 50.00     | 20  |
| 4. To rust proof affected areas.                                                                                                                                                | 120.00    | 60.00     | 30  |
| 5. To remove, refit air-con condenser and recharge air con gas.                                                                                                                 | 150.00    | 120.00    | X   |
| 6. To remove, refit front LH tyre/sport rim and balancing.                                                                                                                      | 50.00     | 40.00     | X   |
| 7. To conduct electronic wheel alignment test.                                                                                                                                  | 180.00    | 150.00    | X   |
| Labour total                                                                                                                                                                    | 3,330.00  | 2,670.00  |     |
| Parts & Labour total                                                                                                                                                            | 20,651.60 | 16,243.08 |     |

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is :  
and the recommended number of working days for the repairs is :

\$12,900.00

8  
6 days

B J Loi (I Eng. MIMI, AIRTE)  
Automotive Appraiser