

Your Ref: MTS2022D0000625
Our Ref : CI/III22001252/P

15th February 2022

M/s India International Insurance Pte. Ltd.

64 Cecil Street #04, #05
IOB Building
Singapore 049711

**TECHNICAL INVESTIGATION REPORT OF WARRANTY CLAIM INVOLVING
THE INSURED VEHICLE SDK 1212T ON 9th February 2022**

1. We refer to your letter dated 9th February 2022 and the instructions therein.
2. Our analysis, comments and opinions with respect to the cause of abnormalities to the insured vehicle SDK 1212T (herein referred to as “**Insured Vehicle**”) are set out below.

Inspection of the Insured Vehicle

3. The Insured Vehicle was physically inspected on 13th January 2022 at the premises of AutoSprint Pte Ltd located at 24 Leng Kee Rd, #07-01, Singapore 159096
4. A physical inspection was carried out to the Insured Vehicle where the following general information was recorded:-

Vehicle Registration No.	: SDK 1212T
Make / Model	: MERCEDES BENZ S500L
Chassis No	: W1K2231632A015015
Year of Registration	: JUNE 2021
Mileage	: 12,303KM

5. The complaint on the Insured Vehicle was noted be an error and warning message light regarding the electronic Advanced Driver Assistance Systems (ADAS) for the steering rack and pinion system. There is a recommendation by the workshop to replace the steering rack and pinion assembly. The vehicle was observed to be unaffected by any signs of accident.

6. Prior to our inspection, the workshop had informed us that they had already conducted check of the components and the electrical systems of the steering rack and pinion system and visually all components was intact without any damage and however, the issue was still present during our inspection of the Insured Vehicle. See photos 1 – 9 below.



Photo 1 shows the mileage of the Insured Vehicle recorded at the time inspection at 12,303KM



Photo 2 shows the general view of the front portion of the Insured Vehicle at the time of our inspection. The Insured Vehicle is observed to be unaffected by any signs of accident.



Photo 3 shows the general view of the engine portion of the Insured Vehicle at the time of our inspection. The engine compartment is observed to be unaffected by any signs of accident.



Photo 4 shows the chassis number of the Insured Vehicle at the time of our inspection.



Photo 5 shows the general view of the engine underside portion of the Insured Vehicle at the time of our inspection. The engine underside compartment is observed to be unaffected and by any signs of accident.




Photo 6 shows the close up view of the power steering portion of the Insured Vehicle at the time of our inspection. The Electronic Power Steering unit and its steering rack and pinion component is observed to be unaffected and by any signs of accident.




Photo 7 shows the close up view of the front left wheel of the Insured Vehicle at the time of our inspection. The steering tie rod (arrowed) is observed to be unaffected and by any signs of accident.




Photo 8 shows the close up view of the front right wheel of the Insured Vehicle at the time of our inspection. The steering tie rod (arrowed) is observed to be unaffected and by any signs of accident.





Photo 9 shows the conducted ECU diagnosis of the Insured Vehicle at the time of our inspection. There was an electronic error (arrowed) on the Electronic Power Steering of the Insured Vehicle.

XENTRY



Event	Text	Status
Name	First occurrence	Last occurrence
Outside temperature	> 25°C	> 25°C
Brake pedal position	Brake pedal	Brake pedal
Status of engine operation	OPERATED	OPERATED
Ignition signal	No engine start request	No engine start request
Temperature of printed circuit board	Ignition ON	Ignition ON
Status of drivetrain	44.00°C	44.00°C
Supply voltage of control module	Drivetrain	Drivetrain
Vehicle speed	OPERATIONAL	OPERATIONAL
Appl_Slot_Index (Development data)	12.50V	12.50V
Aurix_Die_Temperature (Development data)	Vehicle stationary	Vehicle stationary
Ethernet_Switch_Temp_Flag (Development data)	10	10
PCB_Sensor_DRAM (Development data)	No	No
PCB_Temperature1 (Development data)	No	No
PMIC_Thermal_Shutdown (Development data)	44.00°C	44.00°C
Supply_Voltage1 (Development data)	No	No
Frequency counter	12.50V	12.50V
Main odometer reading	---	1
Number of ignition cycles since the last occurrence of the fault	2112km	2112km
Operating time	---	0
	655986ms	655986ms

S=STORED, A+S=CURRENT and STORED

N68 - Electrical power steering (ES)				-F-
Model	Part number	Supplier	Version	
Hardware	223 901 94 06	Bosch	19/30 000	
Software	223 902 35 12	Bosch	20/35 009	
Boot software	---	---	20/23 000	
Diagnosis identifier	005A04	Control unit variant	EPS223_Development_R12	
Fault	Text	Status		
P063544	The electric power steering has a malfunction. There is an error in the data memory.	S		
Name	First occurrence	Last occurrence		
Battery current	-0.10A	-0.10A		
Temperature of printed circuit board	34.00°C	34.00°C		
Temperature in control unit	-70.00°C	-70.00°C		
Steering wheel Torque	0.00Nm	0.00Nm		
EPS_rack_position	0.00mm	0.00mm		
EPS_rack_position_offset	0.00mm	0.00mm		
EPS_rack_speed	0.00 1/min	0.00 1/min		
Ignition status	Off	Off		
Mon_ID	256	256		
Mon_ID_Flag	Mon_ID	Mon_ID		
Electric motor Torque	0.00Nm	0.00Nm		
Temperature of output stage	32.00°C	32.00°C		
Control unit 'Powertrain' Status	No	No		
Reduction Output level	0.00%	0.00%		
System status (SAR)	0	0		
Steering wheel angle	0.00°	0.00°		
Steering wheel Rotational speed	0.00 1/min	0.00 1/min		
Supply voltage	6.20V	6.20V		
System status	NM_Wait	NM_Wait		
Vehicle speed	0.00km/h	0.00km/h		
Temperature of electric motor	20.00°C	20.00°C		
Reading of odometer	429496736.00km	429496736.00km		
Frequency counter	---	1		
Main odometer reading	429496736.00km	429496736.00km		
Number of ignition cycles since the last occurrence of the fault	---	0		
Operating time	0.008s	0.008s		
C159100	Torque sensor 2 of the power steering system has a malfunction. _	A+S		
Name	First occurrence	Last occurrence		
Battery current	0.00A	-0.10A		
Temperature of printed circuit board	87.00°C	83.00°C		
Temperature in control unit	92.00°C	86.00°C		

06.01.2022 03:22:38

09/2021

W1K2231632A015015

Copyright 2022 Mercedes-Benz AG

223.163

Page '17' of '26'

Photo 10 shows the conducted ECU diagnosis of the Insured Vehicle at the time of our inspection. There was an electronic error (arrowed) on the Electronic Power Steering of the Insured Vehicle.

7. Our checks with both local and international bodies and associations had also revealed that at the time of writing this report, there is no manufacturer recall of similar make and model vehicle as the Insured Vehicle that may possibly be related to abnormalities being originated from the steering system of the Insured Vehicle. See search result from LTA below.



Vehicle Recall Details

* ONLY INFORMATION ON VEHICLE RECALLS SUBMITTED FROM 9 APRIL 2007 IS AVAILABLE

Owner ID Type Singapore NRIC	Owner ID 506A
Vehicle No. SDK1212T ←	Make/Model MERCEDES BENZ/ S500L AMG PREMIUM M-HYBRID AUTO
Engine No.: 25693030262595	Chassis No.: W1K2231632A015015 ←
Recall Details: No Recall Detail records ←	

Save as PDF

OK →

Print

Recall details. Shows the vehicle recall results retrieved from LTA's website. There was no recall on the Insured Vehicle at the time of incident.

Conclusion

8. We did not find any evidence which had suggested that the cause of abnormalities to the Insured Vehicle was due to poor maintenance and/or recurring problem.
9. The recommendation to replace the Power steering rack and pinion assembly at \$6,498.55 is justifiable as all the relevant checks has been conducted.



Sherwin Beh
Technical Investigator



Ang Bryan Tani
AMSOE, AMIRTE, AFF SAE, M.MATAI, AFF.Inst.AEA
Senior Technical Investigator
Technical Investigation & Reconstructionist (SAE-A)

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.