

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647.Singapore 542224

Email: Winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

Our Ref: WG/TP/2021-186
Invoice No: TP/RWAVE/2021-186 Date 02 November 2021
Vehicle No: FBK1759G
Attn: RWAVE SUPERBIKE PTE LTD
Company: RWAVE PTE LTD
Address: 50 Bukit Batok Street 23, Midview Building, #02-25 . Singapore 659578

Invoice

Surveyor Fee:	S\$360
Re-inspection Fee:	S\$80
Transport:	S\$60
Photographs:	S\$60/- (@ \$1 per photo, total 60 photos)
Total:	S\$560

Surveyor:
Signature:
Date:

Winson Goh
02 November 2021



WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : RWAVE SUPERBIKE PTE LTD
C/O RWAVE PTE LTD
50 Bukit Batok Street 23, Midview Building, #02-25
Singapore 659578

Date : 02 November 2021
Our Ref : WG/TP/2021-186

REFERENCE PARTICULARS

Date of Accident : 21 September 2021
Date of Inspection : 24 September 2021

Type of Inspection : Third Party Claim
Date of Re-Inspn : 07 October 2021

VEHICLE PARTICULARS

Registration No : FBK1759G
Make : YAHAMA
Model : FZS1000
Year : 2005

Engine No : N511E004913
Chassis No : JYARN141000004080
Odometer : Na
Colour : Maroon

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front side	: Firelli	120/70ZR17	5 mm
Rear Side	: Firelli	180/55ZR17	5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the left side portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$5,900.00** nett at lump sum basis.(Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Five (05) working days.

Enclosed Sixty (60) photographs depicting damage to the vehicle.

Inspection conducted at : RWAVE PTE LTD
50 Bukit Batok Street 23, Midview Building, #02-25 . Singapore 659578

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a "WITHOUT PREJUDICE BASIS".

VEHICLE NO : FBK1759G
 MODEL : FZS1000

Our Ref : WG/TP/2021-186

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

	QTY	ASSESSED		ORIGINAL	REVISED
	PC/SET	CONDITION		QUOTATION	QUOTATION
A) SPARE PARTS					
01 COVER REAR FENDER	1	CRACKED	\$	521.00	\$ 521.00
02 FENDER REAR	1	NOT NECESSARY	\$	119.00	\$ -
03 FENDER FRONT	1	NOT NECESSARY	\$	114.00	\$ -
04 SIDE COVER 2	1	GRAZED/CRACKED	\$	211.00	\$ 211.00
05 SIDE DAMPER 1	1	NECESSARY	\$	15.00	\$ 15.00
06 SIDE DAMPER 2	1	NECESSARY	\$	12.00	\$ 12.00
07 CASE CHAIN	1	NOT NECESSARY	\$	141.00	\$ -
08 SEAL GUARD	1	NECESSARY	\$	55.00	\$ 55.00
09 SWING ARM	1	GRAZED	\$	890.00	\$ 890.00
10 BODY FRONT UPPER 1	1	CRACKED	\$	542.00	\$ 542.00
11 FRONT BODY UPPER INNER GANRISH LH	1	CRACKED	\$	231.00	\$ 231.00
12 PANEL INNER 1	1	GRAZED /CRACKED	\$	311.00	\$ 311.00
13 PANEL INNER 2	1	GRAZED/CRACKED	\$	214.00	\$ 214.00
14 REAR VIEW MIRROR LH	1	GRAZED	\$	131.00	\$ 131.00
15 FRONT FLASHER LIGHT ASSY RH	1	GRAZED	\$	76.00	\$ 76.00
16 FRONT FLASHER LIGHT ASSY LH	1	GRAZED	\$	76.00	\$ 76.00
17 FRONT HEADLIGHT ASSY	1	NOT NECESSARY	\$	657.00	\$ -
18 LEVER HOLDER ASSY LH	1	GRAZED	\$	119.00	\$ 119.00
19 FOOTREST ASSY LH	1	BENT	\$	212.00	\$ 212.00
20 FOOTREST BRACKET LH	1	BENT	\$	341.00	\$ 341.00
21 FOOTREST ASSY REAR LH	1	BENT	\$	211.00	\$ 211.00
22 FOOTREST ASSY BRACKET REAR LH	1	BENT	\$	192.00	\$ 192.00
23 GEAR SHIFT PEDAL ASSY	1	BENT	\$	214.00	\$ 214.00
24 ENGINE COVER	1	GRAZED	\$	354.00	\$ 354.00
25 RADIATOR COVER LH	1	GRAZED	\$	119.00	\$ 119.00
26 HANDEL BAR	1	BENT	\$	430.00	\$ 430.00
27 BALANCE	1 SET	GRAZED	\$	120.00	\$ 120.00
28 HANDLE GRIP LH	1	GRAZED	\$	101.00	\$ 101.00
29 SLIDER	2	GRAZED	\$	110.00	\$ 110.00
31 FUEL TANK	1	DENTED	\$	832.00	\$ 832.00
			\$	7,671.00	\$ 6,640.00
			Less 10%	\$ 767.10	\$ 664.00
			\$	6,903.90	\$ 5,976.00

B) S/NETT ITEM

32 FRONT NUMBER PLATE	1	NECESSARY	\$	80.00	\$ 60.00
33 COOLANT	1 BOT	NECESSARY	\$	60.00	\$ 50.00
			\$	140.00	\$ 110.00

Parts Total : \$ **7,043.90** \$ **6,086.00**

C) LABOUR CHARGES & MISC

34 REPLACE , REALIGN AND ADJUST ABOVE DAMGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM			\$	600.00	\$ 400.00
35 TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING			\$	380.00	\$ 250.00
36 TO REMOVE/REFIT, STRAIGHTEN FRONT FORK TUDES			\$	180.00	\$ 150.00
37 SPRAY PAINTING			\$	450.00	\$ 380.00
38 TOWING SERVICE			\$	150.00	\$ 120.00
			\$	1,760.00	\$ 1,300.00

Labour Total : \$ **1,760.00** \$ **1,300.00**

Total Parts and Laboure : \$ **8,803.90** \$ **7,386.00**

FINAL LUMP SUM ADJUSTMENT

\$ **5,900.00**

POINT OF IMPACT

The impact was confined to the left side portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **SS\$5,9000.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully
WG APPRAISAL SERVICES



Winson Goh
Automotive Appraiser