

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22005290/EVY3M4
Date: 06/07/2022

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MCF22A00000100
Claimant Vehicle No :	SMP8080C	Insured Vehicle No :	SMM6546E
Date of Loss:	29/05/2022	Nature of Claim:	TP
		Claim No:	DMCF2200080H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP8080C	Engine No:	27091031527836
Make & Model:	MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A)	Chassis No:	WDC1569422J471808
Reg. Date:	23/02/2018 (Man. Year: 2017)	Odometer:	42316 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,253.07	1,866.84	1,386.23	42.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	2,260.00	640.00	22.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,153.07	4,126.84	2,026.23	32.93
+ GST 7.00/7.00% (\$\$)	430.71	288.88	141.83	32.93
Nett Amount (\$\$)	6,583.78	4,415.72	2,168.06	32.93

INSPECTION

Date of Assignment:	02/06/2022	
Date Inspected:	20/06/2022	Inspected At:
Estimated Period of Repair:	3.0 days	

Cycle & Carriage Industries Pte Ltd (Pandan Loop)
 188 Pandan Loop
 Singapore 128378

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jul 2022)

Parts: M1-SUV MERCEDES-BENZ GLA180 URBAN (R18 LED) 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMP8080C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,186.13 FS	*- FS
2	1		*BOTTOM BLACK TRIM BUMPER (BLACK)	Cut	596.27 FS	*596.27 FS
3	1		*REAR BOTTOM TRIM BUMPER (CHROME)	Cut	1,052.97 FS	*1,052.97 FS
4	14		*RIVET	Not Necessary	67.34 FS	*- FS
5	1		*FOOT STEP PLATE (UPPER CHROME)	Necessary	217.60 FS	*217.60 FS
6	1		*LH/BOTTOM BRACKET BUMPER	Not Necessary	66.38 FS	*- FS
7	1		*RH/BOTTOM BRACKET BUMPER	Not Necessary	66.38 FS	*- FS
Total Parts (S\$)					3,253.07	1,866.84

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,440.00	960.00
2	RESPRAY REAR BUMPER	New	960.00	800.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT	New	120.00	120.00
Gross Labour Cost (S\$)			2,900.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >