

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006736/ANY3Q2**Date:** 31/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00134442200

Claimant Vehicle No : SKA2655L **Insured Vehicle No :** SKT6361H

Date of Loss: 14/07/2022 Nature of Claim: TP Claim No: SNM22D204894/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA2655L**

Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZY134241

Reg. Date: 09/02/2011 (Man. Year: 2010) Chassis No: MR053HY9305177855

Colour: Silver Odometer: 212607 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15

Front Left Side: Crucero 6 mm Rear Left Side: Crucero 6 mm

Front Right Side: Crucero 6 mm Rear Right Side: Crucero 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,009.32	5,478.35	5,530.97	50.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,480.00	3,380.00	2,100.00	38.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,489.32	8,858.35	7,630.97	46.28
Approved Total (Overridden) (\$\$)		7,000.00		
Nett Amount (\$\$)	16,489.32	7,000.00	9,489.32	57.55

INSPECTION

Date of Assignment: 20/07/2022

Date Inspected: 15/07/2022 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Oct 2022)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA2655L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Distorted	575.00 FL	*575.00 FL
2	1		*BOOT LID LOGO	Necessary	70.00 FL	*70.00 FL
3	1		*BOOT LID EMBLEM VIOS	Necessary	65.00 FL	*65.00 FL
4	1		*BOOT LID EMBLEM E	Necessary	55.00 FL	*55.00 FL
5	1		*BOOT LID OUTER MOULDING	Cracked	190.00 FL	*190.00 FL
6	2		*BOOT LID NUMBER PLATE LAMP	Not Necessary	84.60 FL	*- FL
7	1		*BOOT LID TOP LOCK	Damaged	155.00 FL	*155.00 FL
8	1		*BOOT LID LOWER LOCK	Not Necessary	25.00 FL	*- FL
9	1		*BOOT LID OUTER KEY LOCK	Not Necessary	163.00 FL	*- FL
10	1		*BOOT LID WEATHERSTRIP	Cut	205.00 FL	*205.00 FL
11	2		*BOOT LID HINGE	Bent	140.00 FL	*140.00 FL
12	1		*REAR BUMPER	Distorted	495.00 FL	*495.00 FL
13	2		*REAR BUMPER REFLECTOR	Cracked	210.00 FL	*210.00 FL
14	2		*REAR BUMPER BRACKET	Bent	178.00 FL	*178.00 FL
15	2		*REAR BUMPER SIDE RETAINER (FRONT)	Not Necessary	210.00 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINER (REAR)	Damaged	110.00 FL	*110.00 FL
17	2		*TAIL LAMP	Cracked	690.00 FL	*690.00 FL
18	1		*TAIL LAMP PANEL	N/S Dented	380.00 FL	*190.00 FL
19	1		*REAR FENDER	N/S Buckled	1,830.80 FL	*915.40 FL
20	1		*REAR FENDER AIR VENT LH	Not Necessary	49.20 FL	*- FL
21	2		*REAR FENDER INNER COWLING	Not Necessary	350.00 FL	*- FL
22	2		*REAR FENDER INNER TRIM	Not Necessary	590.00 FL	*- FL
23	1		*REAR WINDSCREEN MOULDING	Necessary	90.40 FL	*90.40 FL
24	1		*REAR END PANEL	Distorted	439.00 FL	*439.00 FL
25	1		*REAR END PANEL TOP GARNISH	Deformed	230.00 FL	*230.00 FL
26	1		*REAR FLOORPANEL TOP BOARD	Torn	175.00 FL	*175.00 FL
27	2		*REAR FLOORPANEL TOP SPONGE (SIDE)	Deformed	550.00 FL	*550.00 FL
28	1		*REAR FLOORPANEL TOP SPONGE (INNER)	Not Necessary	220.10 FL	*- FL
29	1		*CENTER EXHAUST	Not Necessary	3,100.00 FL	*- FL
30	1		*CENTER EXHAUST INSULATOR	Not Necessary	95.00 FL	*- FL
31	1		*SET CENTER EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
32	4		*REAR EXHAUST MOUNTING	Not Necessary	180.00 FL	*- FL
33	1		*SET REAR EXHAUST GASKET	Necessary	60.00 FL	*60.00 FL
34	1		*REAR EXHAUST INSULATOR	Not Necessary	89.00 FL	*- FL
35	1		*REAR EXHAUST PIPE WITH BOX	Bent	690.00 FL	*690.00 FL
36	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
37	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
38	1		*SET BOOT LID OUTER MOULDING CLIP	Necessary	30.00 FS	*10.00 FS
39	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
40	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
41	2		*REAR FENDER SEALANT	Necessary	300.00 FS	*50.00 FS
42	1		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
43	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
44	1		*SET TAIL LAMP CLIPS	Necessary	30.00 FS	*20.00 FS
45	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
46	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

10/31/22, 12:00 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR EXHAUST CHROME PIPE (SPECIAL TYPE)	Bent	250.00 FS	*120.00 FS
48	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					14,209.10	7,097.80
- List Item Discount on L Items 25.00/25.00% (\$)					3,199.78	1,619.45
Total Parts (\$)					11,009.32	5,478.35
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD ,CUT ,KNOCK ,GRAZE ADJUST ,REPLACE NEW PARTS	New	2,000.00	1,400.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX ADJACENT PANELS	New	1,800.00	1,400.00
3	TUFF COAT	New	250.00	100.00
4	WIRING /BULB CHECKING	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	200.00	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX FUEL TANK	New	180.00	60.00
8	REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
9	REMOVE AND REFIX REAR EXHAUST	New	180.00	80.00
10	TRANSFER BOOT LID MECHANISM	New	80.00	60.00
11	TO CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
12	REAR CHASSIS MEMBER ALIGNMENT	New	250.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,480.00	3,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >