

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT122009096/GWY3E2**Date:** 07/02/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00147132100
Claimant Vehicle No :	PC4513E	Insured Vehicle No :	GBK8101H
Date of Loss:	12/09/2022	Nature of Claim:	TP
		Claim No:	SNM22D206531/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC4513E	Engine No:	ISB67E528522176276
Make & Model:	YUTONG ZK6116H1, 6.7 D (A)	Chassis No:	LZYTBT61F1067803
Reg. Date:	03/03/2016 (Man. Year: 2015)	Odometer:	0 km
Colour:	Multi-colour		
Engine Capacity:	6690 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	11 R22.5	Rear Tyre Size:	11 R22.5
Front Left Side:	Double Star 6 mm	Rear Left Side:	Double Star 6 mm
Front Right Side:	Double Star 6 mm	Rear Right Side:	Double Star 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,476.00	3,735.50	3,740.50	50.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,650.00	1,280.00	6,370.00	83.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,126.00	5,015.50	10,110.50	66.84
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	15,126.00	4,000.00	11,126.00	73.56
+ GST 8.00/8.00% (S\$)	1,210.08	320.00	890.08	73.56
Nett Amount (S\$)	16,336.08	4,320.00	12,016.08	73.56

INSPECTION

Date of Assignment:	03/02/2023		
Date Inspected:	16/09/2022	Inspected At:	SC Auto Industries (S) Pte Ltd (HQ) 51 Senoko Road, #03-01 Singapore 758133
Estimated Period of Repair:	3.0 days		

Adjuster: XinYu**Manager:** XING GUO QIANG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Feb 2023)	
Parts:	N/A	YUTONG ZK6116H1 6.7 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC4513E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,980.50 F	*1,980.50 F
2	1		*REAR NUMBER PLATE	Bent	80.00 F	*50.00 F
3	1		*TAILGATE	Repair	2,660.50 F	*- F
4	2		*REAR NUMBER PLATE LIGHT	Distorted	855.00 F	*855.00 F
5	1		*BODY STICKER	Necessary	1,700.00 F	*800.00 F
6	1		*SUNDRIES	Necessary	200.00 F	*50.00 F

F=Franchise part.

Total Parts (S\$)	7,476.00	3,735.50
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE AND REINSTALL REAR WIRE HARNESS AND CHECK INTERIOR WIRING ACCORDING TO DAMAGE	New	500.00	0.00
2	LABOUR TO REMOVE AND REINSTALL BODY STICKER	New	800.00	0.00
3	LABOUR TO REMOVE, REINSTALL AND REPAIR REAR BUMPER AND REAR PANEL INNER, REAR LID	New	3,200.00	640.00
4	LABOUR TO RESPRAY REAR BUMPER, REAR PANEL INNER AND REAR LID	New	2,800.00	640.00
5	LABOUR TO CARRY OUT DIAGNOSTIC CHECK	New	350.00	0.00
Gross Labour Cost (\$\$)			7,650.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >