

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI22011135/TQY3Q2**Date:** 04/01/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000276		
<b>Claimant Vehicle No :</b>	SHD3277H	<b>Insured Vehicle No :</b>	SLN7559T		
Date of Loss:	06/11/2022	Nature of Claim:	TP	Claim No:	M2206259

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD3277H</b>	Engine No:	2ZR2G77582
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU403091299
Reg. Date:	15/04/2020 (Man. Year: 2020)	Odometer:	221193 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,341.08	921.64	419.44	31.28
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	875.00	630.00	245.00	28.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,227.08</b>	<b>1,562.64</b>	<b>664.44</b>	<b>29.83</b>
<b>+ GST 7.00/7.00% (S\$)</b>	155.90	109.38	46.52	29.84
<b>Nett Amount (S\$)</b>	<b>2,382.98</b>	<b>1,672.02</b>	<b>710.96</b>	<b>29.83</b>

INSPECTION

Date of Assignment:	08/11/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	08/11/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2023)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3277H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	551.89 FL	*551.89 FL
2	1		*REAR BUMPER LOWER COVER	Deformed	654.96 FL	*654.96 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	378.32 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*REVERSE SENSOR	Not Necessary	135.70 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					1,742.87	1,228.85
- List Item Discount on L Items 25.00/25.00% (S\$)					401.79	307.21
Total Parts (S\$)					1,341.08	921.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	525.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
Gross Labour Cost (\$\$)			875.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >