

Your Ref: TP/IP/27089/2022  
Our Ref : CI/TPD22011565/N

20 January 2023

**Fatal Accident Investigation Team**

Traffic Police Department  
Singapore Police Force  
10 Ubi Avenue 3  
Singapore 408865

**INSPECTION REPORT OF MOTORCYCLE FZ 9569J**


1. We refer to your request dated 31 October 2022 to conduct a physical inspection of a motorcycle bearing registration number FZ 9569J (herein referred to as “**Motorcycle**”), which was involved in a fatal road traffic accident on 6 October 2022.
2. The purpose of this inspection is to primarily determine if there was any possible mechanical failure to the Motorcycle that may have contributed to the accident.
3. Following the request, we had carried out a physical inspection of the Motorcycle on 19 January 2023 at the premises of Traffic Police vehicle pound, 517 Airport Road Singapore 539942. We now set out below our observations and comments with respect to this inspection.

**General Condition**

4. The mileage of the Motorcycle was not recorded at the time of our inspection due to a missing speedometer gauge as a result of the accident.
5. The Motorcycle was observed to have sustained damages all around. The body parts that were found to have been damaged include its speedometer gauge, headlight assembly, front forks, front mudguard, handlebar, radiator covers, petrol tank, top box rack, rear number plate and exhaust muffler, amongst others.

**Tyres and Wheel Rims**

6. The condition of the front tyre of the Motorcycle was observed to be in serviceable condition. We did not observe any tear, burst mark(s) and/or punctured hole(s) on the sidewalls as well as across the tread of the front tyre. The tread pattern of the front tyre was clearly visible. The front tyre was observed to be sufficiently inflated for vehicular operation.
7. We found the rear tyre to be deflated most likely as a result of the accident. However we did not observe any tear and/or burst mark(s) on the sidewalls as well as across the tread of the rear tyre. The tread pattern of the rear tyre was clearly visible.
8. The tyre brand, tyre size and remaining tread depth of the 2 tyres were recorded as follows:-



Bridgestone 160/60 - 17 (6mm)  
(Deflated)

Bridgestone 120/60 - 17 (3mm)

9. The 2 tyres were wrapped around alloy wheel rims. At the time of our inspection, we did not observe any visible damage on the front wheel rim of the Motorcycle. However we did observe that the rear wheel rim was bent as a result of the accident. See photos 1 – 15 below.



**Photo 1** shows the mileage of the Motorcycle could not be recorded at the time of our inspection due to a missing speedometer gauge as a result of the accident (circled).



**Photo 2** shows a general view of the frontal portion of the Motorcycle at the time of our inspection. The Motorcycle was observed to have sustained damages all around.





**Photo 3** shows a general view of the right body of the Motorcycle at the time of our inspection. The Motorcycle was observed to have sustained damages all around. The body parts that were found to have been damaged include its speedometer gauge, headlight assembly, front forks, front mudguard, handlebar, radiator covers, petrol tank, top box rack, rear number plate and exhaust muffler, amongst others.



**Photo 4** shows a closer view of the missing headlight assembly (arrowed) of the Motorcycle as a result of the accident.



**Photo 5** shows a closer view of the front mudguard which was amongst the body parts at the front body of the Motorcycle that had sustained damage as a result of the accident (arrowed).



**Photo 6** shows a closer view of the bent handlebar (arrowed) which was amongst the body parts at the front body of the Motorcycle that had sustained damage as a result of the accident.





**Photo 7** shows the right radiator cover of the Motorcycle that had sustained damages of grazing nature as a result of the accident (arrowed).



**Photo 8** shows the left radiator cover of the Motorcycle that had sustained damages of grazing nature as a result of the accident (arrowed).



**Photo 9** shows a closer view of the petrol tank, which was amongst the body parts of the Motorcycle that had sustained damage as a result of the accident (arrowed).



**Photo 10** shows a closer view of the rear number plate (circled) which was amongst the body parts of the Motorcycle that had sustained damage as a result of the accident.





**Photo 11** shows the exhaust muffler (circled) which was amongst the body parts of the Motorcycle that had sustained damage as a result of the accident.



**Photo 12** shows a closer view of the top box rack (arrowed) which was amongst the body parts at the rear body of the Motorcycle that had sustained damage as a result of the accident.






**Photo 13** shows the front tyre of the Motorcycle at the time of our inspection. The front tyre was observed to be in serviceable condition with remaining tread depth of approximately 3mm. The pattern of the tread was also clearly visible. There was no tear, burst mark(s) and/or punctured hole(s) on the sidewalls as well as across the tread of the front tyre.



**Photo 14** shows the condition of the Motorcycle's rear tyre. The rear tyre was observed to be in serviceable condition with remaining tread depth of approximately 6mm. We did not observe any tear, burst mark(s) and/or punctured hole(s) on the sidewalls as well as across the tread of the rear tyre. However the rear tyre was also observed to be deflated.



**Photo 15** shows the deflated rear tyre (arrowed) and bent rear wheel rim (circled) of the Motorcycle as a result of the accident at the time of our inspection.

### **Engine & Drive Train**

10. Upon examination of the Motorcycle's engine area, we had observed that the various engine related parts and components were intact with no visible damage. There was also no sign(s) or indication(s) of fluid leak observed around the engine area of the Motorcycle.
11. The gear train of the Motorcycle was found to be intact without any misalignment. It was also adequately lubricated for operating purposes. See photos 16 – 19 below.






**Photo 16** shows the left side of the engine of the Motorcycle at the time of our inspection. The various engine related parts and components were found to be intact with no visible damage. There was also no sign(s) or indication(s) of fluid leak observed around the left engine area of the Motorcycle.



**Photo 17** shows the right side of the engine of the Motorcycle at the time of our inspection. The various engine related parts and components were found to be intact with no visible damage. There was also no sign(s) or indication(s) of fluid leak observed around the right engine area of the Motorcycle.



**Photo 18** shows the general view of the gear train (arrowed) of the Motorcycle, which was observed to be intact with no misalignment. It was also adequately lubricated for operating purposes.



**Photo 19** shows a closer view of the gear train (arrowed) of the Motorcycle, which was observed to be intact with no misalignment. It was also adequately lubricated for operating purposes.



**Steering System & Braking System**

12. For this case, we were not able to conduct any test(s) on the steering system of the Motorcycle due to the damage of its front forks. The right front fork was found to be bent as a result of the accident which had rendered the Motorcycle immobile.
13. The braking system of the Motorcycle was observed to be of a full hydraulic type, where hydraulic (brake fluid) pressure controls the brake for the front wheel and rear wheel. The brake for the front wheel is engaged by pressing the brake lever at the right side of the Motorcycle's handle bar while the brake for the rear wheel is engaged by stepping on the brake pedal at the right side foot rest of the Motorcycle.
14. Our visual examination of the various components in the Motorcycle's braking system like the brake discs, brake calipers, brake lever, brake foot pedal and brake hoses revealed all to be intact and without damage. There was also no leakage of brake fluid observed along the brake hoses. This was from the respective brake fluid reservoirs to the front brake calipers and rear brake caliper of the Motorcycle. The brake fluid for the front brake and rear brake was also found to be of sufficient level for operational purposes and without any contamination.
15. Static brake tests conducted on the Motorcycle had appear to indicate that the braking system of the Motorcycle was in serviceable condition. There was some resistance felt (spongy like feel) upon pressing the brake lever and upon stepping on the brake pedal. This would indicate that there was no leakage of pressure/vacuum in the brake system.
16. For this case, we were not able to carry out any operational tests to the steering system and braking system of the Motorcycle due to the damage of its front forks, which had rendered the Motorcycle immobile for the operational tests. We were not able to push the Motorcycle manually forward and backward, simulating movement of the Motorcycle, for the operational tests. See photos 20 – 26 below.




**Photo 20** shows the front forks of the Motorcycle. The right front fork was observed to be bent as a result of the accident (arrowed). We were hence not able to conduct any tests on the steering system of the Motorcycle.




**Photo 21** shows a close up view of the front brake caliper, front brake disc and front brake hose (arrowed) at the right side of the Motorcycle's front wheel, which are all part of the components in the hydraulic front brake system of the Motorcycle. Our visual checks of these various components had revealed all to be intact with no visible damage. No leakage of brake fluid was also observed.






**Photo 22** shows a close up view of the front brake caliper, front brake disc and front brake hose (arrowed) at the left side of the Motorcycle's front wheel, which are all part of the components in the hydraulic front brake system of the Motorcycle. Our visual checks of these various components had revealed all to be intact with no visible damage. No leakage of brake fluid was also observed.



**Photo 23** shows the brake fluid reservoir for the front brake of the Motorcycle. The brake fluid was observed to be of sufficient level for operational purposes and without contamination.



**Photo 24** shows the front brake lever being depressed. There was some resistance felt (spongy like feel) upon pressing the front brake lever (arrowed). This would indicate that there is no leakage of pressure/vacuum in the front brake system.



**Photo 25** shows a close up view of the rear brake caliper, rear brake disc and rear brake hose (arrowed) of the Motorcycle, which are all part of the components in the hydraulic rear brake system of the Motorcycle. Our visual checks of these various components had revealed all to be intact with no visible damage. No leakage of brake fluid was also observed.





**Photo 26** shows the brake fluid reservoir for the rear brake of the Motorcycle. The brake fluid was observed to be of sufficient level for operational purposes and without any contamination.

### **Conclusion**

17. For this particular case, we were unable to determine whether there was any possible mechanical failure to the Motorcycle that may have contributed to the accident. This was mainly due to the extent of damage that it had sustained. Its steering system was damaged as a result of the accident. The braking system of the Motorcycle was observed to be in serviceable condition.
18. The 2 tyres of the Motorcycle were found to be in serviceable condition (which included the deflated rear tyre) with remaining tread depth of approximately 3mm and 6mm. There was no tear, cut or burst mark(s) on the outer and the inner sidewalls as well as across the tread of the 2 tyres. The front tyre was sufficiently inflated for vehicular operation.

19. Our findings were based solely on a static and visual inspection of the Motorcycle. No operational test(s) could be carried out to the Motorcycle due to the damage of its front forks (as a result of the accident), which had rendered the Motorcycle immobile.

**Muhd Nazril***Senior Technical Investigator***Ang Bryan Tani***AMSOE, AMIRTE, AFF SAE, M.MATAI, AFF.Inst.AEA**Senior Technical Investigator**Technical Investigation & Reconstructionist (SAE-A)*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.