12/23/22, 1:33 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22011744/TVY3Q2

23/12/2022 Date:

**REFERENCE** 

Handling Insurer: **ECICS Limited** 

Policy No:

**Claimant Vehicle** No:

SCK9779J

Insured Vehicle No:

SKW303A

Date of Loss: 02/11/2022 Nature of Claim: ΤP Claim No: DMPC2200527H/ST

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SCK9779J

TOYOTA CAMRY, 2.5 (A) Make & Model: **Engine No:** A25A0377257

Reg. Date: MR2B63HKX04002337 21/06/2019 (Man. Year: 2019) Chassis No:

Colour: Odometer: 58813 km Grey

**Engine Capacity:** 2487 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 235/45 R18 235/45 R18 Rear Tyre Size: Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		936.52	45.00	891.52	95.19
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,040.00	420.00	620.00	59.62
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	1,976.52	465.00	1,511.52	76.47
	+ GST 7.00/7.00% (S\$)	138.36	32.55	105.81	76.47
	Nett Amount (S\$)	2,114.88	497.55	1,617.33	76.47

**INSPECTION** 

Date of Assignment: 22/11/2022

Shu Fatt Auto Works (HQ)

Date Inspected: 24/11/2022 Inspected At: Block 1009 Bukit Merah Lane 3, #01-90

Singapore 159723 Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID **VERON CHEN** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

## REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2022)

Parts: 143 TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SCK9779J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	526.50 FL	*- FL
2	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
3	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	268.60 FL	*- FL
4	1		*LEFT REAR BUMPER SENSOR	Not Necessary	393.60 FL	*- FL
F=Fra	nchise	part. L=ListIter	nDisc.	_		
				Sub Total (S\$)	1,248.70	60.00
	- List Item Discount on L Items 25.00/25.00% (S\$)			312.18	15.00	
				Total Parts (S\$)	936.52	45.00
			Report was unsubmitted during	g this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO KNOCK ,STRAIGHTEN REAR SUPPORT PANEL,LEFT REAR FENDER,RENEW REAR BUMPER AND ASSEMBLY	New	450.00	200.00
2	TO RESPRAY DAMAGED PARTS	New	450.00	220.00
3	TO REMOVE REAR GARNISHES ,CARPETS ,UPHOLSTERY TO FACILITATE REPAIRS AND ASSEMBLY	New	80.00	0.00
4	TO RESEAL JOINTS ,REINSULATE ,ANTI RUST PANELS AND ASSEMBLY	New	60.00	0.00
	Gross Labour Cost (S\$)		1,040.00	420.00
	Report was unsubmitted during t	his print-out.		

< END OF ESTIMATES >