6/13/23, 9:15 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIS22012691/NPA3Q2

13/06/2023 Date:

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2002103413 **Claimant Vehicle** SH9120K Insured Vehicle No: SMH5565H

No:

Date of Loss: 16/12/2022 Nature of Claim: TP Claim No: 202222008937

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH9120K

Make & Model: HYUNDAI AE IONIQ HEV, 1.6 DCT (A) G4LEJU083483 Engine No:

Reg. Date: 17/03/2017 (Man. Year: 2017) Chassis No: KMHC851CVHU022742

Colour: Blue Odometer: 902166 km

Engine Capacity: 1580 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 195/65 R15 Rear Tyre Size: Front Left Side: West Lake 4 mm Rear Left Side: Dunlop 3 mm Front Right Side: West Lake 4 mm Rear Right Side: Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,940.15	949.24	1,990.91	67.71
Miscellaneous Items		0.00	0.00	0.00	
Labour		750.00	630.00	120.00	16.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,690.15	1,579.24	2,110.91	57.20
	Approved Total (Overridden) (S\$)		1,250.00		
	Nett Amount (S\$)	3.690.15	1.250.00	2,440,15	66.13

INSPECTION

Date of Assignment: 16/12/2022

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 19/12/2022 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: Muhammad Nazril Bin Abdullah **CHEN TSUE YEE** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jun 2023)

Parts: 143 HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH9120K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Cracked	459.40 FL	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTER MOULDING	Cracked	451.25 FL	*451.25 FL
4	1		*REAR BUMPER BEAM	Serviceable	394.80 FL	*- FL
5	1		*REAR BUMPER STAY LH	Serviceable	138.10 FL	*- FL
6	1		*REAR REFLECTOR LH	Serviceable	41.45 FL	*- FL
7	1		*REAR BUMPER SIDE BRACKET LH	Serviceable	55.80 FL	*- FL
8	1		*BSD -BLIND SPORT RADER	Serviceable	1,784.40 FL	*- FL
9	1		*REAR BUMPER CENTRE UNDER COVER	Deformed	225.00 FL	*225.00 FL
10	1		*REAR BUMPER SIDE UNDER COVER LH	Deformed	108.00 FL	*108.00 FL
11	1		*REVERSE SENSOR	Serviceable	180.00 FS	*- FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	3,860.20	1,265.65
			- List Item Discount on L It	ems 25.00/25.00% (S\$)	920.05	316.41
				Total Parts (S\$)	2,940.15	949.24
			Report was unsubmitted during	this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	our Items						
1	PANEL BEATING	New	400.00	350.00			
2	SPRAY PAINT	New	300.00	250.00			
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00			
		Gross Labour Cost (S\$)	750.00	630.00			
	Report was unsubmitted during this print-out.						

< END OF ESTIMATES >