

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Mar 2023)
Parts: M1-SUV	TOYOTA HARRIER 2.0 PREMIUM CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGX1283J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,395.42 FL	*800.00 FL
2	1		*FRONT RH BONNET HINGE	Bent	85.84 FL	*65.30 FL
3	1		*FRONT LH BONNET HINGE	Bent	85.84 FL	*65.30 FL
4	1		*FRONT WIPER ARM (LONG)	Repair	185.05 FL	*- FL
5	1		*FRONT WIPER ARM (SHORT)	Not Necessary	150.13 FL	*- FL
6	2		*FRONT BONNET DAMPER	Not Necessary	323.86 FL	*- FL
7	1		*FRONT RH FENDER	Dented	791.88 FL	*791.88 FL
8	1		*FRONT LH FENDER	Repair	791.88 FL	*- FL
9	1		*FRONT BUMPER	Cracked	667.35 FL	*667.35 FL
10	1		*FRONT RH BUMPER RETAINER	Cracked	112.35 FL	*70.00 FL
11	1		*FRONT LH BUMPER RETAINER	Not Necessary	112.35 FL	*- FL
12	1		*FRONT RH HEAD LAMP	Cracked	3,072.86 FL	*1,500.00 FL
13	1		*FRONT LH HEAD LAMP	Cracked	3,072.86 FL	*1,500.00 FL
14	1		*FRONT RH HEAD LAMP SUPPORT	Repair	161.50 FL	*- FL
15	1		*FRONT LH HEAD LAMP SUPPORT	Repair	161.50 FL	*- FL
16	1		*FRONT BUMPER DIFFUSER	Cracked	296.49 FL	*296.49 FL
17	1		*FRONT BUMPER MIDDLE GRILLE	Cracked	275.27 FL	*275.27 FL
18	1		*FRONT BUMPER TOP GRILLE	Missing	634.19 FL	*300.00 FL
19	1		*FRONT RH FOG LAMP	Not Necessary	318.92 FL	*- FL
20	1		*FRONT LH FOG LAMP	Not Necessary	318.92 FL	*- FL
21	1		*FRONT RH FOG LAMP GARNISH	Not Necessary	105.95 FL	*- FL
22	1		*FRONT LH FOG LAMP GARNISH	Not Necessary	105.95 FL	*- FL
23	1		*FRONT BUMPER TOWING COVER	Scratched	48.23 FL	*48.23 FL
24	1		*FRONT SUPPORT PANEL	Dented	445.41 FL	*445.41 FL
25	1		*FRONT BUMPER ENFORCEMENT SPONGE	Broken	127.13 FL	*127.13 FL
26	1		*RADIATOR HOUSING	Not Necessary	854.71 FL	*- FL
27	2		*HONK	Not Necessary	280.80 FL	*- FL
28	1		*WIPER TANK	Cracked	149.72 FL	*60.00 FL
29	1		*FRONT TOP PANEL COVER	Broken	326.32 FL	*250.00 FL
30	1		*FRONT BONNET LOCK	Dented	312.00 FL	*160.00 FL
31	1		*FRONT BONNET CATCH	No such part	163.23 FL	*- FL
32	1		*FRONT RH FENDER INNER PANEL	Repair	583.20 FL	*- FL
33	1		*FRONT LH FENDER INNER PANEL	Repair	583.20 FL	*- FL
34	1		*RADIATOR	Not Necessary	1,041.51 FL	*- FL
35	1		*AC CONDENSER	Dented	561.84 FL	*380.00 FL
36	1		*FRONT RH BUMPER SUPPORT	Dented	212.00 FL	*212.00 FL
37	1		*FRONT LH BUMPER SUPPORT	Serviceable	212.00 FL	*- FL
38	1		*FRONT CENTRE BUMPER SUPPORT	No such part	732.25 FL	*- FL
39	1		*FRONT COLLISION ENFORCEMENT BAR	Dented	898.00 FL	*490.00 FL
40	1		*FRONT RH WHEEL ARC COWLING	Broken	195.00 FL	*195.00 FL
41	1		*FRONT RH ABSORBER	Bent	457.92 FL	*457.92 FL
42	1		*FRONT ENGINE UNDER TRAY	Cracked	229.53 FL	*180.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	10		*WHEEL ARC COWLING CLIPS	Necessary	35.00 FL	15.00*35.00 FL
44	2		*REAR TAILGATE ELECTRIC DAMPER	Not Necessary	2,237.84 FL	*- FL
45	1		*REAR BOOT	Dented	1,938.51 FL	*1,450.00 FL
46	1		*REAR BOOT INNER PANEL	Broken	1,216.12 FL	*600.00 FL
47	1		*REAR BUMPER	Cut	1,849.22 FL	*900.00 FL
48	1		*REAR RH BUMPER RETAINER	Not Necessary	85.84 FL	*- FL
49	1		*REAR LH BUMPER RETAINER	Not Necessary	85.84 FL	*- FL
50	1		*REAR BUMPER DIFFUSER	Cracked	746.80 FL	*450.00 FL
51	1		*REAR BUMPER REVERSE SENSOR	Shorted	350.00 FL	*200.00 FL
52	2		*REAR BOOT HINGE	Not Necessary	167.76 FL	*- FL
53	1		*REAR BOOT LOCK	Dented	972.73 FL	*500.00 FL
54	1		*REAR BOOT WEATHER STRIPE	Not Necessary	583.94 FL	*- FL
55	1		*REAR RH BOOT LAMP	Not Necessary	484.03 FL	*- FL
56	1		*REAR LH BOOT LAMP	Not Necessary	484.03 FL	*- FL
57	1		*REAR BOOT OUTER LOGO PANEL	Not Necessary	70.39 FL	*- FL
58	1		*REAR BOOT EMBLEM (HARRIER)	Necessary	74.24 FL	*74.24 FL
59	1		*REAR END PANEL	Repair	916.12 FL	*- FL
60	1		*REAR ANTENNA MODULE	Not Necessary	555.10 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	34,493.87	13,546.52
- List Item Discount on L Items 25.00/25.00% (\$\$)	8,623.47	3,386.63

Total Parts (\$\$)	25,870.40	10,159.89
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FIX & DISMANTLE AND REMOVE DAMAGED FRONT PORTIONS; AFFECTED DAMAGED PORTION	New	1,500.00	1,400.00
2	TO APPLY ANTI RUST COAT AND AFFECTED AREAS	New	150.00	30.00
3	TO CHECK WIRING	New	180.00	30.00
4	WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT	New	800.00	0.00
5	SPRAY PAINTING FOR FRONT PORTIONS AFFECTED PARTS	New	2,000.00	1,800.00
6	REFOCUSING OF THE FRONT HEADLAMP	New	180.00	0.00
7	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE	New	180.00	0.00
8	3D WHEEL ALIGNMENT	New	120.00	0.00
9	TO APPLY WATERPROOFING SEALER ON FRONT SUPPORT PANELS	New	200.00	0.00
Gross Labour Cost (\$\$)			5,310.00	3,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

Celine Fong (LKKAuto)

From: Fievel Foo <Fievel_Foo@sg.msig-asia.com>
Sent: Tuesday, 16 May 2023 2:11 PM
To: Xin Yu (LKK Auto)
Cc: SUR
Subject: RE: SGX1283J & SKK4842A DOA: 14.01.2023 MSIG ref no.299695 FF
Attachments: adjustment.pdf

Dear Xin Yu

The vehicle is repair part by part or lump sum. Let us know if it can adjust to \$12,138.95 if the adjustment is part by part.

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts	11,838.60	25,870.40	10,159.89	15,710.51	60.73
Miscellaneous Items	8,878.95	0.00	0.00	0.00	
Labour	3260.00	5,310.00	3,260.00	2,050.00	38.61
Paintwork Labour	12,138.95	0.00	0.00	0.00	
	9,500.00				

Thanks with regards

Fievel Foo
Executive, Claim Services (Motor)
D: +65 6012 1335 | Fievel_Foo@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way, #21-01 SGX Centre 2, Singapore 068807 | T: +65 6827 7888 |

Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

Join our mission in protecting our planet, please consider the environment before you print.

From: Xin Yu (LKK Auto) <xinyu@lkkauto.com>
Sent: Friday, March 31, 2023 10:10 AM
To: Fievel Foo <Fievel_Foo@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SGX1283J & SKK4842A DOA: 14.01.2023 MSIG ref no.299695 FF

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Fievel,

Please provide us the breakdown of the repair cost as requested by the repairer. Thank you.

Best Regards,

Xin Yu | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | fax: 6256-4315 | email: xinyu@lkkauto.com / sur@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)