

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001759/RNP3Q2**Date:** 03/07/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00021632201

Claimant Vehicle No : SMZ1897G **Insured Vehicle No :** YM7122X

Date of Loss: 11/02/2023 Nature of Claim: TP Claim No: SNM23D201199/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ1897G**

Make & Model: BMW X1, 1.5 SDRIVE 18I (A) Engine No: 37166316B38A15F

Reg. Date: 15/04/2021 (Man. Year: 2021) Chassis No: WBA32AA0605T10519

Colour: Blue Odometer: 23073 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,597.00	326.45	1,270.55	79.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,172.00	495.00	18.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,264.00	2,498.45	1,765.55	41.41
+ GST 8.00/8.00% (S\$)	341.12	199.88	141.24	41.40
Nett Amount (S\$)	4,605.12	2,698.33	1,906.79	41.41

INSPECTION

Date of Assignment: 16/02/2023

Date Inspected: 14/03/2023 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2023)
Parts:	M1-SUV	BMW X1 1.5 SDRIVE 18l (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ1897G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*40.00 FS
2	1		*RR BUMPER LH CORNER MOUNTING	Not Necessary	151.90 FS	*- FS
3	1		*RR BUMPER RH CORNER MOUNTING	Not Necessary	151.90 FS	*- FS
4	1		*REAR BUMPER PANEL PRIMED	Not Necessary	926.75 FS	*- FS
5	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Scratched	272.45 FS	*272.45 FS
6	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					1,597.00	326.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE BUMPER REAR PANEL AND ATTACHMENTS	New	1,275.00	850.00
2	TO SPRAY PAINT BUMPER REAR PANEL	New	1,038.00	986.00
3	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
Gross Labour Cost (S\$)			2,667.00	2,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >