

## REPAIR ESTIMATE\*

DATE: 21.02.21  
MVA: RUMANN  
DOA: 22.02.21

**INCOME**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	BOOTLID COVER <i>dent/brush</i>			\$2,379.38 ✓ 2329.38
	BOOTLID LOCK ?			\$273.40 ✓ 273.40
	BOOTLID EMBLEM - STAR <i>mc</i>			\$45.46 ✓ 45.46
	REAR SIDE BUMPER LH <i>X MW</i>			\$473.60 ✓ 473.60
	TAILLAMP ASSY LH <i>crh</i>			\$622.44 ✓ 622.44
	REAR BUMPER ASSY <i>Br</i>			\$1,372.00 ✓ 1372
	REAR BUMPER REINFORCEMENT <i>dent</i>			\$462.48 ✓ 462.48
10	REAR BUMPER CLIPS <i>mc</i>			\$22.00 ✓ 22
	BUMPER REINFORCEMENT BRACKET LH ?			\$141.14 <i>X MW</i> 141.14
	BUMPER REINFORCEMENT BRACKET RH ?			\$141.14 <i>X MW</i> 141.14
	REAR WINDSCREEN GLASS <i>Br</i>			\$1,273.98 ✓ 1273.98
	<b>SUB TOTAL</b>		6127.74	\$7,157.02
	<b>LESS 20%</b>		1225.54	\$1,431.40
	<b>DISCOUNTED TOTAL</b>		4902.19	\$5,725.62
1	REAR NUMBER PLATE			\$80.00 NET ✓
2	WINDSCREEN SEALANT			\$46.00 NET ✓
1	BOOTLID MAXI LOGO			\$80.00 NET ✓
1	REVERSE SENSOR			\$288.00 NET <i>X MW</i> ✓
				\$494.00
	<b>Labour Charge</b>			
	PANEL BEATING			\$1,200.00 <i>900 -</i>
	SPRAY PAINT			\$600.00 <i>500 -</i> 500
	CHECK WIRING			\$50.00 <i>30 -</i>
	TUFF KOTE			\$50.00 <i>30 -</i>
	REMOVE/ REFIX REAR WINDSCREEN GLASS			\$120.00 <i>80 -</i>
	REMOVE/REFIX REVERSE SENSOR			\$80.00 <i>50 -</i> 30 -
	<b>TOTAL LABOUR</b>			\$2,100.00
	<b>ESTIMATE TOTAL</b>		6578.19	\$8,319.62
			208 = 1315.63	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

4 days L/S  
23/2/23  
1st m 3pm  
*[Signature]*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the Insurance company.

FT = 5250