

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23003385/SWY3Q2**Date:** 24/05/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT101393		
Claimant Vehicle No :	SHC8083Y	Insured Vehicle No :	SKK9198R		
Date of Loss:	30/03/2023	Nature of Claim:	TP	Claim No:	M2302129

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8083Y	Engine No:	G4LEKU422025
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU193023
Reg. Date:	29/04/2021 (Man. Year: 2019)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,233.84	1,871.92	361.92	16.20
Miscellaneous Items	311.00	311.00	0.00	0.00
Labour	1,130.00	630.00	500.00	44.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,674.84	2,812.92	861.92	23.45
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	3,674.84	2,250.00	1,424.84	38.77
+ GST 8.00/8.00% (S\$)	293.99	180.00	113.99	38.77
Nett Amount (S\$)	3,968.83	2,430.00	1,538.83	38.77

INSPECTION

Date of Assignment:	31/03/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	31/03/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2023)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC8083Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Scratched / Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Cracked	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	*394.80 FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Dented	138.10 FL	*138.10 FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Dented	138.10 FL	*138.10 FL
7	1		*REAR BUMPER SIDE BRACKET LH	Not Necessary	55.80 FL	*- FL
8	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	55.80 FL	*- FL
9	1		*ANTENNA SMARTKEY	Not Necessary	40.50 FL	*- FL
10	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
11	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
12	1		*REAR BUMPER LOWER CTR MOULDING	Scratched	155.00 FL	*155.00 FL
13	1		*REAR BUMPER UNDER CTR COVER	Cracked	225.00 FL	*225.00 FL
14	1		*REAR NUMBER PLATE WITH TRIM COVER	Cracked	55.00 F	*55.00 F
15	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 F	*50.00 F
16	1		*REAR BUMPER REVERSE SENSOR	Faulty	180.00 F	*180.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,721.05	2,268.65
- List Item Discount on L Items 20.00/20.00% (\$\$)	487.21	396.73
Total Parts (\$\$)	2,233.84	1,871.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	RENEW ADVERTISEMENT	300.00	300.00
2	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			311.00	311.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			1,130.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >