4/17/23, 10:18 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI23003677/RVY3Q2

Date: 17/04/2023

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MX010545

Claimant Vehicle CLACEFOT CORROSON

CROSSON

No: SHA6558T Insured Vehicle No: GBC8308X

Date of Loss: 06/04/2023 Nature of Claim: TP Claim No: M2302289

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA6558T

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU414072
Reg. Date: 30/10/2020 (Man. Year: 2019) Chassis No: KMHC851CVLU191407

Colour: Blue Odometer: 300753 km

Engine Capacity: 1580 cc
Market Value/New Car
N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: DURATURN 6 mm Rear Left Side: DURATURN 6 mm
Front Right Side: DURATURN 6 mm
DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,292.68	796.12	496.56	38.41
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	780.00	640.00	140.00	17.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,083.68	1,447.12	636.56	30.55
+ GST 8.00/8.00% (S\$)	166.69	115.77	50.92	30.55
Nett Amount (S\$)	2,250.37	1,562.89	687.48	30.55

INSPECTION

Date of Assignment: 10/04/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 10/04/2023 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Apr 2023)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA6558T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Torn	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Scratched	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REFLECTOR RH	Not Necessary	32.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Not Necessary	138.10 FL	*- FL
7	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	55.80 FL	*- FL
8	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 F	*50.00 F
F=Fra	ınchise	part. L=ListIt	emDisc.			
				Sub Total (S\$)	1,603.35	982.65
	- List Item Discount on L Items 20.00/20.00% (S\$)		310.67	186.53		
				Total Parts (S\$)	1,292.68	796.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount			
Misc	Miscellaneous Items							
1	1	OD/TP Case (Insurer)		11.00	11.00			
			Sub Total (S\$)	11.00	11.00			

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	40.00
		Gross Labour Cost (S\$)	780.00	640.00
	Report was	s unsubmitted during this print-out.		

< END OF ESTIMATES >