

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI23004948/RQY3M4**Date:** 04/07/2023**REFERENCE****Insured/Claimant:** SELVAGANESAN S/O SIVALINGAM**Policy No:** DMPG23005091**Date of Loss:** 02/05/2023**Nature of Claim:** OD**Claim No:** CDMPG23001078**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SMM226T**Make & Model:** BMW X3 SDRIVE20I, 2.0 M SPORT (A)**Engine No:** F8503256B48B20A**Reg. Date:** 29/04/2019 (Man. Year: 2019)**Chassis No:** WBATR12000LM17670**Colour:** White**Odometer:** 106555 km**Engine Capacity:** 1998 cc**Market Value/New Car Price:** S\$158,000.00**Sum Insured (\$\$):** **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 245/50R19**Rear Tyre Size:** 245/50R19**Front Left Side:** Pirelli 6 mm**Rear Left Side:** Pirelli 6 mm**Front Right Side:** Pirelli 6 mm**Rear Right Side:** Pirelli 6 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,099.60	6,138.80	4,960.80	44.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,153.00	5,273.00	7,880.00	59.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>24,252.60</b>	<b>11,411.80</b>	<b>12,840.80</b>	<b>52.95</b>
<b>- Excess (\$\$)</b>	500.00	500.00	0.00	0.00
<b>(\$\$)</b>	23,752.60	10,911.80	12,840.80	54.06
<b>+ GST 8.00/8.00% (\$\$)</b>	1,900.21	872.94	1,027.27	54.06
<b>Nett Amount (\$\$)</b>	<b>25,652.81</b>	<b>11,784.74</b>	<b>13,868.07</b>	<b>54.06</b>

**INSPECTION****Date of Assignment:** 15/05/2023**Date Inspected:** 16/05/2023 **Inspected At:**

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance  
Centre  
Singapore 159941

**Estimated Period of Repair:** 5.0 days**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2023)
Parts:	M1-SUV	BMW X3 SDRIVE20I 2.0 M SPORT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM226T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*TAIL PANEL	Not Necessary	558.45 FS	*- FS
3	1		*INTERIOR TAIL TRIM PANEL	Not Necessary	488.15 FS	*- FS
4	1		*TRUNK LID	Bent	2,112.45 FS	*2,112.45 FS
5	1		*REAR BUMPER CARRIER	Not Necessary	800.10 FS	*- FS
6	1		*LH SIDE GUIDE FOR BUMPER	Not Necessary	136.30 FS	*- FS
7	1		*RH SIDE GUIDE FOR BUMPER	Not Necessary	136.30 FS	*- FS
8	1		*LH BUMPER GUIDE	Not Necessary	175.25 FS	*- FS
9	1		*RH BUMPER GUIDE	Not Necessary	175.25 FS	*- FS
10	1		*REAR BUMPER BOTTOM REINFORCEMENT	Not Necessary	124.55 FS	*- FS
11	1		*REAR BUMPER TOWING LUG COVER (M)	Not Necessary	79.10 FS	*- FS
12	1		*REAR BUMPER PANEL PRIMED (M/PMA)	Deformed	1,536.45 FS	*1,536.45 FS
13	1		*SET MOUNTING PDC/PMA SENSOR REAR(M)	Not Necessary	138.65 FS	*- FS
14	1		*REAR BUMPER BOTTOM TRIM PANEL (M)	Deformed	365.85 FS	*365.85 FS
15	10		*BUMP STOP	Not Necessary	34.50 FS	*- FS
16	1		*REAR SILENCER HEAT INSULATION	Not Necessary	80.75 FS	*- FS
17	1		*REAR LH LIGHT IN THE SIDE PANEL	Not Necessary	612.05 FS	*- FS
18	1		*REAR RH LIGHT IN THE SIDE PANEL	Not Necessary	612.05 FS	*- FS
19	1		*REAR LH LIGHT IN THE TRUNK LID	Cracked	428.45 FS	*428.45 FS
20	1		*REAR RH LIGHT IN THE TRUNK LID	Cracked	428.45 FS	*428.45 FS
21	2		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	10.60 FS	*10.60 FS
22	2		*ULTRASONIC SENSOR ALPINWEISS (U300)	Not Necessary	772.00 FS	*- FS
23	1		*SET ADHESIVE PADS FOR ACE 2.0	Not Necessary	37.35 FS	*- FS
24	1		*(DG) CLEANER R1 (100ML)	Necessary	30.05 FS	*30.05 FS
25	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
26	1		*(DG/SL)ADHESIVE PRIMER VP 206 (30ML	Necessary	28.50 FS	*28.50 FS
27	1		*PLAQUE 82MM	Necessary	72.85 FS	*72.85 FS
28	1		*LETTERING X3	Necessary	65.60 FS	*65.60 FS
29	1		*LETTERING S DRIVE 20I	Necessary	98.35 FS	*98.35 FS
30	10		*HOOK AND LOOP FASTENER	Necessary	26.00 FS	*26.00 FS
31	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
32	2		*ULTRASONIC SENSOR BLACK	Not Working	508.10 FS	*508.10 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,099.60 6,138.80

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE BUMPER REAR PANEL, BOOT LID, TAIL END PANEL AND INTERIOR TAIL TRIM	New	5,950.00	1,700.00
2	TO SPRAY PAINT BUMPER REAR PANEL, BOOT LID, TAIL END PANEL AND INTERIOR TAIL TRIM	New	3,562.00	1,972.00
3	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	574.00
4	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
5	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
6	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	112.00
7	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	0.00
8	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
9	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	504.00
10	TO REPLACE BOOTLID SMART OPENER CONTROL UNIT, TOP AND BOTTOM SENSOR LINE INCLUDING PROGRAM AND CONDUCT CHECK FOR PROPER FUNCTION	New	661.00	0.00
11	TO REPLACE REAR PDC SENSOR WIRE HARNESS INCLUDING RESET AND CONDUCT CHECK FOR PROPER FUNCTION	New	266.00	0.00
12	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
<b>Gross Labour Cost (\$\$)</b>			<b>13,153.00</b>	<b>5,273.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >