GBJ7866X

7Pl China

A314-32-C

## REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 24 May 2023)

Parts:

TOYOTA DYNA 150 2.8 D 5MT (M) (Model not available in database)

(Price-denominated Standard List)

Labour:

Repairer's

Print Code: (Unsubmitted, no print-code for GBJ7866X)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

|               | y Part No.   | Particulars                                   | %             | Disc | %Depr | Amount       |            |
|---------------|--|---|---------------|------|-------|--------------|------------|
| 1 1           |  | *1 pc rear exhaust pipe                       |               | 0.00 | 0.00  | *210.00 F    |            |
| 2 1           |  | *1 pc LH taillamp  *1 pc LH taillamp panel    | M             | 0.00 | 0.00  | *105.00 F •  | _          |
| 3 1           |  | *1 pc LH taillamp panel                       | 47            |      | 0.00  | *35.00 F     |            |
| 4 1           |  | *1 pc front bumper B-1/cm                     |               | 0.00 | 0.00  | *230.00 F    |            |
| 5 1           |  | *2 pcs front bumper brackets @ \$105/pc All h | 4             | 0.00 | 0.00  | *210.00 F    |            |
| 6 1           |  | *1 pc front grille                            |               | 0.00 |       | CM *220.00 F |            |
| 7 1           |  | *1 pc front grille logo                       |               | 0.00 | 0.00  | *40.00 F     |            |
| 8 1<br>9 1    |  | *4 pcs front grille clips @ \$2/pc            | 1             | 0.00 | 0.00  | Mer *8.00 F  |            |
|               |  | *2 pcs headlamps @ \$320/pc                   | r             | 0.00 | 0.00  |              |            |
| 10 1          |  |   |               | 0.00 | 0.00  |              | - Commence |
| 11 1          |  | *1 pc front panel                             |               | 0.00 | 0.00  |              |            |
| 12 1          |  | *1 pc air-con evaporator                      |               | 0.00 |       |              |            |
| 3 1           |  | *1 pc air-con blower                          |               | 0.00 |       |              |            |
| 4 1           |  | *1 pc front panel emblem Dyna                 |               | 0.00 |       |              | )F—        |
| 5 1           |  | *1 pc front wiper panel                       |               | 0.00 |       |              |            |
| 6 1           |  | *1 pc front LH wiper nozzle                   |               | 0.00 |       |              |            |
| 7 1           |  | *1 pc front windscreen glass rubber           |               | 0.00 | 0.00  | 0 مر *95.00  | OF L       |
| 3 1           |  | *1 pc front LH mirror                         |               | 0.00 | 0.00  |              |            |
| 1             |  | *1 pc front LH cornal garnish                 | <b>)</b>      | 0.00 | 0.00  | 0 *140.00    | 0F 1       |
| 1             |  | *1 pc front chassis cross member              |               | 0.00 |       |              |            |
| 1             |  | *1 pc air-con condenser assy                  |               | 0.00 |       |              |            |
| 1             |  |   | 91)           | 0.00 |       |              |            |
| 1             | The second secon | *1 pc cabin rear LH pillar emblem D4D (A      | _             |      |       |              |            |
| ranchise part |  |   | ~ _           |      |       |              |            |
|               |  | Sub Total (S                                  | 121           |      |       | 5,229.0      | 20         |
|               |  | + Margin on L,N Items 10.00% (S               |               |      |       | 522.9        |            |
|               |  |   | _             |      |       |              |            |
|               |  | Total Parts (S                                | 3 <b>\$</b> ) |      |       | 5,751.9      | 90         |

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

**Qty Particulars** 

Not Swhoiks Ulhy & Renny After Pain

**Amount** 

35.00

35.00 4 380.00

### Miscellaneous Items

| 1 | 1 | i pe front number plate |  |
|---|---|-------------------------|--|
| 2 | 1 | 1 pc rear number plate  |  |
| 3 | 1 | 1 pc rear step bar      |  |

1 set reverse sensor

2 pcs rear stoppers @ \$110/pc

LKK Auto Consultants nence notify

the Repairer of the following: To resurvey before after spray painting

To disple dame ad part(s) during resurvey

 Parts prices a: reject to confirmation • Third party st s on a "Without Prejudice" basis Sub Total (S\$)

 No illegat morr. O. (51 is allowed Supplementary

s) must resurveye and is subject to final approval from Insurance Company

Acknowledged by Renaver

Squali :

870.00

5hor 200.00 -

ne 220.00

Estimates on Labour

- back to OneMotoring

|   | Park and a second |             | (-12)            |
|---|---|-------------|------------------|
| N | o Particulars   | Lab.Type    | Amount           |
| L | bour Items  |             |                  |
| 1 | Remove & refix rear step bar,taillamps,exhaust pipe;to straighten,knocking & repair rear RH chassis,rear truck end member & realign the same  | New         | 700.00           |
| 2 | Remove & refix front windscreen glass   | New         | 60.00            |
| 3 | Remove & refix air-con,check,vacuum & refill gas  | New         | 100.00           |
| 4 | Remove & refix dashboard,meter assy & check wiring  | New         | 254 280.00       |
| 5 | Remove & refix frt bumper assy,grille,headlamps,frt wiper assy;to cutting,welding & renew frt panel,frt main chassis,crossmember;Remove & refix frt LH door,transfer lock assy,inner attachment;knocking & repair frt LH windscreen pillar & realign the same   | New J       | 1,500.00         |
| 6 | Remove & refix frt LH door glass  | New         |                  |
| 7 | Putty & respray on frt panel,frt LH door,frt bumper,grille,wiper panel,windscreen pillar,cabin rear LH windscreen pillar,frt chassis cross member & all affected areas  |             | Rog 1,100.00     |
| 3 | 1 pc freezer box RH tailgate assy   | M New (     | Bill) 3,500.00 Z |
| ) | 1 pc freezer box rear frame including labour to renew freezer box rear frame and check system   | New         | 2001 2,300.00 ?  |
| 0 | Putty & respray rear RH tailgate  | New         | 300.00           |
| 1 | To rewrite advertisement  | New         | (Bill) 450.00 7  |
|   | Gross Labo  | our Cost (S | 5) 10,350.00     |

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

# **©** SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

IMPORTABLE TO TICE.

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **ACCIDENT STATEMENT**

Date of Submission 22/05/2023 18:33 (SGT) Reported by **Actual Driver** Date of Accident 19/05/2023 07:00 (SGT) Exact Location of Accident Singapore Additional Location Information Country/State of Loss **Singapore** 

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number ...... **GBJ7866X** 

INSURED/POLICYHOLDER

Is company? TUAN GOU PTE LTD Name Of Registered Owner Company Reg No 2XXXXX312D Email Address xiaoqiang@tiantian.sg (Phone) +65-94358156 Mobile Phone No

Alternative Phone No ...

VEHICLE PARTICULARS

**Toyota** Manufacturer ..... Dyna Model ..... Variant .....

Exact purpose for which vehicle was being used at time of **Employment** 

accident ..... Are you claiming under your own insurance policy for repair to

No - Claiming third party ...... your vehicle? Commercial vehicle Vehicle Category

Manual Transmission 2982 management access on community remaining management in

INSURANCE COMPANY

Sompo Insurance Singapore Pte. Ltd. Name of Insurance Company Policy Number / Cover Note Number **D22MTPCVE002367** 

DRIVER

**WEI YANFENG** Name of Driver Passport No/FIN GXXXX387T Date Of Birth 22/02/1989 Occupation Outdoor

| NOTE PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14DAYS TIME I RAME for you to submit OWN DAMAGE  Claim under your Own Comprehensive policy. Pls check your policy for more information.  ( ) Claim Own Policy ( ) Claim Third and |
|--|
| ( ) Claim Own Policy ( ) Claim Third party ( ) Reporting Onlly  ( ) Claim OD/ TP at other workshop ()  |
| Sketch Plan  |
| SMP3490K GBS 7866X GX8917T   |
|  |
|  |
|  |
|  |
|  |
| PEROPT.  |
| POLICE   |
|  |
| 40   |
| MACHED   |
| $K_{il_{I_{i}}}$   |
|  |
|  |
| Declaration  We declare the foregoing particulars are true in every respect.   |

GOU A REG. NO. 201701312D

Rolicyholder's Signature / Date & Time

1

Driver's Signature (if driver is not the policyholder) / Date & Time 19/5/23

19/5/23

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)